



Hacienda Buena Vista  
Bo Magueyes, Ponce, Puerto Rico  
Photo by Michel Cinquino  
March 1990 / delegates at PRSAPO  
View of Canal

Photo # 1





Hacienda Buena Vista

Bo. MAGÜEVES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

JULY 1988

NEGATIVES - FIDEICOMISO DE CONSERVACION  
VIEW OF AQUEDUCT

PHOTO #2





HACIENDA BUENA VISTA  
BO MA BUENES, PONCE, PUERTO RICO

PHOTO BY Michel CINQUINO

MARCH 1990 / Negatives of PR 5470

View of a Canal

PHOTO #3







HACIENDA BUENA VISTA  
Bo MABÜeyes, Ponce, Puerto Rico  
PHOTO BY Michel CINQUINO  
MARCH, 1990/negatives PRATHPO.

View of Canal.

PHOTO #4



HACIENDA BUENA VISTA  
BO MABUEYES, PONCE, PUERTO RICO  
PHOTO BY MICHEL CINQUINO


MARCH / 1990. / Negatives PRHPD

View of Canal

PHOTO #5

23 14 0 58 + 27





Hacienda Buena Vista

BO MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY MICHEL CINGUINO

MARCH 1990 / Negatives at PRSHPO

View  
of Canal

PHOTO # 6







HACIENDA BUENA VISTA

BO MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

July 1978 / Negatives - Idelcomiso Conservacion

View of Aqueduct

PHOTO # 7



HACIENDA BUENA VISTA

BO MAGÜEYES, PONCE PUERTO RICO

PHOTO BY RICARDO MEDINA

JULY 1988 Negatives at Fideicomiso de Conservación

View of a canal and corn mill house

PHOTO #8

#19 in a set of 27





HACIENDA BUENA VISTA

BO. MAGUEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA


JULY 1988

NEGATIVES AT FIDEICOMISO DE CONSERVACION

VIEW OF COFFEE DEPULPING AND HUSKING MILL

PHOTO #9







HACIENDA BUENA VISTA  
BO. MASUEYOS, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

JULY 1988

NEGATIVE AT FIDEICOMISO DE CONSERVACION

VIEW OF Coffee Mill House, Coffee Depulper, Slave Quarters, and water trough

PHOTO #10



HACIENDA BUENA VISTA

BO. MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA


JULY 1988

NEGATIVES AT FIDEICOMISO DE CONSERVACION

VIEW OF COFFEE DEPULPER (MACHINE)

PHOTO # 11





HACIENDA BUENA VISTA

BO. MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

JULY 1988

NEGATIVES AT FIDEICOMISO DE CONSERVACION.

VIEW OF COFFEE HUSKER

PHOTO # 12







HACIENDA BUENA VISTA  
Bo MABUEYES, Ponce, Puerto Rico

PHOTO BY RICARDO MEDINA

July 1988 / debates at Fideicomiso construction

View of Canal and Corn mill house.  
CORN MILL

PHOTO # 13

F 10 in a set of 27



HACIENDA BUENA VISTA  
BO. MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

JULY 1988

NEGATIVES AT FIDEICOMISO DE CONSERVACION

VIEW OF MILL STONES AT CORN MILL

PHOTO # 14





HACIENDA BUENA VISTA

BO MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

July 1988 / negatives at Fideicomiso de  
CONSTRUCCIÓN

View of the main house, coffee bean drying building and the slaves  
quarters.

PHOTO #16

in a set of 27







HACIENDA BUENA VISTA  
BO MAGÜEYES, PONCE, PUERTO RICO

PHOTO BY RICARDO MEDINA

Julio 1988 / July 88 / negatives at Fideicomiso de Conservación

"Casa Grande" / Facade  
Main House

#PHOTO # 177 of 27



HACIENDA BUENA VISTA  
Bo. Magüeyes, Ponce, Puerto Rico  
Photos by Ricardo Medina

July 1988

Negatives at Fideicomiso de Conservación  
View of mule stables, Hurricane Shelter and warehouse.

Photo # 19





HACIENDA BUENA VISTA

Bo Magüeyes, Ponce, Puerto Rico

PHOTO BY RICARDO MEDINA

July / 1988 / Negatives at Fideicomiso de  
CONSTRUCCION

View main entrance, the main House and the warehouse

Photo # 20 of 27