

MAR 2 | 1979

NAME: Fort Sumner Railroad Bridge
LOCATION: vicinity of Fort Sumner, De Baca
County, New Mexico

PHOTO CREDIT: Wendell Bell June 22, 1977

NEGATIVE FILED AT: History of Engineering
Program, Texas Tech University
IDENTIFICATION: View looking morthnortheast
No. 1

JAN 2 9 1979

FT SUMNER RAILROAD BRIDGE
FAILD LOOKING MORTH-NORTHEAST
6-22-77-0



MAR 2 | 1979

NAME: Fort Sumner Railroad Bridge
LOCATION: vicinity of Fort Sumner,
De Baca County, New Mexico
PHOTO CREDIT: Wendell Bell June 22, 1977
NEGATIVE FILED AT: History of Engineering
Program, Texas Tech University
IDENTIFICATION: View looking north
No. 2

JAN 2 9 1979

FORT SUMNERS RAIL ROAD BRIDGE



MAR 2 | 1979

NAME: Fort Sumner Railroad Bridge
LOCATION: vicinity of Fort Sumner,

De Baca County, New Mexico

DATE: 1905

NEGATIVE FILED AT: History of Engineering

Rrogram, Texas Tech University
IDENTIFICATION: Historic (1905) photograph. Construction of one of the concrete piers.

No. 3

Platosnic (1905)
Platosnaphic Showing
Piek Construction 3



NAME: Fort Sumner Railroad Bridge
LOCATION: vicinity of Fort Sumner,
De Baca County, New Mexico
DATE: 1907
NEGATIVE FILED AT: History of Engineering
Program, Texas Tech University
IDENTIFICATION: Historic (1907) photograph. View looking north-northwest
No. 4
MAR 2 | 1979

Historic (1907) photographic VIEW 100 king North-North WEST