# National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for *Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

1. Name of Property	·····			
historic name	Van Del	len, John and Murta	House	
other names/site number				
2. Location				
street & number		t Eighth Street		A not for publication
city, town	The Dal			
state Oregon	<u>` code (</u>	DR county Wasco	code (	)65 zip code 97058
3. Classification			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
Ownership of Property		Category of Property	Number of Reso	ources within Property
X private		X building(s)	Contributing	Noncontributing
public-local		district	_2	buildings
public-State		site		sites
public-Federal		structure		structures
		object		objects
			2	Total
Name of related multiple pr	operty listing		Number of contr	ibuting resources previously
N/A		· · · · · · · · · · · · · · · · · · ·		ional RegisterN/A
4. State/Federal Agenc	y Certificat	ion	······································	· · · · · · · · · · · · · · · · · · ·
		National Historic Preservation		
In my opinion, the prope	h. Ja al Oregon	does not meet the National		continuation sheet. December 31, 1990 Date
In my opinion, the prope	rty 🗌 meets	does not meet the National	Register criteria. See	continuation sheet.
Signature of commenting or	other official			Date
State or Federal agency and	l bureau		· · · · · · · · · · · · · · · · · · ·	
5. National Park Service	e Certificati	on	dutered 1	n tha
I, hereby, certify that this pr			Astima.	Registar /
entered in the National I See continuation sheet determined eligible for th Register. See continua determined not eligible for National Register.	Register. ne National ation sheet.	Allout	Zyen	2/20/9/
removed from the Natior other, (explain:)	al Register.		o of the Keener	Date of Action
		ignature	e of the Keeper	Date of Action

1-

JAN 1 4 1991

NATIONAL REGISTER 63

Historic Functions (enter categories from instructions)	Current Functions (enter categories from instructions)		
	Current i unct	ions (enter categories nom instructions)	
Domestic: single dwelling	Domestic:	single dwelling	
7. Description			
Architectural Classification (enter categories from instructions)	Materials (enter categories from instructions)		
	foundation	concrete	
Late 19th and Early 20th Century American Movements: Craftsman Bungalow	walls	wood: weatherboard	
	roof	asphalt: composition shingle	
	other	brick trim and chimney	

Describe present and historic physical appearance.

 $\fbox$  See continuation sheet

## National Register of Historic Places Continuation Sheet

Section number \_\_\_\_7 Page \_\_\_1

The Van Dellen house is located on 8th and Federal Streets in The Dalles. Oregon. The road in front (8th) was called Alvord street at the time of construction in 1920. This area was the high class location intrown at that time. The street still has all of the old houses on it.

The house was built by the lumber yard owner who spared no expense to build this 1½ story home with a full basement. The house was built on top of rock and hence was elevated above the street level. A concrete wall was built along the sidewalk on the west and north sides and fill dirt/sand was used to fill the void. The cut out rectangular house has multiple corners and a top story set in on three sides of the lower story.

Thehouse has 57 windows, multiple doors and such features as cedar sub-flooring and roof sheathing. The pitch of the roof is low and in places is nearly flat. The front of the house has a covered porch with large brick pillors and wide concrete steps leading to it from the sidewalk in two sections.

The home had the latest features such as an electric range in the kitchen and the ice box had a plumbed in drain. A day servant was employed for the frequent dinners and had her own room in the back near the kitchen. The front room and dinning rooms were build with large false beams, much like the local Elks lodge. The dinning room has a silver light fixture in the center and two matching ones over the built in cabinets.

A large tiled fireplace was built in the living room and the plaster walls were done in a blue stipple. Hardwood floors are found throughout the house and the wide abundant woodwork is in stained softwood (prob ably Douglas Fir)

The garage was designed for the latest automoblies and was a "double" garage. The yard was expensively landscaped and the back yard was fenced with a wood fence built primarily out of 2x2's.

# National Register of Historic Places Continuation Sheet

Section number 7 Page 2

This home is currently occupied by the Fred Krauss family . Fred is the superintendent of the Wasco Education Service District which is the county office formerly the County School Superintendent's office.

The home is in excellent condition and is being maintained in nearly original form. The exterior is particularly in the original condition as when built. No remodeling, or additions to the home have been made.

The house faces North on a lot which has streets on the North and West sides. Short concrete walls are next to the sidewalks and are topped with ivy covered fences.

The neighborhood is made up of mostly single family homes and has much of its historical character still remaining.

The house has a low pitched roof with wide overhanging eaves and exposed rafters which have been curved. It is of a rectangular composition with horizontal earth-hugging qualities. It has a massive appearance however from the street side as it is built up to avoid having to dig down through rock for the full concrete floored basement.

The widows are mainly double hung with several other windows being fixed or hopper type. Several windows are also sash type and often are flanked by two smaller windows. These are all original.

This wood frame house has a large open front porch, a small, formerly screened in, back porch and a small balcony on the second story. The front porch is indented into the main house and is supported by a massive brick tapered porch post. The house also has a large sunroom located upstairs on the south side.

The siding is wood (original) clapboard and the trim is of wide wood.

The interior of the home has many typical bungalow features. The dining room has wood-panelled walls to the plate-rail and built in cabinets. A major feature in the front room and dining room are the boxed in beams which are also found in some of the old public buildings in The Dalles. The woodwork is of earth tone and has been retained throughout most of the house.

The home is currently decorated and furnished in the style of the times, in part with several Mission type items. Many of the original light fixtures remain and are of particular interest. The silver plated ones in the dining room are of particular interest.

The bathrooms have been maintained with their original fixtures and house features with only a couple of exceptions.

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_7 Page \_\_\_3

The floors of the house are hardwood over cedar which gives them a distinctive sound as one walks through the house. In the bathrooms the linoleums have a base of concrete.

The interior walls are plaster as are the ceilings except where water damage required that they be replaced. The kitchen ceiling has been lowered and sheetrocked also. The ceilings and upper walls have been hand decorated in several rooms and wall paper has been used in several rooms.

Each room has one or more hot water radiators(original) and has wide wood moldins along the baseboard and doorways that are oversized by todays standards. The doors are original with brass hinges and hardware and glass doorknobs. Double doors with multiple glass panes lead into the front room and dining room. In many situations the light switches are still the push button style and the covers are brass. Multipane doors to the cabinets in the dining and front room add to the originalness of the house. A large mantle across one end of the frontroom is about 30" wide and the fireplace is extra large.

The sunroom on the back(south) side of the house has multiple push out type windows and is screened(original wood frames) so that it makes a very pleasant summer sleeping place. Also upstairs are two other bedrooms a bathroom and a small room no doubt used as a dressing room originally.

Several things suggest that this home was built for people of means. No chimhey in the kitchen hence either a gas or electric stove. A drain for the icebox plumbed in and a kitchen which was very utilitarian which suggests a hired cook. The room off of the kithen does not have a closet which supports the notion that the family had a hired cook. The dining room is large and beautiful and the garage in back had a beam projecting out in the manner to allow for easier unloading of ice, bulk groceries and other items. And the basement has a large storage room for food stores. The garage was a double one which is unique for this neighborhood, perhaps suggesting a early two car family. The laundry was was done in the basement and hung there to dry, No wash in the wind The 5000 feet of living space, the 57 windors, the cedar for this house. sheathing and subfloors, the fancy doors, the silver plated light fixtures, the neighborhood(then) etc. etc. suggest over and over that the house was was and is a reflection of prosperity and upper middle class tastes of the times(1918-1920).

8. Statement of Significance	
Certifying official has considered the significance of this property in relation to other propert nationally statewide X locally	ies:
Applicable National Register Criteria	
Criteria Considerations (Exceptions)	
Areas of Significance (enter categories from instructions)Period of SignificanceArchitecture1920	Significant Dates
Cultural Affiliation	
	······································
	e i i e e e e e e e e e e e e e e e e e
Significant Person Architect/Builder	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

#### 9. Major Bibliographical References

street & number 400 E. Eighth Street

The DAlles

city or town \_\_\_\_

Wasco County Clerk and Assessor's records, Wasco County Courthouse

City of The Dalles Historic Resources Inventory, 1984. Inventory Data Sheets, No. 142 et. seq.

Interviews, Betty Van Dellen (Mrs. John) Skirving, daughter of John and Murta Van Dellen, October-November, 1990.

	See continuation sheet		
Previous documentation on file (NPS):			
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:		
has been requested			
previously listed in the National Register	Other State agency		
previously determined eligible by the National Register	Federal agency		
designated a National Historic Landmark	Local government		
recorded by Historic American Buildings	University		
Survey #	Other		
recorded by Historic American Engineering	Specify repository:		
Record #			
10. Geographical Data	<u></u>		
Acreage of property 0.14 acres The Dalles, (	Dregon-Washington 1:62500		
UTM References			
A 10 641725 5050675 B			
	Zone Easting Northing		
	See continuation sheet		
Verbal Boundary Description			
The nominated area is located in $NW_4^1$ $SW_4^1$ Section :	3, Township 1N, Range 13E, Willamette		
Meridian, in The Dalles, Wasco County, Oregon. If			
Block 5, Gibson Addition to the City of The Dalles			
Tax Lot 5800 at said location.			
	See continuation sheet		
Boundary Justification	······································		
The nominated area corresponds to the legally reco	orded lot lines of the parcel		
historically developed and occupied by lumber com			
1920 onward. It includes as a separately contribu			
Craftsman-style garage which is part of the origin			
crarcsman-scyre garage which is part or the origin	ini acverognene.		
	See continuation sheet		
11. Form Prepared By			
name/title Fred D. Krauss			
organization	date August, 1990		

telephone (503) 296-4172

state \_\_\_\_

<u>Oregon</u> zip code 97058

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_8 Page \_1A

The two-story bungalow occupying the southwest corner of the intersection of East Eighth and Federal streets in the Laughlin Bluff neighborhood of The Dalles, Oregon was built in 1920 for John Van Dellen, the owner of the Van Dellen Lumber Company. No architect or builder has been identified to date, but the Van Dellen House is a local distillation of the Western Stick, or California Bungalow style. Comparative analysis of bungalows in the City of The Dalles Historic Resources Inventory shows this to be the outstanding interpretation of the high style. As such, it meets National Register Criterion C. The house is notably well preserved inside and out, and reflects the importance placed by the owner on solid construction and craftsmanship and his ready access to fir and straight-grained cedar, the choicest of local building materials.

The Van Dellen House is a rectilinear volume characterized by numerous porches and projections having broad, gently-pitched gable roofs with deep eaves carried on exposed rafter ends and outsized triangular, or gallows brackets. Vergeboards have decoratively finished ends in the Craftsman tradition, and the exterior is clad with lapped cedar weatherboards. Fine brickwork is exhibited in the exterior chimney on the east side elevation and in the matching railings and massive tapered uprights of the front porch. A variety of window types was used, including window banks, picture windows, both single and three-part, and double-hung windows with upper sash divided into many small lights. All are framed with architrave surrounds.

The interior is carried out in dark-stained Arts and Crafts finishwork noteworthy for beamed ceilings in living room and dining room, high paneled wainscoting, built-in fireplace cabinetry, and well-proportioned door and window surrounds with architrave molding.

The Western Stick style emerged in California in the work of Charles and Henry Greene, Bernard Maybeck and others in the 1890s and was popularized by <u>The Craftsman</u> magazine and building trade journals. It was a style rooted in the Arts and Crafts Movement that expressed its wood post and beam construction system in exterior stickwork. Its low-lying horizontality was accentuated by gently-pitched roofs with shadow-creating deep eaves and boldly projecting horizontal framing members. The qualities of horizontal

## National Register of Historic Places Continuation Sheet

Section number <u>8</u> Page <u>1B</u>

structuralism and quality craftsmanship that characterized the California Bungalows of master architects are embodied in the Van Dellen House in The Dalles.

A small automobile garage situated at the southwest corner of the property is oriented at a right angle to the house, fronting on Federal Street. Because it is finished with the same siding and trim as the house and has a low-pitched gable roof on exposed rafter ends and gallows brackets, it is counted a separately contributing feature. The original double-leaf folding doors are in place.

## National Register of Historic Places Continuation Sheet

Section number <u>8</u> Page <u>2</u>

This large house built in 1920 for John Van Dellen and his wife, Murta, is locally significant under Criterion C as the largest, best preserved and most distinctive example of Craftsman Bungalow architecture in The Dalles, Oregon.

The builder of the house, owner of a lumber yard, had the will and the means to build this home with the best materials of construction available. The concrete was used in abundance as was brick, lumber and trim, doors and windows (57 of them) The subfloors and roof sheathing are of cedar. The light fixtures are of the finest quality and the workmanship is excellent.

The neighboring house to the west was built in 1921 by the same builder as the neighborhood was developed from East to West on this street. The sidewalk was installed by S. A. Fredericksen in October of 1916 in anticipation of the growth on the brow of Laughlin's Bluff.

The house was lived in by the Van Dellen (John and or Florence) for around 40 years. Susequently, three other families have occupied the house. Two of those owners were local citizens of note. Bob Taylor the third owner was the high school principal until very recently and the current owner since 1975, Fred D. Krauss,

is the superintendent of The Wasco Education Service District ( County School Superintendent). The Van Dellens continue to have family living in the area who are of high social standing and achievement.

While most of the home is preserved in soriginal condition, there have been some changes. The back wooden fence has been moved and replaced, and the fish pond has been filled in. The garage is now a hobby shop and the kitchen was modernized in the 1970's by the Taylors and they replaced the shingle roof with asphalt shingles. Some wiring improvements

 $\leq z$ 

United States Department of the interior National Park Service

# National Register of Historic Places Continuation Sheet

Section number \_\_8 Page \_\_3

were done in the 1960's and have continued piecemeal ever since. Some knob and tube wiring remains. The coal furnace was converted to oil along the way and was replaced in the late 1970's with a gas furnace though most of the original hot water radiators and the piping remains in place.

The basement has had a party room added and the clothes washing facilities have been relocated. The coal room is now used for storage. Original plumbing fixtures grace the bathrooms and many original light fixtures remain in place including silver (plated) ones in the wood paneled dining room.

Wall paper now covers the blue stipled plaster in the lining room and wall to wall carpets cover many of the hardwood floors. But recently light fixtures and hardware in one of the rooms were restored to original after many years and coats of paint.

A fence has been added in the front of the house to help preserve the house and is now almost totally covered with ivy and the maple trees on the west side of the house have been removed and replaced by birch trees and the parking strips have been paved with concrete. It is expected that the shingle roof will be restored in due course.

Based on comparative analysis of data in the City of The Dalles Historic Resources Inventory of 1984, the Van Dellen House clearly rises to the top as the most distinctive example of Craftsman Bungalow architecture locally in terms of its scale and quality of design and craftsmanship. Proportions of exterior elevations are fine enough to suggest to some that an architect, as opposed to a builder, was responsible for the design. No designer has been identified to date, however.

# National Register of Historic Places Continuation Sheet

Section number \_\_\_\_8 Page \_\_\_\_4

My analsis is that the Van Dellen house is one of the best three examples of this style of architecture as shown by the city records. In addition, of the 23 structures identified as Bungalows, the Van Dellen house appeared to be outstanding among them in the following ways.

- Two story and further it was the only one with the second story indented (smaller than the first level) and hence with roof lines at two levels. There were other homes with attic type second stories and even a 2<sup>1</sup>/<sub>2</sub> story house, but this style was particularly unusual.
- 2) Iregular rectangular shape. This home has numerous indentations in its outside frame lines. No other home shows this elaborate configuration. This is not only unique, but expensive to construct. This is found at all stories of the house and its basement.
- 3) The structure was one of six homes listed in excellent condition and no exterior alterations noted. It is also the only one of the six best preserved examples that has brick as a decorative (and structural) feature and one of only two that have brick or masonry (rock) integrated into their exterior construction.

Further analysis shows that this home is located near the center of town in what was in the early days of The Dalles the fine residential district located on the bluff overlooking the town and the river. This area was above the flood zone of the town, hence was particularly desir able. THE DALLES, OREGON



#### REMARKS: 14 11 3 3. 131 . 59 .8. 8 . . ζ. d, ... . g 61 2 11 • 4 11 14 18 ٠. 1 6\_1 5 4 • + 1 . 114 ... FEDERAL. • n • 1 - 4 27 20 20 10 PORLH • • 12 • . . . ST. $\mathcal{E}$ ·8+2 ... •• . • 1 . . . .... . . .... . DEP. % REPL. COST LUMP SUM TOTAL DESCRIPTION TYPE AREA S.F. BASE Adj base QUAL. INDEX % MDF. DEPRECIATED REPLACE-MENT COST PHYS % USE % GOOD % REPL. COST NO. DIMENSION USE FOUND FLOOR WALLS ROOF MISC. CCX,C 17×19 GARAGE CONC CAB PUSTIC 30G 15.55 ..... ----ATT DET BSMT 4753 x 106 <u>c/s</u> 5041 ...... 2522 x 50 1 х x x 2 x X X 3 x -----X X 4 X X х x X X X X 1 x x x X X x X \$ TOTAL DEPRECIA . TVEMENTS (TRANSFER TO VALUE SUMMARY)

#### BUILDING DIAGRAM AND OUTBUILDINGS

.

de.





j.

i



