


Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (1 of 7): Southwest front facade, southeast side; photographer facing north.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (2 of 7): Detail, south corner, showing front porch; photographer facing northwest.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (3 of 7): Rear and northwest side; photographer facing south.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (4 of 7): Detail, front facade; photographer facing northeast.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (5 of 7): Reception area showing main front doors; photographer facing southwest.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (6 of 7): Interior, looking towards rear of building; photographer facing northeast.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: May, 1982. Description: (7 of 7): Fireplace in reception area; photographer facing northwest.