Iowa Site Inventory Office of Historic Preservation Iowa State Historical Department East 12th & Grand Avenue Des Moines. Iowa 50319

Site Number	67	 	
District Name		 	
Map Reference 4	# 67		

Identification

v

1 Cr	Sittincation					
		m Haner Polygonal				
2.	Village/Town/City Pisgah	illage/Town/City_Pisgah_vic,TownshipAllen		County_Harrison		
3.	Street Address	County -16				
4.	Legal Location	<u>81 N</u>		43 W		t of SE t
	Urban Rural:			block range	parcel section	subparcel % section of % section
		,		U		
5.	UTM Location: zone15	easting265,480	_northing4,633,	490; Acreage	<u>e less tha</u>	n one acre
	Owner(s) Name Lester					
	Owner(s) Address R. R.		Moorhead		lowa	51558
7.		Street address)	(City)		State)	(Zip)
8	Use Present Gen'l pur	pose barn	Original	Purebred	Hereford	cattle barn
0.		· · · · · · · · · · · · · · · · · · ·				
	ecription		Willi	am B. Han	er, origin	al owner
	escription Date of Construction_1912	Architect/Bu	_		-	maha
9. 10.	Building Type:					
	single-family dwelling		🗌 other	institutional		eligious
	multiple-family dwelling	🔲 educational	🗌 publi	c	🖀 a	gricultural
11	🗌 commercial Exterior Walls: 🖀 claphoard	stone brick board	and batten 🗆 shir	ngles El stucc	0	
				igiesstucci	0	
				light members	(balloon frame)	
12.	Tructural System: Wood fr	ame with interlocking joints s 📋 iron frame 🛛 🗋 steel fra	me with curtain wa	light members	red concrete	
12	Condition: Devcellent		d			
] moved—if so, when?				
14.	Notes on alterations, addition	is (with dates and architect, if	known) and any oth	ner notable feat	ures of building	and site:
	See reverse side.		,		2	
15.	•	perty: 🗌 barn 📕 other fan		-	• • - ·	ivy
	-	<u> </u>				
16.	is the building endangered?	🗃 no 🔄 yes—if so, why?		····		
17.	• •	open land 🗍 woodland		•		
	_ industrial _ residential _	other	<u> </u>			
				······		
18.	Map		19. Photo	o		
			Koll_02	2Frame_22	View	*
	R-	43W				
	•	#67				
1			VBD:			ameter, based
1				on center	r point of	barn, includes
				barn and	attached	shed.
1						
A						
1	-FIA -+ m					
		• • • •				
	3					
P						
1						
12		EN				
1 7	30 20 20 70 70 720	27 26 25 /				
CPE	-41965				MAY 27	1986
273-					, 1	

Significance

(Indicate sources of information for all statements)

20. Architectural significance

- a. Key structure/individually may qualify for the National Register
- b. Contributing structure
- C. Not eligible/intrusion

N/A

Continuation of 14. Integrity.

54' diameter. 12 sides - 14' on a side. 50' high. Metal roof replaced by wood shingles in 1951. 12 sided gambrel roof with gable dormer on south side. Circular interior. Hay loft extends 16' in from wall. Center open to roof. Part of lumber salvaged from Olympis Church.

21. Historical Significance

Theme(s) _____ Special Function; Cattle type.

- a. Key structure/individually may qualify for the National Register
- b. Contributing structure
- C. Not eligible/intrusion

This barn was originally built to shelter purebred Herefords and horses and as of 1979 was still used for cattle, as well as for hogs and to store grain. Cattle barns are generally characterized by an open floor plan, which is the case with this barn. The construction, in the early 20th century, of special function barns represented an important experimental shift in the traditional use of the barn.

22. Sources (for primary and secondary sources, give complete facts of publication: author, title, place of publication, date, etc.):

Lester Haner, RR 2, Moorhead, IA 51558 Dwight I. Mills, Harrison County Laison Officer, RR 1, Dunlap, IA 51529 Soike, Lowell J. <u>Without Right Angles</u>. Des Moines, Iowa: Iowa State Historical Department, Office of Historic Preservation, 1983.

Prepared by	_Date
Address	Telephone
Organization	

For Office of Historic Preser	rvation Use Only
 Office Information Sources on this Property County Resource File 	Review and Compliance Project:
☐ Windshield Survey	Other
□ National Register	Other
Grants-In-Aid:	Other
Determination of Eligibility	
	3. Photo Images
2. Subject Traces	
à.	
b	
(
d	
e	