

#1

Southwest (facade) elevation Wilkinson-Swem Building 217 East Main Street Medford, Jackson County, Oregon

Photography: Unknown

Negative: detail #2076(enlarged detail)

S.O.H.S.

Date of photograph: ca. 1900

North view

Special **⊀**eature: Compare with #8

Photo 1 of 14

This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, Jacksonville Museum, Box 480, Jacksonville, Oregon 97530. SOHS neg. no.\_\_\_\_\_

Portion 7 Ney



#2 Commercial structures northside East
Main Street.
Major Commercial buildings, (1 to r),
Lindley Bld. Wilkinson-Swem Bld.,
J.H. Steward blg. & Barnum and McAndrews blg.
Medford, Jackson County, Oregon
Photographer: Unknown
Negative: #4383 SOHS DATE: ca 1904
North view - special feature:"City
Meat Market, Arnold and Barnegurg"
near the Wilkinson-Swem Blg.
Photo 2 of 14

Mredford, Or.

Street Construction

Mr. Beck in center with hat.

Ed Root with broom

and dog, "Cal Wash" that belonged to Ed Root.

This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, Jacksonville Museum, Box 480, Jacksonville, Oregon 97530. SOHS neg. no.\_\_\_\_\_



#3 Southeast (facade) elevation
Wilkinson-Swem Bldg. (center)
217 East Main Street
Medford, Jackson County, Oregon
Photographer: Unknown
Negative: #4818 SOHS
Date: ca. 1905
Northwest view
Special feature: Compare with #'s 6 & 7
Photo 3 of 14

Medford Street Scene - 1905 (East main St)

This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, Jacksonville Museum, Box 480, Jacksonville, Oregon 97530. SOHS neg. no.



#4 Interim view, Wilkinson Meat Market Wilkinson-Swem Bldg.
217 East Main Atreet
Medford, Jackson Co., Oregon
Photographer: Unknown/Barneburg
Collection

Negative: #4830 SOHS

Date: ca. 1900 Special feature: Edward H. Wilkinson, (r)

Photo #4 of 14

Ory. Jeon Barreburg Collection



## OREGON HISTORICAL SOCIETY COLLECTIONS.

#5 Commercial structures north side,
East Main Street
Major commercial buildings (1 to r)
Lindley, blg., Wilkinsom-Swem blg.
Phipps, blg., J. H. Steward blg.
(roof only), Barnum and McAndrews
blg., Hubbard Bros. Hdwr. blg., and
Sparta blg.
Medford, Jackson County, Oregon
Photographer: Unknown

Negative: #2930 SOHS
Date of Photograph: ca. 1915
North view
Special feature: Southern Oregon
Traction Co. streetcar
Photo #5 of 14



#6 Commercial structures north side, East
Main Street
First 7 commercial bldgs. (r to 1)
J. H. Stewart Blg. Phipps blg.,'
Wilkinson-Swem Blg., Lindley Blg.
(hidden by Wilkinson bay window),
Harris blg., Jackson County Bank,
(Central Avenue) and Medford National
Bank.
Medford, Jackson County, Oregon
Photographer: Unknown

Negative: #2475 SOHS
Date of Photograph: ca. 1920
Northwest view
Special feature: compare with photo.
#'s 3 and 7

Photo #6 of 14

This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, acasonville Museum, Box 480, Jacksonville, Oregon 97530. SOHS neg. no.

2475



#7 Commercial structures northside, East
Main Street,
First 7 commercial bldgs. (r to 1),
J. H. Stewart blg. (first two storefronts from corner), Phipps blg. Wilkinson-Swem blg. (center of block), Lindley
blg. (hidden behind it own massive
awning), Harris blg., Jackson County
Bank, (Central Ave.) and U.S. National
Bank (1965 replaced the 1906 structure).
Medford, Jackson County, Oregon

Negative: #4031 SOHS

Date of Photograph: Dec. 23, 1980

Northwest view

Special feature: compare with Photo

no's 3 and 6. Photo #7 of 14

Photo by Douglas & Smith



Southeast (facade) elevation Wilkinson-Swem Building #8 2/17/ East Main Street Medford, Jackson County, Oregon. photographer: Douglas R. Smith, staff SOHS.

Negative # 4849 SOHS


Date of Photograph: November 8, 1981

Northview

Special feature: compare with #1 Photo #8 of 14

This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, Jacksonville Museum, Box 480, Jacksonville, Oregon

97530. SOHS neg. no.\_\_\_



Northwest Elevation Wilkinson Swem Blog. 217 East Main St medford, Or.

Northwest (rear) elevation Wilkinson-Swem Building 217 East Main Street Medford, Jackson County, Oregon Photographer: Douglas R. Smith, staff, SOHS.

> Negative: #4848, SOHS Date of photograph: November 8, 1981 Southeast view

Photo #9 of 14

Photo by Douglai R. Smith 11-8-81



#10 Northeast and northwest (rear) elevations
Wilkinson-Swem Building
217 East Main Street
Medford, Jackson County, Oregon
Photographer: Douglas R. Smith,
staff, SOHS
Negative: #4846 SOHS
Date of Photograph: Nov. 8, 1981
South view
Special feature: Rear of Phipps blg.,

(left) - rear of Lindley blg.(right)

Photo #10 of 14

Photo day Douglas P Smith 11-8-81



This photograph is released for reference use only. NOT FOR PUBLICATION. Southern Oregon Historical Society, Jacksonville Museum, Box 480, Jacksonville, Oregon 97530. SOHS neg. no.

#11 Interior detail curved staircase
(1953)
Wilkinson-Swem Building
217 East Main Street
Medford, Jackson County, Oregon
Photographer: Douglas R. Smith,
staff, SOHS
Negative: #4863 SOHS
Date of Photograph: Nov. 8, 1981
Special feature: renovation in progress.
Shingled counter (r. of stairs removed)
Photo # 11 of 14

Photo by Douglas R. Smith 11-8-81



#12 Interior detail, looking towards storefront (first floor) and bay window
(second floor) from the mezzanine.
Wilkinson-Swem Building
217 East Main Street
Medford, Jackson County, Oregon
Photographer: Douglas R. Smith,
staff, SOHS.
Negative: #4853 SOHS
Date of Photograph: Nov. 8, 1981
Southeast view

Special feature: Ornamental wroughtiron railings with monogramed "S". Photo #12 of 14

Photo by Douglas A Smith



#13 Interior detail, Bay window detail,
 (second floor)
 Wilkinson-Swem Building
 217 East Main Street
 Medford, Jackson County, Oregon
 Photographer: Douglas R. Smith,
 staff, SOHS
 Negative: #4862 SOHS
 Date of photograph: No.v 8, 1981
 Southeast view
 Special feature: Fireplace location,
 (right); pattern of multi-colored
 lights in central, double hung,
 sash window.
 Photo #13 of 14

Photo by Douglas R. Smith 11-8-81



Frieglace - Interior 2nd floor - front room Southwest wall It Ihim - Swem Bldg. Medford Dugen - 1981

Wilkinson-Swem Bldg.
217 East Main Street
Medford, Jackson County, Oregon
Photographer: Douglas R. Smith,
staff, SOHS
Negative: #4854 SOHS
Date of Photograph: Nov. 8, 1981
Photo #14 of 14

(second floor)

#14

Interior Detail, overmantel Fireplace,

Phato by Douglas R. Smith