



Clover Hill

Montgomery County, Maryland

Photo: Sheldon R. Mandel

January 1980

Neg: Maryland Historical Trust, AnnapolisMD

East Facade

1/12

JUN 7 1982

M.D.

SE

2/14



Clover Hill

Montgomery County, Maryland *H. 28 23/51* JUN 7 1982

November 1978

Photo: Hal Etinger

Neg: Maryland Historical Trust, Annapolis, MD
East Facade - Main Entrance

2/12

2

CLOVER HILL
Montgomery County

1 of 11

E
South Facade, Main Entrance - 19th cen
Hal Etinger, Jan. 1979

neg. at MHT

JAN 29 1980



Clover Hill

Montgomery County, Maryland

November 1978

Photo: Hal Ettinger

Neg: Maryland Historical Trust, AnnapolisMD

East facade - Main Entrance

3/12

Handwritten: JUN 7 1982

CLOVER HILL
Montgomery County

Handwritten: 2 of 11

South Facade-Main Entrance-19th cen.

Hal Ettinger, Jan. 1979

Handwritten: Neg. at MHT

JAN 29 1980



Clover Hill

JUN 7 1982

Montgomery County, Maryland

Photo: Hal Ettinger, January 1979

Neg: Maryland Historical Trust, Annapolis, MD

N.W. Facade shows 18th & 19th century portions joining

4/12

CLOVER HILL
Montgomery County

NW
West Facade-shows 18th & 19th cen.
portions joining
Hal Ettinger, Jan. 1979



Clover Hill
Montgomery County, Maryland
January 1979
Photo: Hal Ettinger
Neg: Maryland Historical Trust, Annapolis, MD
Main stairwell-looking from 19th cen. 2nd fl.
to 18th cent. 2nd floor
5/12

JUN 7 1982

CLOVER HILL
Montgomery County

4 of 11
Neg. at MHT
Main Stairwell-looking from 19th
cen. second floor to 18th cen.
second floor.

Hal Ettinger, Jan. 1979

JAN 29 1980



Clover Hill
Montgomery County, Maryland JUN 7 1982
January 1979

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD
Stairwell detail looking from 19th cen. 1st
fl. to 18th cent. 2nd floor 6/12

5 of 11
CLOVER HILL
Montgomery County

Neg. at MHT
Stairwell detail looking from 19th
cen. first floor to 18th cen. 2nd
floor Hal Ettinger, Jan. 1979

JAN 29 1980



Clover Hill
Montgomery County, Maryland
January 1979

JUN 7 1982

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD

Window and balcony detail of S. facade

2nd floor

7/12

CLOVER HILL
Montgomery County

6 of 11

Window and balcony detail of south
facade, 2nd floor

Hal Ettinger, Jan. 1979

Neg. at MHT

JAN 9 1980



Clover Hill

Montgomery County, Maryland

1992

January 1979

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD

Window detail-west wing living room#1

8/12



Clover Hill

Montgomery County, Maryland

January 1979

UN

7 1982

Photo: Hal Etinger

Neg: Maryland Historical Trust, Annapolis, MD

Fireplace detail-2nd fl. library- W. wing

9/12



Clover Hill

Montgomery County, Maryland

JUN

7 1982

January 1979

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD

Detail of 18" drop from 18th cen. hallway

looking to 19th cen. level

10/12



Clover Hill
Montgomery County, Maryland
January 1979

110611
JUN 7 1982

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD

Fireplace & window detail of 18th cen.

living room #2

11/12



Clover Hill

Montgomery County, Maryland

JUN 7 1982

January 1979

Photo: Hal Ettinger

Neg: Maryland Historical Trust, Annapolis, MD

Detail of 18" drop from 18th cen. and original
18th cen Newell post. 12/12