



Driskell-Martin House (Plantersville MRN #1)
Plantersville, Alabama, Dallas County

Carl Kling, Nov. 1977
Alabama Historical Commission

East facade, close up

Photo number: 1

Although photograph was taken 9 years ago, it reflects the current condition of the property and was verified in the summer of 1986 by

SHPO staff Tom Dolan.



Driskell-Martin House (Plantersville MRN #1)
Plantersville, Alabama, Dallas County

Carl Kling, November 1977
Alabama Historical Commission

East facade

Photo number: 2

Although photograph was taken 9 years ago, it reflects the current condition of the property and was verified in the summer of 1986 by SHPO staff Tom Dolan.



Driskell-Martin House (Plantersville MRN #1)
Plantersville, Alabama, Dallas County

Carl Kling, November 1977
Alabama Historical Commission

Interior, south front parlor, showing mantel
and plaster work

Photo number: 3

Although photograph was taken 9 years ago, it
reflects the current condition of the property
and was verified in the summer of 1986 by SHPO
staff Tom Dolan.



Driskell-Martin House (Plantersville MRN #1)
Plantersville, Alabama, Dallas County

Carl Kling, November 1977
Alabama Historical Commission

Detail of entrance, east facade

Photo number: 4

Although photograph was taken 9 years ago, it reflects the current condition of the property and was verified in the summer of 1986 by SHPO staff Tom Dolan.



Driskell-Martin House (Plantersville MRN #1)
Plantersville, Alabama, Dallas County

Carl Kling, November 1977
Alabama Historical Commission

Interior central hall w/staircase, looking west

Photo number: 5

Although photograph was taken 9 years ago, it reflects the current condition of the property and was verified in the summer of 1986 by SHPO staff Tom Dolan.