



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: view from west

Photograph Number: 1 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: view from west - barn

Photograph Number: 2 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: view from west - cow barn and dairy

Photograph Number: 3 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: fleur-de-lis in north parlor

Photograph Number: 4 of 8





Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: mantel in north parlor

Photograph Number: 5 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: center stair

Photograph Number: 6 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: mantel in south parlor

Photograph Number: 7 of 8



Name: Mifflin Marim Agricultural Complex

Location: Route 9 below Muddy Branch, Little Creek Hundred, Kent County, Delaware

Photographer: Stephen G. Del Sordo

Date of Photograph: August 1983

Location of Negative: Bureau of Archaeology & Historic Preservation

Description: south parlor end wall

Photograph Number: 8 of 8