



Silver Houses Historic District

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

View west from J.A. Silver House Site (HA-385)

From left: Deer Creek Harmony Presbyterian Ch.

(HA-165); Silas B. Silver House (HA-407);  
Benjamin Silver House (HA-398); W.F. Silver  
House (HA-389)

1 of 48



Silver Houses Historic District

HA-408

(John A. Silver House Site - HA-385)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

Barn, north elevation  
2 of 48



Silver Houses Historic District

HA-408

(John A. Silver House Site - HA-385)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Barn and wagon sheds from west

3 of 48



Silver Houses Historic District

HA-408

(John A. Silver House Site - HA-385)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Tenant House, South elevation

4 of 48





Silver Houses Historic District

HA-408

(Jeremiah P. Silver House - HA-384)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

North elevation

5 of 48



Silver Houses Historic District  
(Jeremiah P. Silver House - HA-384)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevation and rear wing

6 of 48



Silver Houses Historic District  
(Jeremiah P. Silver House - HA-384)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

East elevation and rear wing

7 of 48

---



Silver Houses Historic District  
(Jeremiah P. Silver House - HA-384)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: living room

8 of 48





Silver Houses Historic District  
(Jeremiah P. Silver House - HA-384)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg location: Maryland Historical Trust

Interior: living room mantel

9 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevation

10 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Entrance detail

11 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

West and south elevations

12 of 48





F  
M  
ASSN  
ON G

Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

North elevation and rear wing

13 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: dining room

14 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Parlor

15 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Parlor mantel

16 of 48

---





Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Log smokehouse, east elevation

17 of 48



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Log smokehouse, south elevation

18 of 48

---



Silver Houses Historic District  
(Benjamin Silver House - HA-398)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust  
Tenant house, south elevation

19 of 48



Silver Houses Historic District  
(Benjamin Silver Barn - HA-399)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

North elevation

20 of 48





Silver Houses Historic District HA-408  
(B. Silver Dairy, HA-400; Slave Quarters, HA-401; Smokehouse, HA-402)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevations 21 of 48



Silver Houses Historic District                      HA-408  
(B. Silver Icehouse, HA-403; Carriage Houses,  
HA-404)

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevations              22 of 48



Silver Houses Historic District  
(B. Silver Corncrib - HA-405)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevation

23 of 48



Silver Houses Historic District  
(B. Silver Calf Pens - HA-406)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

South elevation

24 of 48





Silver Houses Historic District  
(William F. Silver House - HA-389) HA-408  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
November 1982  
Neg. location: Maryland Historical Trust  
South elevation  
25 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
November 1982  
Neg. location: Maryland Historical Trust  
West elevation

HA-408



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

East elevation

27 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Entrance hall

28 of 48





Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Stair detail

29 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Living room

30 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Dining room mantel

31 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

Slave quarters, south elevation

32 of 48





Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Barn, east elevation detail

33 of 48



Silver Houses Historic District  
(William F. Silver House - HA-389)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Tenant house, south elevation



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

North elevation

35 of 48



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

East elevation

36 of 48





Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland :

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Entrance hall

37 of 48



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

Interior: Mantel

38 of 48



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

Smokehouse and woodshed, north elevations

39 of 48



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

Carriage house, north elevation

40 of 48





Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity  
Harford County, Maryland

Photo: Janet Davis

August 1983

Neg. location: Maryland Historical Trust

View west from barn

41 of 48



Silver Houses Historic District  
(Silas B. Silver House - HA-407)

HA-408

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

View north from house

42 of 48



Silver Houses Historic District

HA-408

(Deer Creek Harmony Presbyterian Church HA-165)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis

November 1982

Neg. location: Maryland Historical Trust

General view from northeast

43 of 48

---



Silver Houses Historic District HA-408  
(Deer Creek Harmony Presbyterian Church HA-165)  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
November 1982  
Neg. location: Maryland Historical Trust  
Northeast elevation  
44 of 48





Silver Houses Historic District                      HA-408  
(Deer Creek Harmony Presbyterian Church HA-165)  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
August 1983  
Neg. location: Maryland Historical Trust  
Interior: View toward rear of sanctuary

45 of 48



Silver Houses Historic District                      HA-408  
(Deer Creek Harmony Presbyterian Church HA-165)  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
August 1983  
Neg. location: Maryland Historical Trust  
Interior: View toward pulpit  
46 of 48

---



Silver Houses Historic District HA-408  
(Deer Creek Harmony Presbyterian Church HA-165)

Darlington vicinity

Harford County, Maryland

Photo: Janet Davis


August 1983

Neg. location: Maryland Historical Trust

Interior: Window detail

47 of 48

26



Silver Houses Historic District                      HA-408  
(Deer Creek Harmony Presbyterian Church HA-165)  
Darlington vicinity  
Harford County, Maryland  
Photo: Janet Davis  
August 1983  
Neg. location: Maryland Historical Trust  
Interior: Pew detail  
48 of 48

---