



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (1 of 15): Driveway and house  
from entrance gates; photographer facing  
north.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (5 of 15): Rear of house; photo-  
grapher facing southeast.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (6 of 15): East side of house;  
photographer facing southwest.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (7 of 15): Front porch; photo-  
grapher facing west.





CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (8 of 15): First-floor stair-  
hall; photographer facing northwest.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (9 of 15): First-floor living  
room; photographer facing northwest.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (10 of 15): First-floor dining  
room; photographer facing northwest.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (11 of 15): First-floor library;  
photographer facing northwest.





CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (12 of 15): Southeast bedroom,  
second floor, original section of house;  
photographer facing northeast.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (13 of 15): Northwest bedroom,  
second floor, original section of house;  
photographer facing southwest.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (14 of 15): Nut house (left)  
and garage (right); photographer facing  
north.



CRESTWOOD

Valdosta, Lowndes County, Georgia

Photographer: James R. Lockhart

Negative filed: Georgia Department of  
Natural Resources

Date: February, 1983

Description (15 of 15): Pecan grove surrounding front of house; photographer facing northwest.