



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 1 of 33.  
East (front) elevation.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 2 of 33.  
West (rear) elevation.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 3 of 33.

East (front) elevation, showing the main entrance.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 4 of 33.

Northeast corner (front and side) elevation.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 5 of 33.

North elevation, showing sunroom windows and side porch.




Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 6 of 33.

North elevation, showing the porch with the south wing  
in the distance.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 7 of 33.

North elevation of the south wing, from a rear window  
of the second floor, showing the bay and mansard roof  
of the south wing.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 8 of 33.

South elevation, showing the garage and servant's quarters.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 9 of 33.  
South elevation.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 10 of 33.

East (front) elevation, also showing the south  
elevation.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 11 of 33.

East elevation (front), showing details of the new  
roofs of the entry porch and front bay.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 12 of 33.

North elevation, showing details of the wrought iron railing of the porch.






Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 13 of 33.

Main hall and staircase, looking southwest.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 14 of 33.

Main hall, looking northeast, showing bay windows and  
tiled entry hall.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 15 of 33.  
Library, looking southwest.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 16 of 33.

Living room, looking north, showing rug, fireplace,  
with the sunroom beyond.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 17 of 33.  
Sunroom, looking northwest.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 18 of 33.

Dining room, looking west, showing window overlooking  
garden, and doors to porch.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 19 of 33.  
Side entry hall, looking south.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 20 of 33.

Pantry, looking south, showing cabinets, first floor  
door of the wood lift, and the breakfast nook beyond.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 21 of 33.  
Kitchen, looking southeast.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 22 of 33.

Kitchen, looking southwest, showing the original  
refrigerator.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 23 of 33.

View down the main staircase from the second floor  
landing, looking east, showing details of the railings,  
and the bay windows beyond.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 24 of 33.

Main second floor hall, looking southeast, showing railing, chandelier, and details of woodwork.






Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 25 of 33.

Main second floor hall, looking northeast, showing  
details of woodwork.




Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 26 of 33.

Master bedroom, looking east.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 27 of 33.  
Sitting room of master suite, looking northwest.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 28 of 33.

Bathroom, northwest corner of the second floor, looking  
northwest, showing details of tile and fixtures.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 29 of 33.

Bedroom, northwest corner of the second floor, looking southwest.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 30 of 33.

Bedroom, southeast corner of the second floor, looking east.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 31 of 33.

Bedrooms and connecting bath, south wing, looking west through the door of the large southeast corner bedroom into the center bedroom and on through the bath to the bedroom in the southwest corner.



Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 32 of 33.  
Southwest corner bedroom, south wing, looking west.





Wheeler, Mrs. Coleman H. (Cora)  
House (1923)  
1841 S.W. Montgomery Drive,  
Portland, Multnomah County, Oregon

James W. Fiscus and Associates Photo (1989)  
3253 S.E. Belmont,  
Portland, Oregon 97214

Number 33 of 33.

West garden, looking west, from the second floor of the house, showing original horseshoe bench, with garden and fountain beyond.