

FORM 10-301 A (6/72)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Federal Building		AUG 1 5 1974
2. LOCATION		
STATE	COUNTY CALLANT	TOWN
New Mexico	Santa Fe	Santa Fe
STREET AND NUMBER	IN RECEIVED	
	MAYO	
Cathedral Pl. at Palace	1974	
3. PHOTO REFERENCE	A NATION	
PHOTO CREDIT	DATE REGIST 3	NEGATIVE FILED AT
Warma Roll	May 17, 1973	GSA, WASHINGTON, DC
Wayne Bell	riay 1/ , 1973 6	,,
4. IDENTIFICATION	[101]].	

DESCRIBE VIEW, DIRECTION, ETC.

View of north facade showing main entrance flanked by open courtyard in front of which is covered walkway.

#143



FORM 10-301 A (6/72)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Federal Building		AUG 1 5 1974
2. LOCATION	ITIET.	
New Mexico	Santa Fe	Santa Fe
STREET AND NUMBER	AT RECEIVED I	1 En
Cathedral Pl. at Palace	MAY 9 1974	18
3. PHOTO REFERENCE	T-I NATIONA	
PHOTO CREDIT	DATE REGISTE	NEGATIVE FILED AT
Wayne Bell	May 17, 1973	GSA, WASHINGTON, DC
4. IDENTIFICATION		

DESCRIBE VIEW, DIRECTION, ETC.

View of northeast corner showing main facade (east) with covered walkway and central courts flanked by one and two story projecting wings.

#2 073



FORM 10-301 A (6/72)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Federal Building	9-14-16	AUG 1 5 1974
2. LOCATION		
New Mexico	Santa Fe 14115	Santa Fe
STREET AND NUMBER Cathedral Pl. at Palace	RECEIVED MAY 9 1974	
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE ANATIONAL	NEGATIVE FILED AT
Wayne Bell	May 17, RE97STE	GSA, WASHINGTON, DC
4. IDENTIFICATION	/ /FILLIAN \	

DESCRIBE VIEW, DIRECTION, ETC.

View from southwest corner showing rear of building which was formerly postal dock area.