MASON CITY, IOWA	IDENTIFICATION (1.3.) NUMBER COUNTY
Cerro Gordo County	1. Common Name Kenneth Schulthers House
HISTORIC BUILDINGS &	i i
SITES FIELD SURVEY	2. Historic Name C,P, Shipley House
Environmental Planning and Research, Inc.	3. Address 114 3rd St. N.W.
Surveyed by: Ronald Schmitt, Architect	
Survey Date: 11-5-76 Research by: R.S.	4. Subdiv. Felts Plat Blk. 2 Parcel 6.55 of 8  5. UTM: 15/482490 4777790 Acreage: less than one
INFORMATION	
1. Present Owner KanhEl B. SCHUMEIS	
2. Owner's Address 114 3rd St. N.W.	
3. Use: Original house	
Present LOUSE	
4. Construction Date 1913	
5. Accessible to Public? Yes No_V_	
6. Zoning District G-BUSINESS	
7. Maintenance: Excellent Good Fair Poor	
Structure	
Adjacent Buildings	
Vicinity	
MATURE OF SITE DESCRIPTION	<b>1</b>
	es: a) one b) two v c) three d) other
Site Other 2. Building mate	erials: a) ext. walls Stucco
SOURCE OF INTEREST b) foundat	ion stuce (ever brick?)c) roof NiV. d) porches
	wood trim, brick chimney
3. Intensity:	a) original site / b) moved d)from
ARCHITECTURAL QUALITY	
Excellent	Iterations (dates if known)
Fair	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
Poor 4. Threats to Si URBAN DESIGN VALUE	re: none known, however, condition, location & joning against retention
Exceptional 5. Significant F	Features: SEE back
Good	
Minor	
SIGNIFICANCE	
Neighborhood ADDITIONAL R	EMARKS
State	
CONDITION	. No.
Sound Min. Def. SOURCES A C	ity Sewer Records
Maj. Def.	Ty Jower records
Substandard	
Points Group 2 Photos R=6	Mapped Other See back of page 🗸

## 5. SIGNIFICANCE CBD-14

The house, although suffering from deterioration, is a good example of the Prairie School Style. It has a broad, overhanging, low-pitched hip roof; grouping of windows in a non-traditional manner; a centralized chimney; and stucco walls of visual weightlessness. All were characteristics of the radical design approach of the movement. The use of double-hung windows was the major throwback to traditional design.