



Rock Hill school, Rock Hill Drive
LINN Co., OREGON

May 1991, Rosalind Keeney

925 SW. 5th Avenue

Albany, Oregon 97321

east (front) and south facades

1 of 20



Rock Hill School
Rock Hill Drive
LINN Co., Oregon

Rosalind Keeney, May 1991

925 S.W. 5th Ave.

Albany, Oregon 9732

east (FRONT) facade

2 of 20



Rock Hill School
Rock Hill Drive
Linn County, Oregon

Rosalind Keeney, May 1991

925 S.W. 5th Ave.

Albany, Oregon 97321

North facade

3 of 20



Rock Hill School

Rock Hill Drive, Linn County, Oregon

Rosalind Keeney, May 1991

925 S.W 5th Avenue

Albany, Oregon 97321

South (side facing Rock Hill Drive) facade

4 of 20



Rock Hill School

Rock Hill DRIVE

Linn County, OREGON

Rosalind Keeney, May 1991


925 S.W. 5th AVENUE

ALBANY, OREGON 97321

West

(Rear) facade

5 of 20



ROCK HILL DIST. 31.

Rock Hill School

Rock Hill Drive

Linn County, Oregon

Rosalind Keener, May 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

close up of bracket and sign
above front door

East facade

6 of 20



Rock Hill School
Rock Hill Drive
Linn County, Oregon
Rosalind Keeney, May 1991
925 S.W. 5th Avenue
Albany, Oregon 97321

close up of Bell Tower
east Facade

7 of 20



Rock Hill School

Rock Hill DRIVE

Linn County, OREGON


Rosalind Keeney, May 1991

925 S.W. 5th Ave.

Albany, OREGON 97321

close up of frieze and corner boards
on Northeast corner

8 of 20



Rock Hill School
Rock Hill Drive
Linn County, Oregon
Rosalind Keeney May 1991
925 S.W. 5th Avenue

Albany, Oregon 97321

close up of vandalized window
on the south facade

9 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon

Linda Jones, September 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

INTERIOR showing three of the four
windows on the South side

11 of 20



Rock Hill School
Rock Hill Drive
Linn County, Oregon
Rosalind Keeney, May 1991
925 S.W. 5th Avenue

Albany, Oregon 97321

close up of siding near entrance
on the east facade.

10 of 20



Rock Hill School

Rock Hill DRIVE

Linn County, OREGON

Linda Jones, September 1991

925 S.W. 5th AVENUE

ALBANY, OREGON 97321

INTERIOR NORTHWEST CORNER
showing door to the wood shed
and chalk boards

12 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon

Linda Jones, September 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

INTERIOR NORTH WEST CORNER
showing door to woodshed and
open exterior woodshed door

13 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon

Linda Jones, September 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

INTERIOR east (FRONT) end showing
ENTRANCE door opening, wood stove
grate on floor, part of coat hanging area,
and attic access opening

14 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon


Linda Jones, September 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

INTERIOR showing east side
showing coathanging area and
part of the north side

15 of 20



Rock Hill School

Rock Hill Drive

Lincoln County, Oregon

Linda Jones, September 1991

925 SW 5th Avenue

Albany, Oregon 97321

Interior close up of coathanging area

16 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon

Linda Jones, September 1991

925 S.W. 5th Avenue.

Albany, Oregon 97321

Interior, west end showing chimney
with chimney pipe wire, chalkboard area,
and wainscoting.

17 of 20



Rock Hill School

Rock Hill Drive

Linn County, Oregon


Rosalind Keeney May 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

Interior east end showing straw
stored in building before September
cleanup.

18 of 20



Rock Hill School.

Rock Hill Drive

Linn County, Oregon

Linda Jones, September 1991

925 S.W. 5th Avenue

Albany, Oregon 97321

South facade showing protective window
covers painted to look like historic
characters looking out.

19 of 20



Rock Hill School
Rock Hill Drive
LINN COUNTY, OREGON

Rosalind Keeney
925 S.W. 5th Ave.
Albany, Oregon 97321

Historic view c. 1924
20 of 20