



Photograph 1 of ~~14~~ 24

The Burnham/Marston Residence,

3563 Seventh Avenue

San Diego, CA 92103

Photo: S.D. Historical Society

Ticor Collection c1907

View: Southwest to Northeast

AUG 19 1986



Burnham residence, San Diego, 1906-1907

Photograph 2 of ~~24~~ 24

AUG 19 1986

Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103

Photographer: Marvin Rand (Appeared in  
Irving Gill, 1870-1936, Silverlake  
Lithographers, 1958.

Date: c. 1907

Location of Negative: Marvin Rand

View: From the East, looking West,  
Foliage today prevents this view.



Photograph 3 of ~~24~~ 24

The Hamilton Marston house left front;  
Burnham/Marston house at right.

The Burnham/Marston Residence,

3563 Seventh Avenue


AUG 19 1986

San Diego, CA 92103

Photo: S.D. Historical Society

Ticor Collection. c1924

View: west to east



Burnham House, San Diego, 1906 1907

Photograph 4 of ~~10~~ 24

AUG 19 1986

The Burnham/Marston Residence,  
3563 Seventh Avenue  
San Diego, CA 92103

Photo: Irving Gill, 1870-1937.  
Silverlake Lithographers, 1958,  
photo by Marvin Rand.

View: Stairwell near front entrance  
of Burnham/Marston house reflecting  
spindle staircase.





*F. R. Burnham*

Photograph 5 of ~~10~~ 24 AUG 19 1986

Frederick R. Burnham, M.D.

Photo: From Clarence A. McGrew,  
San Diego City and San Diego County

Vol. 2, pp. 435. c1924



Photograph 6 of ~~24~~ 24

The Burnham/Marston Residence,  
3563 Seventh Avenue

San Diego, CA 92103

AUG 19 1986

Photo: by Ray Brandes, 1985.

View: From west at drive looking east  
reflecting foliage, window style and  
brick placement. Entrance to  
residence is left of photo.



Photograph 7 of ~~23~~ 24

The Burnham/Marston Residence,

3563 Seventh Avenue

San Diego, CA 92103

AUG 19 1986

Photo: by Ray Brandes,

2725 Barnson Pl., San Diego, CA 92103,  
1985.

View: Photo reflects front porch area,  
main door entrance to right and the  
Gill/Hebbard use of wood and brick at  
the several levels of construction.



AUG 19 1986

Photograph 8 of ~~40~~ 24

Burnham/Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Dr. Ray Brandes

Date: 1985

Location of NegativeL Dr. Ray Brandes

View: From North to South, taken from  
yard area beyond the North entry  
terrace





AUG 19 1986

Photograph 9 of ~~24~~ 24

The Burnham/Marston Residence,  
3563 7th Ave. San Diego, CA 92103

Photo: by Ray Brandes, 2725 Barnson Pl.,  
San Diego, CA 92103. 1985.

View: is from south side looking north  
giving fine view of the use of timber  
and brick in construction. This  
entrance looks through to main entry  
on north side of house.



AUG 19 1986

Photograph 10 of ~~24~~ 24

The Burnham/Marston Residence,  
3563 Seventh Ave.

San Diego, CA 92103

Photo: by Ray Brandes, 2725 Barnson Pl,  
San Diego, CA 92103. 1985.

View: is from south side lower patio  
with stairs to first floor outdoor  
open porch. Door at left is to base-  
ment area. View to north.



Photograph 11 of ~~11~~ 24 AUG 19 1986  
The Burnham/Marston Residence,  
3563 Seventh Ave.

San Diego, CA 92103

Photo: by Ray Brandes, 2725 Barnson Pl.,  
San Diego, CA 92103. 1985.

View: is from south to north reflecting  
entryway into main part of house. From  
this view one may see straight through  
to front door entry. Closeup of  
timber and brick construction.



Photograph 12 of ~~12~~ 24 AUG 19 1986

Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103

Photographer: Dr. Ray Brandes

Date: 1985

Location of Negative: Dr. Ray Brandes

View: Looking North showing stairs,  
terrace and enclosed first and  
second floor porches projecting  
east





Photograph 13 of ~~12~~24      AUG 19 1986  
Burnham/Marston Residence,  
3563 7th Ave. San Diego, CA 92103  
Photo: by Ray Brandes, 2725 Barnson Pl.  
San Diego, CA 92103. 1985.  
View: just inside main entry facing  
stairwell, reflecting paneling and  
the spindle staircase. From here  
looking south, one sees clear through  
large doors to the south canyon lawn  
and area.



Photograph 14 of ~~24~~ 24

AUG 19 1985

Burnham/Marston Residence,  
3563 7th Ave. San Diego, CA 92103  
Photo: by Ray Brandes, 2725 Barnson  
Place, San Diego, CA 92103. 1985.  
View: At second floor level, north  
side of bannister which encircles  
stairwell. Enclosed porch area is  
seen through doorway at left.



Supplemental Photograph 15 of 24

Burnham/Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Dr. Ray Brandes

Date: June 1986

Location of Negative: Dr. Ray Brandes

View: From West, looking East, supplement  
to Photograph No. 6, further  
illustration of landscaping



Supplemental Photograph 16 of 24

Burnham/Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Dr. Ray Brandes

Date: June 1986

Location of Negative: Dr. Ray Brandes

View: From South, looking North, supplement  
to Photograph No. 10, further  
illustrates stair entrance to first  
floor rear porch





Supplemental Photograph <sup>17</sup> of <sup>24</sup>  
Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103

Photographer: Dr. Ray Brandes

Date: June 1986

Location of Negative: Dr. Ray Brandes

View: Facing North, looking through stair  
hall toward present primary entrance,  
supplement to Photograph No. 13,  
taken from the opposite direction



Supplemental Photograph <sup>18</sup> of <sup>24</sup>  
Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103  
Photographer: Dr. Ray Brandes  
Date: June 1986  
Location of Negative: Dr. Ray Brandes  
View: Driveway entrance to property,  
looking East



Supplemental Photograph <sup>19</sup> of <sup>24</sup>  
Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103  
Photographer: Dr. Ray Brandes  
Date: June 1986  
Location of Negative: Dr. Ray Brandes  
View: Driveway entrance looking West  
towards front gate



Supplemental Photograph 20 24  
● of ●  
Burnham/Marston Residence,  
3563 Seventh Avenue, San Diego, CA 92103  
Photographer: Dr. Ray Brandes  
Date: June 1986  
Location of Negative: Dr. Ray Brandes  
View: To the West showing curved driveway  
and landscaping





Garage Photograph 21 of 24

Burnham/Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Toni L. Nagel-Walston

Date: June 24, 1986

Location of Negative: Dr. Ray Brandes

View: Facing East, West Elevation



Garage Photograph 22 of 24

Burnham/Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Toni L. Nagel-Walston

Date: June 24, 1986

Location of Negative: Dr. Ray Brandes

View: Facing Northwest, East Elevation



Garage Photograph 23 of 24

Burnham/Marston Residence

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Toni L. Nagel-Walston

Date: June 24, 1986

Location of Negative: Dr. Ray Brandes

View: Facing Southeast, North Elevation



Garage Photograph **24** of **24**

Burnham Marston Residence,

3563 Seventh Avenue, San Diego, CA 92103

Photographer: Toni L. Nagel-Walston

Date: June 24, 1986

Location of Negative: Dr. Ray Brandes

View: Facing West, South Elevation visible  
in left portion of photograph