

Main Street National Register District Willimantic, Connecticut View looking southeast at southeast edge of district with Sadd Block at right. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View looking south at #746 Main Street in relation to adjacent structures. Photo by Margo Webber, July, 1980.

Negative on file at Connecticut Historical Commission.

-



# Main Street National Register District Willimantic, Connecticut

View looking southwest at Sadd Block and #776 Main Street. Photo by Margo Webber, July, 1980. Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View looking southwest on Main Street from Ben's Eagle Shoes to Chapman Block. Photo by Margo Webber, July, 1980

Negative on file at Connecticut Historical Commission.

-



Main Street National Register District

Willimantic, Connecticut

View looking northeast at Willimantic Savings and Loan, First Baptist Church.

Photo by Margo Webber, July, 1980

Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View looking northwest at Murray Building. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View from Church Street towards north side of Main Street. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut Facade of Nassiff's at 745 Main Street. Photo by Margo Webber Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut

View northwest from Hayden Block (at right) along Main Street. Photo by Margo Webber, July, 1980. Negative on file at Connecticut Historical Commission.




Main Street National Register District Willimantic, Connecticut

View northeast on Main Street from #873 Main Street to Nathan Hale Hotel. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Photo #11\_

Main Street National Register District Willimantic, Connecticut View northwest at Old Post Office and Windham Town Hall. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View northwest at Windham Town Hall. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.




- Main Street National Register District Willimantic, Connecticut
- View looking south at west side of North Street. Photo by Margo Webber, July, 1980 Negative filed at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View southeast at Windham and Smithville Co. Store. Photo by Margo Webber, July, 1980.

Negative on file at Connecticut Historical Commission.



Main Street National Register District Willimantic, Connecticut View looking north at facade of Windham and Smithville Co. Rowhouse. -Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Non-conforming structure Photo #16 Main Street National Register District -Willimantic, Connecticut View of Beller Block and YMCA on south side of Main Street. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.





Main Street National Register District Willimantic, Connecticut View northeast at library and #893 Main Street on north side of Main Street. Photo by Margo Webber, July, 1980 Negative on file at Connecticut Historical Commission.



Non-conforming structure Photo #18 Main Street National Register District Willimantic, Connecticut View south at #980 Main Street. Photo by Margo Webber, July, 1980. Negative on file at Connecticut Historical Commission.