UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

	**							÷	-			-	÷2,										÷	 						•••				•••	÷							,
ø	Э	1	87	1	Ø,	Ċ.	8	З	X.		Ľ.	3	Ċ,	61	iŝ		٩.	8																		8						ž
	-	8		ŵ					68	23		-0	2	8.6			ø																		88				88			
																																								88		
		200			88	20									8				8																							
				82	20				1								8							8	23	83		88	83													
		88						~							12	87	÷	ŧ.		6		88	2			•	Υ,	88									88		33			
3	-3	0	E	ÉÅ	1	Ξ.	f				8		8	۰.	1	81	Б	8		2	1	8	93	8.3	ά.	9	1					88					8	22	S.,			
2				۰.		**		3					2	. Č.	٨.						8		ad the	÷.			20	23									20		88	88		
8		88							86								8					80									83		82	88			8	20	8	-	88	
									8			88														82	88	22						88		88	R.	8	÷.		20	
														88										83				Ø,			\$		×.	2		20			1	1	1	
X		Ť	÷.	8	É.	2	8		÷.	ö	2	1	e,					8				88			0	t ve		٠.	8		<u>_</u>				83	8	8	8				

AL-IV-A-113

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

1 NAME

HISTORIC First Baptist Church

AND/OR COMMON

2 LOCATION

STREET & NUMBER	212 Bedford Stre	eet	NOT FOR PUBLICATION	
CITY, TOWN	Cumberland		congressional dist Sixth	RICT
STATE	Maryland	CODE 24	county Allegany	code 001

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESI	ENTUSE
DISTRICT	PUBLIC	X_OCCUPIED	AGRICULTURE	MUSEUM
XBUILDING(S)	X_PRIVATE	UNOCCUPIED	COMMERCIAL	PARK
STRUCTURE	вотн	WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDENCE
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	X.RELIGIOUS
OBJECT	IN PROCESS	XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES: UNRESTRICTED	_INDUSTRIAL	TRANSPORTATION
		NO	MILITARY	OTHER:

4 OWNER OF PROPERTY

NAME First Baptist Church c/o Russell L. Livengood, Chairman of Deacons

STREET & NUMBER	• * * *		
212 Bedford	Street		
CITY, TOWN		STATE	
Cumberland	VICINITY OF	Marvland	21502
5 LOCATION OF	LEGAL DESCRIPTION		
COURTHOUSE, REGISTRY OF DEEDS,ETC.	Allegany County Courthouse		
STREET & NUMBER	30 Washington Street		
CITY, TOWN		STATE	
	Cumberland	Maryland	21502
6 REPRESENTAT	TION IN EXISTING SURVEY	S	
TITLE			
DATE			
DATE	FEDERAL	STATECOUNTYL	DCAL
DEPOSITORY FOR			
SURVEY RECORDS			
CITY, TOWN		STATE	



CO	NDITION	CHECK ONE	CHECK (DNE
EXCELLENT GOOD XFAIR	DETERIORATED RUINS UNEXPOSED	UNALTERED X_altered	<u>X</u> original moved	SITE DATE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The First Baptist Church is located at 212 Bedford Street in Cumberland, Maryland. It is a T-shaped brick structure of l¹/₂stories. The 1917 east (front) facade is of white glazed, all stretcher brickwork; this also extends back one bay on the north and south facades. The rest of the building, constructed in 1849, is of red brick laid in common bond with random variations; this has been repointed. The original part has two high brick belt courses on each facade and a single low one on the side facades (although the north side is covered by additions). On the east facade only the low belt course exists, where it is executed in stone.

The church sits on a low foundation of rock-faced, coursed ashlar on the north and south and uncoursed rubble on the west (rear). It has a plain water table. The gable end of the church faces front. The gable roof is covered with sheets of asphalt. A replacement box cornice surrounds the 1849 structure. Two interior brick chimneys are located in the west end. One is original with corbeled cap; the other is a replacement.

The principal (east) facade is a three-part composition divided vertically into nave (on the south) and stair tower (on the north); the latter is divided horizontally to separate a basement from the tower above. This distinction is deliberately obscured on the nave by containing the windows of those two floors within one large opening in the The stair tower wall is brought forward on this facade (in plan the tower comes wall. forward on the east and north elevations), resulting in three exposed corners on this elevation. Each corner is similarly buttressed on its two sides with a three-part buttress, narrowing and set back from bottom to top. The set backs are at the first floor and choir levels and are marked by stone shoulders or weatherings. The top and bottom segments have inset round-arched panels. The choir level segments are terminated by molded concrete copings. The two buttresses which flank the stair tower have an additional section with an applied pediment and another concrete coping (these are not set back). The southernmost buttress is shorter than those on the facade. Its terminal coping turns to rake against the south wall of the nave. The top copings of the facade buttresses are continuous with the copings of their respective roofs.

The nave portion of the facade, wider than the stair tower, contains between the buttresses a large gothic tracery window set in a brick arch topped by a stone arch above the springing. The floor of the auditorium (first floor) is marked by a band of three large quatrefoil panels between the upper and lower windows. The wall above the arch is set with nine round-arched panels in a blind arcade which rises directly out of the window arch and follows the raking of the gable. Above this is the coping of the gable which breaks vertically near the point and then squares off to form a blunt peak.

The wall of the stair tower is similarly composed above the basement, without the quatrefoil or arched panels. The roof coping forms a simple low gable.

The basement contains the main entrance, set in an arch like the window arches, with a blind arcade of five arched panels above. The entrance has a double door of two sixpaneled leaves in a wooden frame. The two parts of the stair tower are separated by a heavy window ledge, continuous with and set back from the weatherings of the buttresses. FHR-8-300A (11/78) UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR HCRS USE	ONLY		
RECEIVED	2 5 1980		
RECEIVED JUN DATE ENTERED.	Ŵ	₩,10	1980

	The First Baptis	st Church			
	Allegany County				
CONTINUATION SHEET	Maryland	ITEM NUMBER	7	PAGE	1

(DESCRIPTION CONTINUED)

At basement level the south facade has a recessed frame coal chute at the rear; this is now sealed. There are three basement windows with 4/4 light sash containing translucer glass, wooden trim, and stone sills. A low brick belt course serves as lintel for these windows. The rear entrance on this facade is recessed and has a flat brick arch, wooden trim, and a two-panel door with one light of translucent glass. The entrance near the front has a four-panel door.

On the first floor of this facade are three round-arched stained glass windows with two tall panels and a fixed half-round one above. These have stone sills, plain wooden trim, and brick arches. The six illustrations in these windows are different from those on the north facade. There is also one small rectangular stained glass window with wooden trim and brick sill.

The west end has two basement windows of thick translucent glass, one with 56 lights and one with 69 and two larger movable panes; both have flat brick arches and brick sills. The door in the north bay is a replacement and the transom is boarded over. The first story has three window openings; the north one has been bricked in but was identical to the south one, which is like the windows on the south. The central stained glass window is shorter and wider and has a gently pointed brick arch and a brick sill. It is an alteration as the brickwork around it is disturbed.

The north facade has one closed up basement window with brick arch. At first story level are three stained glass windows of similar form to those on the south but different parts fixed and movable; they have brick arches, stone sills, and wooden trim. This facade also has a small rectangular window like that on the south; both swing in.

Two small additions are built against the north side of the church; they do not disturb the appearance of the church.

On the interior of the church the stairs are located in the northeast corner. At the basement level the main entrance opens into a hall facing the stair that leads to the main worship area on the next floor. The basement is divided into a number of rooms with walls and folding partitions.

The main floor is divided into a nave in the center, a Sunday School area divided off with a folding wood partition in the east end, and organ, choir loft, and two small rooms at the west end. The chancel area has an elliptical platform raised two steps above the nave and divided from it by three pointed-arched openings with wooden pillars. Behind these arched openings are the choir and organ lofts. The choir loft is slightly raised above the chancel floor. A trap door in the chancel floor covers a baptismal pool. The two rooms next to the chancel are preparation rooms. A closed stair leads from them to the basement.

SEE CONTINUATION SHEET #2.

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

			discontración de alteration
FOR HCRS	HEE ANN V		
TOR TRAD	OSL UNLI		
	_	00	
OF OF MED			
	JUN 2 5 19		
		ANTHI	
DATE ENTE	PEN	INDA	M. M
			10 1980

The First Baptist	Church				
Allegany County					
CONTINUATION SHEET Marya Ind	ITEM NUMBER	7	PAGE	2	-

(DESCRIPTION CONTINUED)

The nave ceiling is a flat plaster one with curved corners. The chancel ceiling is a four-arched cross yault. Four wrought iron lamps with stained glass panels hang from chains in the nave.

The open well stair that leads from the basement to the balcony at the east end of the church has seven landings and six and a half flights. Made of walnut, it is not decorated except for rectangular pendants. There is wainscoting on the walls of the stair.

Woodwork around the doors and windows is plain. The folding partition in the nave has eight seven-panel doors. The double doors leading into the nave are identical to these. The choir rail molding extends around the nave. A walnut paneled railing surround the organ and choir lofts. The face of the balcony is paneled. Architrave trim extends around the top of the walls near the ceiling.

The pipe organ was bought and installed in 1921 and was recently renovated.

8 SIGNIFICANCE

PERIOD	A	REAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	
PREHISTORIC 1400-1499 1500-1599 1600-1699	ARCHEOLOGY-PREHISTORIC ARCHEOLOGY-HISTORIC AGRICULTURE XARCHITECTURE	COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION	LANDSCAPE ARCHITECTURE LAW LITERATURE MILITARY	X_RELIGION SCIENCE SCULPTURE SOCIAL/HUMANITARIAN
1700-1799 X_1800-1899 1900-	ART COMMERCE COMMUNICATIONS	ENGINEERING EXPLORATION/SETTLEMENT INDUSTRY INVENTION	MUSIC PHILOSOPHY POLITICS/GOVERNMENT	THEATER TRANSPORTATION OTHER (SPECIFY)

SPECIFIC DATES 1849, 1917

STATEMENT OF SIGNIFICANCE

BUILDER/ARCHITECT

SIGNIFICANCE With its very stylishly contrived facade, the First Baptist Church is a distinctive structure in the architecture of Cumberland. The original 1849 building has a nave of the church on the second floor, a characteristic common to Baptist and Methodist churches of the second half of the 19th century. The interior detail is also common to that period. The congregation has had ups and downs throughout its history, with the congregation fluctuating from almost nonexistent to very large. The combination of large typical 19th century structure with up-to-date facade of modern materials is illustrative of the cycles in the congregation's history.

<u>HISTORY AND SUPPORT</u> The history of the First Baptist Church in Cumberland has been one of fluctuating fortune. During the last century, this church had its setbacks, but always managed to overcome misfortune to prosper. The first record of Baptist meetings in this area was in the 1840s, when a handful of persons met in a hall above a fire station. The first missionary to come to these Baptists was Rev. Benjamin Gifffith, D.D., who later became the first pastor of the church.

By 1849 Rev. Griffith had gathered enough Baptists into his congregation to build a church, which was dedicated in November 1849.² This original brick building was larger than it need be, according to Lowdermilk, who states that the "seating capacity" was much larger than the number of the congregation.

During the Civil War Cumberland was used to house Union wounded. "Halls, churches, and warehouses" were temporary hospitals where local physicians cared for the wounded soldiers.⁴ The soldiers hospitalized here numbered 500 in December of 1861 and 1,200 in the spring of 1862. Even after the large Clarysville hospital was opened, fifteen different locations in Cumberland housed wounded.⁵ Thomas and Williams state that the First Baptist Church was one of these.⁶

Shortly after the war, for some unknown reason, the council of the church met and decided to disband the organization. It was reorganized in 1871. According to local tradition, the congregation was forced to pay for their land a second time due to an error in the first title. In 1878 Lowdermilk reports of a congregation of seventy persons.

In 1913 the Reverend H.F. Loomis arrived to fill a one year vacancy at the pulpit to find that much of the congregation had drifted away. Through his strenuous efforts he rebuilt the congregation to 300 by 1923. At a cost of \$15,000.00 a new front facade to the church was erected and dedicated in January of 1917.⁸ Included in this facade are architectural components that join to create a balanced visual impact. The tracery windows are the largest in the Cumberland area. The soaring height of these windows

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Courthouse, Cumberland, Maryland.

Lowdermilk, Will H. <u>History of Cumberland</u>. (Reprint of 1878 edition).

Baltimore: Regional Publishing Co., 1971.

ACREAGE NOT VERIFIED

UTM NOT VERIFIED

SEE CONTINUATION SHEET #4.

10GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 54' x 155' **UTM REFERENCES**

A 1 17 6 9 12 0 15 10 5 14 9 11 7 4 10 ZONE EASTING NORTHING	
VERBAL BOUNDARY DESCRIPTION	

VERBAL BOUNDARY DESCRIPTION

Reference Allegany County Deeds 4/259 and 4/398.

STATE		CODE
STATE	CODE COUNTY	CODE
STATE	CODE COUNTY	CODE
FORM PREPARE	D BY	
NAME/TITLE William Pra	tt and Dave Dorsey, Surveyors	
	unty Historic Sites Survey	date 10/4/77
	ce Building, Pershing Street	^{теlерноме} (301)777-5967
		STATE
	C PRESERVATION OFFICER	Maryland 21502 CERTIFICATION
Cumberland STATE HISTORIC THE EVA NATIONAL	LUATED SIGNIFICANCE OF THIS PROPERTY V	Maryland 21502 CERTIFICATION VITHIN THE STATE IS: LOCAL X
Cumberland STATE HISTORIC THE EVA NATIONAL s the designated State Historic	LUATED SIGNIFICANCE OF THIS PROPERTY V STATE Preservation Officer for the National Historic Pre or inclusion in the National Register and certify	Maryland 21502 CERTIFICATION WITHIN THE STATE IS: LOCAL X iservation Act of 1966 (Public Law 89-665), 1
Cumberland STATE HISTORIC THE EVA NATIONAL s the designated State Historic ereby nominate this property for	LUATED SIGNIFICANCE OF THIS PROPERTY V STATE Preservation Officer for the National Historic Pre or inclusion in the National Register and certify by the National Park Service.	Maryland 21502 CERTIFICATION WITHIN THE STATE IS: LOCAL X iservation Act of 1966 (Public Law 89-665), 1
Cumberland STATE HISTORIC THE EVA NATIONAL s the designated State Historic ereby nominate thistoric for iteria and procedures set forth STATE HISTORIC PRESERVATION C	LUATED SIGNIFICANCE OF THIS PROPERTY V STATE Preservation Officer for the National Historic Pre or inclusion in the National Register and certify by the National Park Service.	Maryland 21502 CERTIFICATION WITHIN THE STATE IS: LOCAL X eservation Act of 1966 (Public Law 89-665), 1 that it has been evaluated according to the
Cumberland STATE HISTORIC THE EVA NATIONAL s the designated State Historic ereby nominate this property for iteria and procedures set forth STATE HISTORIC PRESERVATION C TITLE STATE HISTOC NPS USE ONLY	LUATED SIGNIFICANCE OF THIS PROPERTY V STATE Preservation Officer for the National Historic Pre or inclusion in the National Register and certify by the National Park Service.	Maryland 21502 CERTIFICATION WITHIN THE STATE IS: LOCAL $\frac{\chi}{}$ eservation Act of 1966 (Public Law 89-665), 1 that it has been evaluated according to the <u>6-16-80</u> DATE

GPO 892-453

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR HCRS USE ON	_Y		
RECEIVED HIN 2 5	1980		
RECEIVED JUN 2 5 DATE ENTERED	NI.	01. %	1980

	The First Baptist	t Church			
	Allegany County				
CONTINUATION SHEET	Maryland	ITEM NUMBER	8	PAGE	3

(SIGNIFICANCE CONTINUED)

is countered by the molded concrete trim highlighting the buttresses and entrance. The arcaded effect of rows of pointed brick arches above the entrance and the larger window, combined with the recessed position of the window and entrance, present a contrast giving greater depth to the east facade. These Gothic Revival features and the asymmetrical design of the facade are reminiscent of the cultural awareness of the past members of the church.

Additional misfortunes include the murder of a missionary to China during disturbance there, and the loss of the church's history, including the names of many of the pastors, when the records were moved to Baltimore "for historical purposes."⁹

Today the church membership is still active and services continue despite the lack of a minister. It is the determination of a congregation with a history of struggle against misforuune that keeps this church a monument to the courage of the Baptist people of Cumberland. The Gothic facade of this building symbolizes the strength of these people "buttressed" by thier faith in God.

- Will H. Lowdermilk, <u>History of Cumberland</u> (Baltimore: Regional Publishing Co., 1971), p. 464. Reprint of the 1878 edition.
- ² Lowdermilk, p. 465.
- ³ Lowdermilk, p. 464.
- ⁴ Harry Stegmaier, Jr., <u>Allegany County-A History</u> (Parsons, W.Va.: McClain Printing Co., 1976), p. 187.
- ⁵ Ibid.
- ⁶ James W. Thomas and T.J.C. Williams, <u>History of Allegany County</u>, <u>Maryland</u>. (Philadelphia: L.R. Titsworth and Co., 1923), p. 476.
- ⁷ Lowdermilk, p. 465.
- ⁸ Thomas and Williams, p. 477.
- ⁹ Lowdermilk, pp.465-6.

FHR-8-300A (11/78) UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

FOR HCRS USE ONLY	
FOR HCRS USE ONLY RECEIVED 10/2/8	10
DATE ENTERED	NOV 1.0 1980

First Bap	tist Church			
Allegany	County			
CONTINUATION SHEET Maryland	ITEM NUMBER	8	PAGE	

(SIGNIFICANCE, continued) REVISIONS 9/29/80 Ronald Andrews

The significance of the First Baptist Church on Bedford Street in Cumberland, Allegany County, Maryland is derived from the facade that was added in 1917 to the existing church structure erected in 1849. Executed in a modest interpretation of the Late Gothic Revival style, the facade embodies the distinctive characteristics of a type of architecture that, while popular in the United States in the first half of the present century, was not commonly used in Cumberland. The dominant features which characterize the First Baptist Church facade are a smooth, quiet perpendicular design executed in masonry. The position of this structure in the architectural fabric of Cumberland is heightened by its location on a hill from which it is visible from various locations in the center of the city. FHR-8-300A (11/78) UNITED STATES DEPARTMENT OF THE INTERIOR HERITAGE CONSERVATION AND RECREATION SERVICE

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



The First Baptist Church Allegany County CONTINUATION SHEET Maryland ITEM NUMBER 9 PAGE 4.

(MAJOR BIBLIOGRAPHICAL REFERENCES CONTINUED)

Thomas, James W., & Williams, T.J.C. <u>History of Allegany County, Maryland</u>. Philadelphia: L.R. Titsworth and Co., 1923.

Stegmaier, Harry, Jr. <u>Allegany County-A History</u>. Parsons, W.Va.: McClain Printing Co., 1976.

