

Missouri Valley Grocery Company building (#2), 101 E. Main St. (looking SE at NW facade) Mandan Commercial District, N.D.

Norene Roberts -- for Historical Research, Inc. 7/1983 Filed: State Historical Society of North Dakota

Roll 7 Frame 6



NE corner of First Street NW and First Avenue NW; at corner is Kennelly Building (#34) and left is Speilman, Kelsch, and Wirtz Building. (#32)

Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Roll 10 Frame 20

Photo 2 of 24



400 Block of W. Main, showing SW facades from Vinton Block (foreground) to Lewis and Clark Hotel (background) Mandan Commercial District, Mandan, North Dakota 58554

Filed: State Historical Society of North Dakota

Roll 9 Frame 2

J. Sluss for HRI 8/ 1983



```
300 Block of W. Main St. showing SW facades (All Bldg. in foregound) north side of street

Mandan Commercial District, Mandan, N.D. 58554
```

7 Class for Market 1 December 7 9 /1002

J. Sluss for Historical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Roll 9 Frame 4 Photo 4



Looking NW; NW corner of West Main and First Avenue NW; #17 at corner; #18a and b at left.

Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505


Roll 9 Frame 5
Photo 5 of 24



North side of Main St., in 100 block looking north (State Bank of Morton Co., left, to First National Bank) Mandan Commercial District, N.D.

j. Sluss, for Historical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Roll 9 Frame 6



North side of Main Street E., 100 Block looking NW Mandan Commercial District, N.D.

J. Sluss, for Historical Research, Inc. Filed: State Historical Society of North Dakota

Roll 9 Frame 8



N. P. Depot (left) and Cafe (right) in NP Park, south side of Main St. W. looking SE Mandan Commercial District, N. D.

Jacqueline Sluss for Historical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Photo 8

Roll 9 Frame 16



South side of Main St. W. looking SW at (right) #6, N. P. Freight house and (left) #s 58 and 59, metal maintenance buildings, across the NP Park. Mandan Commercial District, N.D.

Jacqueline Sluss, for Historical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Roll 9 Frame 17



Hughes Apartments (#35), looking West at NW facade at corner of First Street and First Avenue NW.

Photo credit: Jacqueline Sluss for HRI

Photo Date: August, 1983 Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Roll 11 Frame 2a

Photo 10 of 24



West side of Collins Ave. between 1st. St. and Main N.W. Commercial District of Mandan, N.D.

Jacqueline Sluss for Historical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Roll 11 Frame 3a



Mandan Police and Fire Station (#30), 108-10 Collins Ave. Commercial District of Mandan, N.D.

Jacqueline Sluss, for Historical Research, Inc. 8/1983

Filed: State Historical Society of North Dakota

Roll 8 Frame 8a



Intersection of First St. N.W. (left) and Second Ave. N.W. with (#36) Engleter Building in center looking southeast at south side of First St. and east side of Second Ave. N.W.

Commercial District of Mandan, N.D.

Jacqueline Sluss for Historical Research, Inc. 8/1983
Filed: State Historical Society of North Dakota


Roll 10 Frame 2



Mandan Federal Building (#29), 108 First St. N.W. looking NE at SW facade (the white building in the background (right) is out of the district boundaries. Commercial District of Mandan, N.D.

Jacqueline Sluss for Hisotrical Research, Inc. 8/1983 Filed: State Historical Society of North Dakota

Roll 10 Frame 5



Teddy Roosevelt Statue (#6)

Photo credit: Jacqueline Sluss for HRI Photo Date: August, 1983

Location of negative: State Historical Society of North Dakota North Dakota Heritage Center

Bismarck, ND 58505

Roll 5 Frame 15

Photo 15 of 24



216-218 West Main (#19a and b) South facade. Photo credit: Jacqueline Sluss for HRI Photo Date: August, 1983 Location of negative: State Historical Society of North Dakota North Dakota Heritage Center Bismarck, ND 58505

Roll 2 Frame 6

Photo 16 of 24



104 Second Avenue NW (#20a) front facade faces West.

Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Photo 17 of 24

Roll 6 Frame 11



103 East Main (#38) North and West facades.

Frame 6


Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center

Bismarck, ND 58505

Dhata 10 af 2/

Ro11 7

Photo 18 of 24




210-12 West Main (#47) South facade.

Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Photo 19 of 24

Roll 2 Frame 3a



214 West Main (#48) South facade.

Photo credit: Jacqueline Sluss for HRI


Photo Date: August, 1983 Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center

Bismarck, ND 58505

Photo 20 of 24

Roll 2 Frame 5



107 ½ First Avenue NW (#53)

Photo credit: Jacqueline Sluss for HRI


Photo Date: August, 1983

Location of negative: State Historical Society of North Dakota North Dakota Heritage Center

Bismarck, ND 58505

Ro11 4 Frame 19

Photo 21 of 24



106 Second Avenue NW (#55) front facade faces West.

Photo credit: Jacqueline Sluss for HRI Photo Date: August, 1983

Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center Bismarck, ND 58505

Roll 6 Frame 10

Photo 22 of 24



106 Second Avenue NW (#55) front facade faces West.

Photo credit: Jacqueline Sluss for HRI
Photo Date: August, 1983
Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Photo 23 of 24

Roll 6 Frame 9



220-222 West Main (#20b) South facade.

Photo credit: Jacqueline Sluss for HRI Photo Date: August, 1983

Location of negative: State Historical Society of North Dakota

North Dakota Heritage Center Bismarck, ND 58505

Roll 2 Frame 7

Photo 24 of 24