



Shady Side (Clifton and James Keith Thomson House), near Lexington, Fayette County, Ky. Gloria Mills, June 1976, Kentucky Heritage Commission, Frankfort.

Photo 1. View from the northwest; showing main facade from entrance gates on U. S. 68.

JUN 28 1976



Shady Side (Clifton and James Keith Thomson House), near Lexington, Fayette County, Ky. Gloria Mills, June 1976, Kentucky Heritage Commission, Frankfort.

Photo 2. View from the northwest showing the facade of the 1838 addition.

NOV 7 1976

JUN 28 1976



Shady Side (Clifton and James
Keith Thomson House), near
Lexington, Fayette County, Ky.
Gloria Mills, June 1976, Kentucky
Heritage Commission, Frankfort.

Photo 3. View from the **Northeast**
showing the rear of the Greek
Revival block on the right and the
earlier brick section on the left.

NOV 7 1976

JUN 28 1976



Shady Side (Clifton and James
Keith Thomson House), near
Lexington, Fayette County, Ky.
Gloria Mills, June 1976, Kentucky

Heritage Commission, Frankfort.
Photo 4. View from the southeast
showing the original brick section and
the later porch and wing at left.

NOV 7

1976

JUN 28 1976



Shady Side (Clifton and James Keith Thomson House), near Lexington, Fayette County, Kentucky.

Gloria Mills, June 1976, Kentucky Heritage Commission, Frankfort.

Photo 5. View from the east showing frame addition to early brick ell and later one-story wing in foreground.

NOV 7 1976

JUN 28 1976



Shady Side (Clifton and James
Keith Thomson House), near
Lexington, Fayette County, Ky.
Gloria Mills, June 1976, Kentucky
Heritage Commission, Frankfort.

Photo 6. Interior photo of newel
post of the spiral staircase in
Greek Revival wing.

NOV 7 1976

JUN 28 1976