



1

NATHANIEL MONTGOMERY HOUSE
178 High Street
Pawtucket, RI

Photographer: Richard E. Greenwood

Date: June, 1983

Negative on file at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View: Front (east) and side (south) elevations.

Photo #1

178



2
NATHANIEL MONTGOMERY HOUSE
178 High Street
Pawtucket, RI

Photographer: Richard E. Greenwood

Date: June, 1983

Negative on file at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View: Detail: front doorway.

Photo #2



3

NATHANIEL MONTGOMERY HOUSE
178 High Street
Pawtucket, RI

Photographer: Richard E. Greenwood
Date: June, 1983
Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View: Rear((west) and side (south) elevations of
house and ell.

Photo #3




4,
NATHANIEL MONTGOMERY HOUSE
178 High Street
Pawtucket, RI

Photographer: Richard E. Greenwood
Date: June, 1983
Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View: New mantel, northwest room, second floor.
(Same type mantel on all rear fireplaces).

Photo #4



5
NATHANIEL MONTGOMERY HOUSE
178 High Street
Pawtucket, RI

Photographer: Richard E. Greenwood

Date: June, 1983

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View: Mantel, northeast parlor, second floor
(nineteenth century mantel salvaged from
another R.I. house).

(Photo #5)