MAINE Historic Preservation Commission

HISTORIC RESOURCES INVENTORY

UTM:19 A 402690/488740	В	
C	D	

IDENTI	FICATION		
1.	Common name:		
2.	Historic name:Bergin_Block		
3.	Street or rural address: 330 Lisbon Stre	eet.	
	City Lewiston	Zip <u>04240</u>	CountyAndroscoggin
4.	Parcel number: Map 18D Lot 330		· ·
5.	Present Owner: <u>Julius Wise</u>		Address: 330 Lisbon Street

City Lewiston Zip 04240 Ownership is: Public Private X

DESCRIPTION

- 7a. Architectural style: Neo-Classical
- 7b. Briefly describe the site or structure and describe any major alterations from its original condition:

6. Present Use: _____Original use: Commercial

Standing four stories high at the corner of Lisbon and Spruce Streets, the Bergin Block is constructed of brick with stone and metal trim. The two principal elevations (west and south) have yellow brick facing and square headed windows with one over one double hung sash. The flat arched lintels, pilasters and metal cornice supported on brackets are neo-classical features. The cornice has a large round arched pediment with scroll-shaped cresting. The name and date of the building is in relief in the pediment. The first story is, like the upper stories, unaltered. A shopfront with cast iron pilasters and wooden and glass display windows and a doorway to the upper floors extends around the elevations. The interior of the store contains original metal ceiling, tile floor and hardware.

Attach Photo(s) Here	8.	Construction date: Estimated Factual
	9.	Architect unknown
	10.	Builder
	11.	Approx. property size (in feet) Frontage Depth or approx. acreage $\frac{1}{4}$ acre
	12.	Date(s) of enclosed photograph(s) 4/85

13.	Condition: ExcellentGood _X Fair Deteriorat	ed No longer in existence
14.	Alterations:	
15.	Surroundings: (Check more than one if necessary) Open land Residential Industrial _X Commercial _X Other:	
16.	Threats to site: None known X Private development Public Works project Other:	Zoning Vandalism
17.	Is the structure: On its original site? X Moved?	Unknown?
18.	Related features:	
SIGN 19.	IFICANCE Briefly state historical and/or architectural importance (include	e dates, events, and persons associated with the site.)
	character and distinctive design, once	as the site of the Bergin Tavern, one of
		Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):
20.	Main theme of the historic resource: (If more than one is checked, number in order of importance.)	NORTH
	ArchitectureX Arts & LeisureX Economic/IndustrialExploration/Settlement	
	Government Military	Ц
	Religion Social/Education Other (describe)	
21.	Sources (List books, documents, surveys, personal interviews and their dates).	
	Interview with owner, August, 1984	
22.	Date form prepared 12/85 By (name) Roger Reed	
	Organization MHPC	
	Address:Zip	
	Phone:	

HISTORIC RESOURCES INVENTORY FORM

Lewiston Historical Commission - Dingley Building 36 Oak Street, Lewiston, Maine 04240

IDEN	<u> PIFICATION</u>			
1.]	Building Name(s):		_Historic_	Bergin Block
	Principal Street Address:			
	Other Street Address: Sp			
4.]	Present Owner's Name:		_5. Owners	ship: publicprivate_X
6.	Owner's Address:			
	Original Owner:			
	Use: original commercial/		sibility to	public:
	present same	exter	ior visible	e from public road X
		inter: acces	ior accessi s to stree	ible: (explain) yes, public tlevel store.
Surve	eyor's Name: Leslie Chat	tterton	_Date: Aug	ust 1984
	ess: Cornell University,			
Posi	tion: volunteer_ other,(explain)_	professional consul	tant	intern <u>xx</u>
	e de la companya del companya de la companya del companya de la co			
DESCR	RIPTION			
10. N	Number of Stories 4	Bays_4 Attic	Baseme	ent_X
11. 5	Structural wood frame,	interlocking joints:	wood fr	mame, light members:
S	System: masonry load	bearing: X metal,	(explain):_	
12. I	Photo	13.	Map	
	Aurence - L			

DESC	RIPTION	
14.	_	Roof: asphalt shingle wood shingle slate concrete composition x metal tile other Walls: wood stone cast iron brick x stucco other orange brick cladding Foundation: brick
15.		excellent good X fair poor deteriorated explain fair or poor condition metal cornice is corroding
16.	Integrity:	original site: yes X no if moved, when list major alterations, dates and designers (if known):
	No evid	ence of major alteration.
17.	Threats to Building:	none x zoning roads developers deterioration other
18.	Related Outbuilding	none
19.	Surrounding	densely built-up x commercial x scattered buildings

20. Interrelationship of Buildings and Surroundings:

The large size and elaborate cornice piece of this building are well suited to the corner location at the intersection of Spruce and Lisbon Streets. Further south, a modern bakery facility is followed by a streetscape of diverse buildings reflecting the mixed use character of the area. This is the last strong element of relatively continuous buildings depicting the commercial character on the east side of Lisbon Street.

DESCRIPTION

21. Other Notable Features of Building and Site, include Interior Features if known:

Classical style features of this sizeable, flat-roofed, light orange, brick clad block include a deep metal cornice with projecting arched pediment supported on oversized metal consoles enriched with relief acanthus foliage. Relief lettering on the tympanum depicts the name "Bergin Block, 1913." Surmounting and surrounding the pediment, the roofline is embellished with large molded rinceaus. Strip pilasters with granite bases and corbeled capitals, rise from above display windows to a brick corbel table over the fourth story windows. The regular fenestration pattern includes rectangular window openings with rock-faced granite sills and reticulated brick, flared lintels. Spandrel panels between floor levels are embellished with patterned brickwork.

The east iron storefront retains many original details including:

o Square columns with paneled shafts supporting a substantial lintel with projecting cornice that separates the storefront from the upper stories.

-CONTINUED ON REVERSE SIDE-

S	T	c	N	T	F	T	C	Δ	N	C	F
2	-	Y	7.4	_	T.	-	·	•	41	·	ٺ

22.	Date of Init	ial Construction:_	1913		
23.	Architect: _	unknown		_Address:	
24.	Builder:	unknown .		_Address:	

25. Historical and Architectural Importance:

This structure contributes to the architectural depiction of Lisbon Street's evolving commercial and residential character. Its facade exhibits a notable similarity to the nearby LaPlante building, (319 Lisbon Street). Common features include the light orange cladding brick, panels of patterned brickwork between floor levels, and the large, ornate metal cornice. These elements suggest the possibility of a common builder, contractor or architect.

The building originally accommodated the Bergin's tavern, reputed to be the finest north of Boston. It is attributed with the distinction of being the first tavern in Maine with the capability of pumping beer up to the streetlevel bar from barrels located in the cellar.

26. Sources:

Tax assessment records, Assessor's Office, City Bldg., Lewiston.

Deed research, Registry Department, Androscoggin County Bldg., Auburn.

Interview with present owner, Julius Wise, August 1984.

21. Notable Features.....cont'd

- o original storefront windows with wood sash and division bars, wood panels below and toplights above;
- o brick strip pilasters at the south facade streetlevel with prominent corbeled capitals supporting the lintel;
- o a recessed entry, elevated on a granite base, featuring a wood paneled ceiling and mosaic tile floor and original door with brass hardware.

The interior retains an original metal ceiling, with relief embellishment and mosaic-tiled floor.