



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

North Facing Front  
of House

1 of 21



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine  
County

OREGON

Photographer - S. Guggenheim

Date 8/1/89

Northwest corner  
of House

2 of 21



Voorhies, Amos Earle House  
421 N.W. B St.  
Grants Pass, Josephine County  
OREGON

Photographer - S. Cugenheim

Date 8/1/89

Western exposure  
of house

3 of 21



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine  
County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Close up North  
Facing Front of  
House

4 of 21





Voorhies, Amos Earle House  
421 N.W. 'B' St.  
Grants Pass, Josephine County  
OREGON

Photographer - S. Gugenheim  
Date 8/1/59

Detail of sunroom  
windows, East-facing  
side of House

5 of 21



Voorhies, Amos Earle House  
421 N.W. 'B' St.  
Grants Pass, Josephine County  
OREGON

Photographer - S. Gugenheim  
Date 8/1/89

Back of House

6 of 21



Voorhies, Amos Earle House  
421 N.W. 'B' St.  
Grants Pass, Josephine  
County

OREGON

Photographer - S. Gugenheim  
Date 8/1/89

Northwest corner  
of Property -  
170 foot Redwood  
in Back Yard

7 of 21



Voorhies, Amos Ewle House

421 N.W. B St.

Grants Pass, Josephine County  
OREGON

Photographer - S. Gugenheim

Date 8/1/89

Redwood tree with

Cement pond in

Back yard

Camera facing west

8 of 21





Voorhies, Amos Earle House

421 N. W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Front Entry Hall  
and Staircase to  
2<sup>nd</sup> story

Camera facing south

9 of 21



Voorhies, Amos Eawle House  
421 N.W. 'B' St.  
Grants Pass, Josephine County  
OREGON

Photographer - S. Gugenheim  
Date 8/1/89

Dining Room from  
Entry Hall. Note  
French Doors to enclosed  
Porch and Antique  
Chandelier

10 of 21



Voorhies, Amos Earle House

421 N. W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Dining room

Camera facing S.E.

corner built in Hutch

11 of 21



Voorhies, Amos Earle House

421 N. W. 'B' St.

Grants Pass Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Entry Way Arch

From Living Room

Note: Entry way

Radiator

12 of 21





Voorhies, Amos Earle House  
421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S Gugenheim  
Date 8/1/89

Living Room showing  
Fireplace and

Antique light fixtures

Camera facing east

Note Entrance to

Sunroom in N.E. Corner  
through French Doors

13 of 21



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Living Room with

Built in Bookcase

Camera facing South



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Sun room showing

2<sup>nd</sup> Fireplaces

French Door

Camera facing south

15 of 21



Voorhies, Amos Eowle House  
421 N.W. B St.  
Grants Pass, Josephine  
County

OREGON

Photographer - S. Gugenheim  
Date 8/1/89

Sunroom showing  
windows and full  
length window seat  
Camera facing east

16 of 21





Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Enclosed Sun Porch  
on West side of  
house

Camera facing  
North

17 of 21



Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

2<sup>nd</sup> Floor

Bedroom

N.E. Corner of House

Note antique light  
fixture (ceiling)

18 of 21



Voorhies, Amos Earle House  
421 N.W. B St.  
Grants Pass, Josephine  
County  
OREGON


Photographer - S. Gugenheim  
Date 8/1/89

2<sup>nd</sup> Floor

Balcony on West  
Side of House

Camera facing  
S. S.E.

19 of 21



Voorhies, Amos Earle House  
421 N.W. 'B' St.  
Grants Pass, Josephine  
County  
OREGON

Photographer - S. Gugenheim  
Date 8/1/89

Finished Attic - 3<sup>rd</sup>


Floor

Note 1/4 circle  
windows

Camera facing East

20 of 21





Voorhies, Amos Earle House

421 N.W. B St.

Grants Pass, Josephine  
County

OREGON

Photographer - S. Gugenheim

Date 8/1/89

Basement - original  
Coal burning  
boiler

Next to oil boiler  
(new)

21 of 21