



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Main (east) facade, view southwest

1



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Rear facade, view east

2



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, attic, showing pieced-up rafter

3



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission
Hartford, CT

Interior, southwest room, view northeast



John Cady House (Babcock Tavern)


Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, front or east room, view northwest 5



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, northwest room, view southeast

6



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, chamber over kitchen, showing purlin post, view northeast ?



John Cady House (Babcock Tavern)

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, southwest chamber, showing wainscot, view northeast 8



John Cady House

Tolland, CT

B. Clouette Photo, 8/79

Negative with Connecticut Historical Commission

Hartford, CT

Interior, east chamber or ballroom, view southwest 9