JAN 2 7 1989

NATIONAL

REGISTER

.

٠.

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for *Completing National Register Forms* (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a), Type all entries.

1. Name of Property						
nistoric name	Munsell, Wi	lliam O., H	ouse			
other names/site number	N/A					
						• ···
2. Location						
treet & number	1507 S.E. A	lder			not for publica	tion
city, town	Portland	<u>,</u>	······································	<u> </u>	vicinity	
state Oregon	code OR	county	Multnomah	code (e 97214
. Classification						
Winership of Property	Cateo	ory of Property		Number of Res	ources within Prope	orty
X private		ilding(s)		Contributing	Noncontributing	•
		itrict		1	•	
public-local					buildin	<u>a</u>
public-State		-			sites	
public-Federal		ucture			structu	
	ob	ject			objects	6
				<u> </u>	Total	
lame of related multiple (Historic and Archi	property listing:				ntributing resources previously	
		rces	6	listed in the Nat	tional RegisterN	I/A
of Eastside Portla 5. State/Federal Agen						
		<u> </u>				
Signature of certifying offi	cial	1 Same De			January 2 Date	
Oreg	on State Histor	ic Preserva	tion Office			
State or Federal agency a			•			
·········			······································			
In my opinion, the prop	erty 🛄 meets 🛄 do	es not meet the	National Register	criteria. 🛄 See	continuation sheet.	
•						
Signature of commenting	or other official				Date	
State or Federal agency a	nd bureau					
				_		
. National Park Servi				·····	· · · · · · · · · · · · · · · · · · ·	
hereby, certify that this	property is:		0	_		11
entered in the National	I Register.	11 0 .	K.	Entered	in the	1dec
See continuation she	et. (Julor	upya	Entered National	Register J	18/89
determined eligible for	the National	> v				
Register. See contin						
determined not eligible						
National Register.						
Hallonal Hoyistol.		•		· · · · · · · · · · · · · · · · · · ·		
removed from the Nati	onal Basiston					
				<u> </u>		
other, (explain:)						•
	······································	<u>_</u>			Dete	Action
		\checkmark	Signature of the Ke	eper		of Action

Historic Functions (enter categories from instructions) DOMESTIC; Single Dwelling		ctions (enter categories from instructions) C; Single Dwelling
7. Description Architectural Classification	Materials (enter categories from instructions)	
(enter categories from instructions)		
	foundation	Brick
Bungalow/Craftsman	walls	
Bungalow/Craftsman Colonial Revival		Weatherboard

Describe present and historic physical appearance.

EXTERIOR DESCRIPTION

This one-and-one-half story house is situated on the southwest corner of the block, on a spacious lot elevated some three feet above the street. It is roughly square in plan, with a hip roof of composition shingles surmounted by four pedimented gable dormers facing the cardinal points. The surrounding yard is well-landscaped, with rhododendrons, fruit trees, roses and bamboo plants. A garage once stood on the southeastern corner, but only the concrete foundation remains. There is also a sunken concrete arch in the side yard, of unknown purpose.

From the front, or southern, elevation an attached porch spans the full length of the house and is covered by a shed roof with Doric columns set on square pedestals. Square balusters compose the balustrade. A rear porch to the south has similar treatment, but the eastern part has been enclosed to accommodate a bathroom addition. A full basement lies beneath. There are two chimneys, one to the central rear, and the other partially exposed on the west wall. Decorative wrought iron supports protect the chimney.

The house is clad with a number of sidings emphasizing the different levels of the house. The first level has wide shiplap with Ionic capital cornerboards. The gable faces are covered with rectangular shingles around pairs of doublehung sash windows. The pedimented gable ends are covered with shingles. The primary window type consists of one-over-one double-hung sash with architrave surrounds, as well as large tri-part picture windows on the first floor of the south elevation. On the roof of the east elevation is a small eyebrow dormer. Below it, on the first floor, is an oriel composed of a round-headed window with the upper panel of leaded glass. The western elevation has a projecting polygonal bay on the first floor, the center section of which is occupied by a transom light in the upper portion. In the center of the main elevation, to the south, lies a two-panelled door with a single square pane. Flanking the door are two large picture windows. In the lower portion of the projecting gable, a set of one-over-one double-hung sash windows have pairs of square pilasters on each side. This pedimented gable end is the only one with a window in it, in the form of an oval with four slender stylized keystones each at its cardinal directions.

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number ____7 Page ___2

Presently, this house has storm windows on all windows and doors. The owners are in the process of restoring the exterior. The house is well-maintained.

INTERIOR DESCRIPTION

The interior of the building has three rooms above and four rooms on the main floor. The focal point of the front hall is an open staircase with turned balusters which rise to the ceiling. An oriel window flanked by classical columns and molded pilasters is located on the east wall of the hall. The living and dining rooms are separated by pocket doors and each has an elaborate fireplace. The ceramic tile front of the dining room fireplace has been removed. The wainscoting, plate rail and picture molding are intact.

The upstairs rooms are arranged around a polygonal hall. Both bedrooms have ample closet space under the eaves. One closet in the rear chamber is illuminated by an eyelid dormer.

8. Statement of Significance		
Certifying official has considered the significance of this provide the significance of this provide the significance of the provide the provide the significance of the provide the p	operty in relation to other properties:	
Applicable National Register Criteria	C 🔲 D	
Criteria Considerations (Exceptions)	D DE F G	
Areas of Significance (enter categories from instructions) Architecture	Period of Significance 1902	Significant Dates
	Cultural Affiliation	
Significant Person	Architect/Builder Unknown	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The William Munsell-Henry Adams House is locally significant under criterion C as a well-preserved and fine example of an eclectic stylistic type incorporating elements of the Colonial Revival and Craftsman/Bungalow styles. Dwellings of this type were constructed throughout the southeast Portland neighborhoods from approximately 1900 through 1926; however, most of those within the subject study area were built prior to 1913. The Munsell House is one of the earliest representatives of this style and unique in terms of overall form and ornament. The date of construction is based on deed records and Sanborn Insurance maps.

Prominently sited on the northeast corner of the intersection of 15th and Alder, the house acts as an important visual element anchoring the western periphery of the potential Buckman historic district. Predominantly Colonial Revival in character, the most striking features are the oversized, pedimented dormers on each elevation. The facade dormer is accented by an oval window with keystones at the cardinal points--a characteristic decorative element found in Colonial Revival style buildings. The builder further enhanced the building by the application of a dentil course and consoles at the eaveline as well as pilaster moldings at the dormer windows.

There are fifteen buildings of this type represented in the survey of which three are considered to be potentially eligible for the National Register. United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number ____8 Page ___2

The original owner of the house was William O. Munsell who lived there for two years after its construction. Munsell was a prominent local businessman. Born in Indiana in 1870, he spent his youth in Missouri. Munsell came to Portland in 1896. Shortly thereafter he bought the lot on which the subject house was built. His first position in Portland was as a clerk with Acme Harvester. He soon rose to the position of assistant manager. In 1906 he went to work as manager for Mitchell, Lewis and Staver, an agricultural implement business located on Morrison Street, in the heart of the rapidly growing east side wholesale and warehouse district. By 1932 Munsell was president and general manager of the company and had become a prominent figure in the east side business community: vice-president of the East Side Commercial Club; president of the Rotary Club; and, longtime member of the Board of Directors of United States National Bank.

The second owners of the house were Henry B. and Ellen Adams who lived in the house from 1904 through 1931. Henry came to Portland from Ohio in 1898. Educated as an attorney, he served as deputy district attorney from 1904 to 1909. From that time to his death in 1926 he was in private practice.

9. Major Bibliographical References			
. City of Portland Building Bureau microform a	nd card files.		
. City of Portland Bureau of Planning, Portlan	d Historic Resource Inventory, 1983.		
. Multnomah County Tax Assessor records, micro	form, and card files, Portland, 1980.		
. Polk, R. L. and Co., Portland City Directori	es, 1910-1920.		
. Ticor Title Company Records, Portland, Orego			
. Oberschmidt, Nancy, current owner, Correspon			
	See continuation sheet		
Previous documentation on file (NPS):			
preliminary determination of individual listing (36 CFR 67) has been requested	Primary location of additional data:		
previously listed in the National Register	Other State agency		
previously determined eligible by the National Register	Federal agency		
designated a National Historic Landmark	× Local government		
recorded by Historic American Buildings			
Survey #	× Other		
recorded by Historic American Engineering Record #	Specify repository:		
0. Geographical Data			
Acreage of property Less than one acre Portland,	Washington-Oregon 1:62500		
JTM References 5 0 4 0 3 5 0 A 1 0 5 0 4 0 3 5 0 Zone Easting Northing	B L L L L L L L L L L L L L L L L L L L		
· International	See continuation sheet		
· · · · · · · · · · · · · · · · · · ·			
/erbal Boundary Description			
East Portland addition, Exc. E. 40' of I	ot 3 & 4, Block 323		
	See continuation sheet		
Boundary Justification	See continuation sheet		
Boundary Justification Taxlot lines	See continuation sheet		
	See continuation sheet		
Taxlot lines	See continuation sheet		
Taxlot lines Taxlot lines 1. Form Prepared By	See continuation sheet		
Taxlot lines 1. Form Prepared By mame/title K. Zisman, J. Koler, J. Morrison,	See continuation sheet A. Yost, B. Grimala		
1. Form Prepared By	See continuation sheet A. Yost, B. Grimala		

•

.

1.4

100 B NELS $\cup R$ C 60 60 60 2 7 7 2 282 322 CENTR З 6 A 6 з 47 2'5 g Ź S.E.WA: 100 (3) \$ '4' S.E. 15 th Ave. 1 Ave Ave and Por 71 7 2 7 2 2 283 300 32: Ź 60 ы S 20 6 3 ТТ ГТ 4 S.Ë. ALDER 100 100 10°E Ĺ 2 7 284 3 5 10 12 ى 11 100 50 \$3.67 S.E.MORRISON 60 1507 S.E. Alder \bigcirc Portland, OR 97214 2 285 . 19 Ac. £6. Ą 3 '9' .85 A 10' IA A.