

**HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES**

HIST-6 REV. 6/83

DEC 9 3 1983

259

3116

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM 18 6 78 7 6 0 4 6 1 2 8 8 0	
QUAD:	
DISTRICT	
<input type="checkbox"/> S <input type="checkbox"/> NR	IF NR, SPECIFY
<input type="checkbox"/> Actual	<input type="checkbox"/> Potential

IDENTIFICATION

DESCRIPTION

1. BUILDING NAME (Common)		(Historic)	
2. TOWN/CITY	VILLAGE	COUNTY	
Southington	Southington, CT 06489	Hartford	
3. STREET AND NUMBER (and/or location)			
1010 Shuttle Meadow Rd. (map 211, parcel 2) 1.92 acres			
4. OWNER(S)			
Judith P. Ross (vol.222,p.226 & vol.238,p.100) <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private			
5. USE (Present)		(Historic)	
Residential		Residential	
6. ACCESSIBILITY TO PUBLIC:	EXTERIOR VISIBLE FROM PUBLIC ROAD	INTERIOR ACCESSIBLE	IF YES, EXPLAIN
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N.A.
7. STYLE OF BUILDING			DATE OF CONSTRUCTION
Georgian			1772 A
8. MATERIAL(S) (indicate use or location when appropriate)			
<input checked="" type="checkbox"/> Clapboard	<input type="checkbox"/> Asbestos Siding	<input type="checkbox"/> Brick	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Asphalt Siding	<input type="checkbox"/> Fieldstone	
<input type="checkbox"/> Board & Batten	<input type="checkbox"/> Stucco	<input type="checkbox"/> Cobblestone	
<input type="checkbox"/> Aluminum Siding	<input type="checkbox"/> Concrete Type:	<input checked="" type="checkbox"/> Cut stone Type: brownstone foundations, front steps	
9. STRUCTURAL SYSTEM			
<input checked="" type="checkbox"/> Wood frame	<input checked="" type="checkbox"/> Post and beam	<input type="checkbox"/> balloon	
<input type="checkbox"/> Load bearing masonry		<input type="checkbox"/> Structural iron or steel	
<input type="checkbox"/> Other (Specify)			
10. ROOF (Type)			
<input checked="" type="checkbox"/> Gable	<input type="checkbox"/> Flat	<input type="checkbox"/> Mansard	<input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth
<input type="checkbox"/> Gambrel	<input type="checkbox"/> Shed	<input type="checkbox"/> Hip	<input type="checkbox"/> Round <input type="checkbox"/> Other (Specify)
(Material)			
<input checked="" type="checkbox"/> Wood Shingle	<input type="checkbox"/> Roll Asphalt	<input type="checkbox"/> Tin	<input type="checkbox"/> Slate
<input type="checkbox"/> Asphalt shingle	<input type="checkbox"/> Built up	<input type="checkbox"/> Tile	<input type="checkbox"/> Other (Specify)
11. NUMBER OF STORIES	APPROXIMATE DIMENSIONS		
2	36 x 28'		
12. CONDITION (Structural)		(Exterior)	
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated		
13. INTEGRITY (Location)		WHEN ?	(Alterations)
<input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved	N.A.	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	IF YES, EXPLAIN
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES			
<input type="checkbox"/> Barn	<input type="checkbox"/> Shed	<input type="checkbox"/> Garage	<input type="checkbox"/> Other landscape features or buildings (Specify)
<input type="checkbox"/> Carriage house	<input type="checkbox"/> Shop	<input type="checkbox"/> Garden	
15. SURROUNDING ENVIRONMENT			
<input type="checkbox"/> Open land <input type="checkbox"/> Wood-land	<input checked="" type="checkbox"/> Residential	<input type="checkbox"/> Scattered buildings visible from site	
<input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial	<input type="checkbox"/> Rural	<input checked="" type="checkbox"/> Low High building density	
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS			

The house faces north close to the street, not near other historic houses.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

In the 5-bay front elevation the central doorway is flanked by fluted pilasters that support a narrow entablature and molded cornice. Flanking the pilasters are small 4/4 windows. Other windows are 6/6 in plain frames. The twin brick chimneys are located 2-3 feet in from the ends of the ridge line. There is a rear, shed-roofed, 1-story extension that appears to be old.

18. ARCHITECT

BUILDER

19. HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

The house is architecturally significant because it is an excellent example of the Georgian style, in a fine state of preservation. The 4/4 windows flanking the front door, if original, are unusual.

SOURCES

Site visit, 1988, by Elizabeth Kopec of the Southington Historical Society

PHOTO

PHOTOGRAPHER

David Ransom

11/85

VIEW

Southeast

NEGATIVE ON FILE
X-19

COMPILED BY

NAME

David Ransom

9/85

ORGANIZATION

ADDRESS

33 Sunrise Hill Drive
West Hartford, CT 06107



20. SUBSEQUENT FIELD EVALUATIONS

1988: This house retains its original fireplaces and wide floor boards on the first floor.

21. THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other _____
- Renewal
- Private
- Deterioration
- Zoning
- Expiration _____