



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (1 of 9): Front facade,
photographer facing southwest.



ST. MARK METHODIST CHURCH


Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (2 of 9): Rear and north
sides of sanctuary, photographer facing
west.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (3 of 9): South side of sanctuary
showing playground and additions. Photo-
grapher facing northwest.



VISITORS
Join Us For



WELCOME TO ST. MARK

ST. MARK METHODIST CHURCH


Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (4 of 9): Narthex (Vestibule),
photographer facing southwest.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (5 of 9): Stained glass windows
in sanctuary. Photographer facing south.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (6 of 9): Sanctuary facing
the altar from the balcony. Photographer
facing east.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (7 of 9): Altar at East end
of sanctuary. Photographer facing east.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (8 of 9): Front entrance
of sanctuary as viewed from the altar.
Photographer facing southwest.



ST. MARK METHODIST CHURCH

Atlanta, Fulton County, Georgia

Photographer: James R. Lockhart

Negative filed: Ga. Dept. of Natural
Resources.

Date: April 1987

Description (9 of 9): Front entrance
of sanctuary (and balcony). Photographer
facing west.