


Name of Property: Hart Hall (Animal Science Building), University of California, Davis. Location: Davis, CA.

Date of Photograph: 1928. Location of Negative: Department of Special Collections, Shields Library,

Photograph by: Unknown.

Photograph Number: 1.04 13

- University of California, Davis.
- Description: View of Hart Hall from the SE, showing the principal facades.



 Name of Property: Hart Hall (Animal Science Building), University of California, Davis.
 Location: Davis, CA.

5. Location of Negative: Department of Special Collections, Shields Library, University of California, Davis.6. Description: Architect's rendering of Hart Hall from the SE, showing the

Drawing by: William Charles Hays.
 Date of Drawing: 1927 or 1928.

Photograph Number: 2.0913

principal facades.



- Name of Property: Hart Hall (Animal Science Building), University of California, Davis.
  Location: Davis, CA.
  Photograph by: Unknown.
- Date of Photograph: circa 1952.
   Location of Negative: Department of Special Collections, Shields Library,
  - University of California, Davis.

    Description: Aerial view of the U.C. Davis campus, with Hart Hall in the center and about one-third of the way down from the top of the photograph.

    Photograph Number: 3.613



of California, Davis.

2. Location: Davis, CA.

3. Photograph by: Robin Elisabeth Datel.

1. Name of Property: Hart Hall (Animal Science Building), University

- 4. Date of Photograph: July 1985.
  5. Location of Negative: Robin E. Datel, 645 C St., Davis, CA 95616.
  6. Description: View of the entrance and tower of Hart Hall, taken from
- Description: View of the entrance and tower of Hart Hall, taken from the E.
  Photograph Number: 4.0 3



- 1. Name of Photograph: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis, CA. 3. Photograph by: Robin Elisabeth Datel.
- 4. Date of Photograph: July 1985.
- 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 6. Description: View of the S wing of Hart Hall, taken from the S.
  7. Photograph Number: 5.0 € 13



- Name of Property: Hart Hall (Animal Science Building), University of California, Davis.
   Location: Davis, CA.
   Photograph by: Robin Elisabeth Datel.
- Date of Photograph: July 1985.
   Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
  6. Description: View of the rear (courtyard) side of Hart Hall, showing the tower, semi-basement, and parts of the S and E wings.
  7. Photograph Number: 6.013




- Name of Property: Hart Hall (Animal Science Building), University of California, Davis.
   Location: Davis, CA.
   Photograph by: Steve Chainey.
- Date of Photograph: July 1985.
   Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
   Description: Close-up of Hart Hall pedimented entrance and tower and
- 6. Description: Close-up of Hart Hall pedimented entrance and tower and their intersection with the E wing.

  7. Photograph Number: 7.013



- 1. Name of Property: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis, CA.
- 3. Photograph by: Steve Chainey. 4. Date of Photograph: July 1985.
- 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 6. Description: Close-up of single ram's head on frieze over entrance.
  7. Photograph Number: 8.**-7.3**



- Name of Property: Hart Hall (Animal Science Building), University of California, Davis.
   Location: Davis, CA.
   Photograph by: Steve Chainey.
- 4. Date of Photograph: July 1985.
  5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
  6. Description: Close-up of balcony, window, and cement plaster finish on S wing of Hart Hall.

7. Photograph Number: 9.0+13



- 1. Name of Property: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis, CA.
- 3. Photograph by: Steve Chainey.
- 4. Date of Photograph: July 1985.
- 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 6. Description: Close-up of brackets and ornamental plaster work.

7. Photograph Number: 10.0f 13



- Name of Property: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis. CA. Photograph by: Robin Elisabeth Datel.
  - Date of Photograph: July 1985. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
  - Description: Interior view of lobby and vestibule, taken from the W.
  - Photograph Number: 11.0613



- 1. Name of Property: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis, CA. 3. Photograph by: Steve Chainey.
- 4. Date of Photograph: July 1985. 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 6. Description: Close-up of stucco cattle heads on capitals of vestibule columns. 7. Photograph Number: 12. 5 3



- 1. Name of Property: Hart Hall (Animal Science Building), University of California, Davis. 2. Location: Davis, CA.
- 3. Photograph by: Robin Elisabeth Datel.

7. Photograph Number: 13.04 13

- 4. Date of Photograph: July 1985. 5. Location of Negative: Robin E. Datel, 645 C Street, Davis, CA 95616.
- 6. Description: Interior view of tower seminar room, taken from the NE.