

Photographer unknown. Courtesy of Mrs. James Graves, Paris, KY

FEB 8 1978

Photo 1 Front facade from south prior to restoration, 1970.

OCT 31 1977



Mary Cronan Oppel
Kentucky Heritage Commission
Frankfort, KY
July 1977

Photo 2, Main facade viewed from southwest.

OCT 3 1 1977



Mary Cronan Oppel
Kentucky Heritage Commission
Frankfort, KY
July 1977
FEB 8 1978

Photo **3**<sup>15</sup>Detail of main facade showing tympanum fanlight, concave recess and main entrance.

Photographer facing north.

OCT 31 1977



FEB 8 1978

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 8. Exterior detail.

Note splayed arch over window and molded cornice bricks.

OUT 31 1977



FEB 8 1978

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 7. Exterior view from northeast 31 1977



FEB 8 1978

Photographer Unknown 1970 Courtesy of Mrs. James Graves, Paris, KY

Photo 12. Rear facade viewed from north. Prior to restoration.

OCT 31 1977



Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 5.6 Doorway leading from dining room to stairhall.

Note decorative stringers and chair-railing.



FEB 8 1978

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 6% East parlor mantel.

OCT 31 1977



FEB 8 1978

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 7, Dining room mantel.

OCT 31 1977



Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo Mantel in central sitting room. Built-in press to right. FEB 8

1978



Escondida FEB 8 1978
Paris vicinity
Bourbon County
Kentucky OCT 3 1 1977

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 193 15 Mantel in first floor bedroom.




Escondida
Paris vicinity FEB 8 1978
Bourbon County
Kentucky

OCT 3 1 1977

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 122 Mantel in first floor bedroom—east wing. Note low baseboard and chair—railing.



Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977


Photo **B** Mantel in second floor bedroom at northeast corner.



Escondida FEB 8 1978
Paris vicinity
Bourbon County
Kentucky OCT 3 1 1977

Mary Cronan Oppel
Kentucky Heritage Commission
Frankfort, KY
July 1977

Photo 149<sup>15</sup> Dining room press. Note gradation of sizes of panels.



Escondida
Paris vicinity FEB 8 1978
Bourbon County
Kentucky OCT 3 1 1977

Mary Cronan Oppel Kentucky Heritage Commission Frankfort, KY July 1977

Photo 1**E**<sub>0</sub>15Ca. 1900 stone barn 25 yards west of residence. View from northeast.