

Photo: #1 of 36 Date: 1-5-83 Antelope Valley Indian Museum Museum with Piute Butte in View: the background Looking north Direction: Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #2 of 36 Date: 1-5-83 Antelope Valley Indian Museum Front of Museum building View: Looking north Direction: Dick Edwards Photographer: DPR, Southern Region Hdqtrs. Negative:




Photo: #3 of 36 Date: 1-5-83 Antelope Valley Indian Museum Front porch of Museum building View: showing use of Joshua Trees Direction: Looking north Dick Edwards Photographer: DPR, Southern Region Hdatrs. Negative:



Photo: #4 of 36 Date: 1-5-83 Antelope Valley Indian Museum Close up of Chumash rock art View: sand paintings by Jean Chernoff Direction: Looking north Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #5 of 36 Date: 1-5-83 Antelope Valley Indian Museum Gable of Museum building show-View: ing Joshua wood battens and murals Looking north Direction: Dick Edwards Photographer: Negative: DPR, Southern Region Hdgtrs.




Date: 1-5-83 Photo: #6 of 36 Antelope Valley Indian Museum Detail of mural by H. Arden View: Edwards Looking north Direction: Dick Edwards Photographer: DPR, Southern Region Hdqtrs. Negative:



Photo: #7 of 36 Date: 1-5-83 Antelope Valley Indian Museum West side of Museum building View: Looking northeast Direction: Dick Edwards Photographer: DPR, Southern Region Hdqtrs. Negative:



Photo: #8 of 36 Date: 1-5-83 Antelope Valley Indian Museum West side Museum building -View: detail of use of natural stone as wall Direction: Looking northeast Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Date: 1-5-83 Photo: #9 of 36 Antelope Valley Indian Museum View: East side of Museum building Direction: Looking west Photographer: Dick Edwards DPR, Southern Region Hdgtrs. Negative:



Photo: #10 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: East side of tower - detail of H. Arden Edwards' mural Direction: Looking west Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #11 of 36 Date: 1-5-83 Antelope Valley Indian Museum North side of Museum building -View: the California Wing Looking south Direction: Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #12 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: California Wing showing the natural stone which continues inside as the floor Direction: Looking southeast Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #13 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Gift Shop Direction: Looking northwest Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #14 of 36 Date: 1-5-83 Antelope Valley Indian Museum Yucca Cottage View: Direction: Looking north Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:




Photo: #15 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Rock Cottage Direction: Looking northwest Photographer: Dick Edwards Negative: DPR, Southern Region Hdqtrs.




Photo: #16 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Butterfly Cottage Direction: Looking northeast Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #17 of 36 Date: 1-5-83 Antelope Valley Indian Museum District Lizard Cottage View: Looking north Direction: Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:




Photo: #18 of 36 Date: 1-5-83 Antelope Valley Indian Museum Bluebird Cottage front view View: Direction: Looking northeast Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #19 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Bluebird Cottage - south and east view Looking northwest Direction: Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #20 of 36 Date: 1-5-83 Antelope Valley Indian Museum Joshua Cottage front view View: Direction: Looking east Photographer: Dick Edwards DPR, Southern Region Hdqtrs. Negative:



Photo: #21 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Joshua Cottage - rear view showing U shape of building Direction: Looking northwest Photographer: Dick Edwards Negative: DPR. Southern Region Hdqtrs.




Photo: #22 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Joshua Cottage - detail of H. Arden Edwards art work Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #23 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Swimming Pool Direction: Looking west Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.




Photo: #24 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Picnic Area Direction: Looking northwest Photographer: Dick Edwards Negative: DPR, Southern Region Hdatrs.




Photo: #25 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Road to cottages and picnic area Direction: Looking northeast Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #26 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Barn and Corral Direction: Looking northwest Photographer: Dick Edwards Negative: DPR, Southern Region Hdqtrs.



Photo: #27 **of 36**Antelope Valley Indian Museum Date: 1-5-83 View: Barn - west and south sides Direction: Looking north Photographer: Dick Edwards Negative: DPR, Southern Region Hdatrs.



Photo: #28 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Garage/Workshop Direction: Looking west Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.




Photo: #29 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Restroom Direction: Looking northwest Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.




Photo: #30 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Paint Shed Direction: Looking north Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #31 of 36 Date: 1-5-83 Antelope Valley Indian Museum View: Utility/Storage Shed Direction: Looking east Photographer: Dick Edwards Negative: DPR, Southern Region Hdgtrs.



Photo: #32 of 36 Date: 1929 Antelope Valley Indian Museum View: Construction of Museum building Direction: Looking northwest Photographer: Unknown Antelope Valley Indian Museum Negative: Advisory Committee



Photo: #33 of 36 Date: 1929 Antelope Valley Indian Museum View: Construction of Museum building Direction: Looking west Unknown Photographer: Negative: Antelope Valley Indian Museum Advisory Committee



Photo: #34 of 36 Date: 1928 Antelope Valley Indian Museum View: Construction of Museum building Direction: Looking west Photographer: Unknown Negative: Antelope Valley Indian Museum Advisory Committee



Photo: #35 of 36 Date: 1929 Antelope Valley Indian Museum View: Construction of Museum building Direction: Looking south Photographer: Unknown Negative: Antelope Valley Indian Museum Advisory Committee




Photo: #36 of 36 Date: 1928 Antelope Valley Indian Museum View: Construction of Museum building Direction: Looking southeast Photographer: Unknown Negative: Antelope Valley Indian Museum Advisory Committee