



Benjamin James House
Hampton (Rockingham Co.), NH

Lisa Mausolf, Photographer

November 2000

Neg; L. Mausolf, Reading, Mass.

View looking NE showing west + southeast.

Photo 1



Benjamin James House
Hampden (Rockingham Co.), NH
Lisa Mausolf, Photographer
November 2000

Neg: L. Mausolf, Reading, Mass.
View looking SE showing north + west elev.
Photo 2



Benjamin James House (Shed)

Hampton (Rockingham Co.), NH

Lisa Mausolf, Photographer

November 2000

Neg: L. Mausolf, Reading, Mass.

View looking SE


Photo 3



CAUTION
FLOOR
ARE T
UP :
OF VE
FOR S

Benjamin James House
Hampton (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec 2001

Neg: L. Mausolf, Reading, Mass.
View looking east at
door surround leading
from entry hall to parlor
photo 4



Benjamin James House
Haupton (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec. 2001

Neg: L. Mausolf, Reading, Mass.

View looking NW at fireplace surround
and summer beam in east parlor


Photo 5



Benjamin James House
Hampton (Rockingham Co.), NH
Lisa Mausolf, Photographer

Dec. 2001

Neg: L. Mausolf, Reading, Mass.
View looking SE at summer beam
in hall
Photo 6



Benjamin James House
Hauptm (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec. 2001

Neg: L. Mausolf, Reading, Mass.
View looking west at west
wall of northwest
chamber, second floor
Photo 7




Benjamin James House
Haystack (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec 2001

Neg: L. Mausolf, Reading, Mass
View looking west at rear
wall of main house
Photo 8



Benjamin James House
Hampton (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec. 2001

Neg: L. Mausolf, Reading, Mass.
View looking toward west end of attic
photo 9



Benjamin James House
Hampton (Rockingham Co.), NH
Lisa Mausolf, Photographer
Dec 2001

Neg: L. Mausolf, Reading, Mass.
View looking toward east
end of attic
Photo 10