


United States Department of the Interior
National Park Service



1332

National Register of Historic Places
Registration Form

This form is for use in nominating or requesting determinations for individual properties and districts. See instructions in *How to Complete the National Register of Historic Places registration Form* (National Register Bulletin 16A). Complete by entering the information requested. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional entries and narrative items on continuation sheets (NPS Form 10-900a). Use a typewriter, word processor, or computer, to complete all items.

1. Name of Property

historic name East Buntyn Historic District

other names/site number N/A

2. Location

street & number Roughly bounded by Central, Southern, Ellsworth & Greer N/A not for publication

city or town Memphis N/A vicinity

state Tennessee code TN county Shelby code 157 zip code 38111

3. State/Federal Agency Certification

As the designated authority under the National Historic Preservation Act, as amended, I hereby certify that this nomination request for determination of eligibility meets the documentation standards for registering properties in the National Register of Historic Places and meets the procedural and professional requirements set for in 36 CFR Part 60. In my opinion, the property meets does not meet the National Register criteria. I recommend that this property be considered significant nationally statewide locally. (See continuation sheet for additional comments.)

Herbert L. Berger 10/4/95
Signature of certifying official/Title Date

Deputy State Historic Preservation Officer, Tennessee Historical Commission
State or Federal agency and bureau

In my opinion, the property meets does not meet the National Register criteria. (See Continuation sheet for additional comments.)

Signature of certifying official/Title Date

State or Federal agency and bureau

4. National Park Service Certification

- I hereby certify that the property is:
- entered in the National Register. See continuation sheet
- determined eligible for the National Register. See continuation sheet
- determined not eligible for the National Register
- removed from the National Register.
- other, (explain): _____

Edson H. Beall 11-22-95
Signature of the Keeper Date of Action

Entered in the
National Register.

5. Classification

Ownership of Property
(Check as many boxes as apply)

- private
- public-local
- public-State
- public-Federal

Category of Property
(Check only one box)

- building(s)
- district
- site
- structure
- object

Number of Resources within Property
(Do not include previously listed resources in count)

Contributing	Noncontributing	
599	80	buildings
		sites
		structures
		objects
599	80	Total

Name of related multiple property listing
(Enter "N/A" if property is not part of a multiple property listing.)

N/A

Number of Contributing resources previously listed
in the National Register

0

6. Function or Use

Historic Functions

(Enter categories from instructions)

DOMESTIC: single dwelling

DOMESTIC: multiple dwelling

DOMESTIC: secondary structure

Current Functions

(Enter categories from instructions)

DOMESTIC: single dwelling

DOMESTIC: multiple dwelling

DOMESTIC: secondary structure

7. Description

Architectural Classification

(Enter categories from instructions)

Craftsman, Bungalow, Colonial Revival, Tudor

Revival, OTHER: Minimal Traditional

Materials

(Enter categories from instructions)

foundation CONCRETE, BRICK

walls Weatherboard, BRICK, STUCCO

roof ASPHALT

other WOOD, STONE

Narrative Description

(Describe the historic and current condition of the property on one or more continuation sheets.)

8. Statement of Significance

Applicable National Register Criteria
(Mark "x" in one or more boxes for the criteria qualifying the property for National Register listing.)

- A** Property is associated with events that have made a significant contribution to the broad patterns of our history.
- B** Property is associated with the lives of persons significant in our past.
- C** Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.
- D** Property has yielded, or is likely to yield, information important in prehistory or history.

Areas of Significance
(Enter categories from instructions)

ARCHITECTURE

Period of Significance
ca. 1925 - 1945

Criteria Considerations
(Mark "x" in all boxes that apply.)

Property is: N/A

- A** owned by a religious institution or used for religious purposes.
- B** removed from its original location.
- C** moved from its original location.
- D** a cemetery.
- E** a reconstructed building, object, or structure.
- F** a commemorative property
- G** less than 50 year of age or achieved significance within the past 50 years.

Significant Dates
N/A

Significant Person
(complete if Criterion B is marked)
N/A

Cultural Affiliation
N/A

Architect/Builder
various

Narrative Statement of Significance
(Explain the significance of the property on one or more continuation sheets.)

9. Major Bibliographical References

Bibliography
(Cite the books, articles, and other sources used in preparing this form on one or more continuation sheets.)

- Previous documentation on file (NPS):** N/A
- preliminary determination of individual listing (36 CFR 67) has been requested
 - previously listed in the National Register
 - Previously determined eligible by the National Register
 - designated a National Historic Landmark
 - recorded by Historic American Buildings Survey # _____
 - recorded by Historic American Engineering Record # _____

Primary location of additional data:

- State Historic Preservation Office
- Other State Agency
- Federal Agency
- Local Government
- University
- Other

Name of repository:
Memphis Housing & Community Development

East Buntyn Historic District
Name of Property

Shelby County, TN
County and State

10. Geographical Data

Acreage of Property 166.5 acres Southeast Memphis, TN 409 SW

UTM References

(place additional UTM references on a continuation sheet.)

1	<u>16</u>	<u>231440</u>	<u>3890500</u>	3	<u>16</u>	<u>230720</u>	<u>3889680</u>
	Zone	Easting	Northing		Zone	Easting	Northing
2	<u>16</u>	<u>231460</u>	<u>3889640</u>	4	<u>16</u>	<u>230120</u>	<u>3890520</u>

See continuation sheet

Verbal Boundary Description

(Describe the boundaries of the property on a continuation sheet.)

Boundary Justification

(Explain why the boundaries were selected on a continuation sheet.)

11. Form Prepared By

name/title Judith Ann Johnson, Historic Preservation Analyst
organization City of Memphis Housing and Community Development date May 1995
street & number 701 North Main Street telephone 901-567-7355
city or town Memphis state TN zip code 38107-2311

Additional Documentation

submit the following items with the completed form:

Continuation Sheets

Maps

A **USGS map** (7.5 or 15 minute series) indicating the property's location

A **Sketch map** for historic districts and properties having large acreage or numerous resources.

Photographs

Representative **black and white photographs** of the property.

Additional items

(Check with the SHPO) or FPO for any additional items

Property Owner

(Complete this item at the request of SHPO or FPO.)

name Public Notice
street & number _____ telephone _____
city or town _____ state _____ zip code _____

Paperwork Reduction Act Statement: This information is being collected for applications to the National Register of Historic Places to nominate properties for listing or determine eligibility for listing, to list properties, and to amend existing listing. Response to this request is required to obtain a benefit in accordance with the National Historic Preservation Act, as amended (16 U.S.C. 470 *et seq.*)


Estimated Burden Statement: Public reporting burden for this form is estimated to average 18.1 hours per response including time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding this burden estimate or any aspect of this form to the Chief, Administrative Services Division, National Park Service, P. O. Box 37127, Washington, DC 20013-7127; and the Office of Management and Budget, Paperwork Reductions Projects (1024-0018), Washington, DC 20303.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 1

East Buntyn Historic District
Shelby County, TN



Physical Description

The East Buntyn Historic District is located in the city of Memphis, Shelby County, in western Tennessee. The eleven block East Buntyn Historic District is located approximately six miles east of downtown and contains a largely intact and homogenous residential building stock. As the district's name implies, the area is due east of the old railroad community of Buntyn. The boundary of the East Buntyn Historic District is formed by the rear property lines of the eastern side of Ellsworth Street on the east, the southern property lines of the last contributing houses before Southern Avenue on the south, the east side of Greer Street on the west, and the south side of Central Avenue on the north. All but Greer Street serve as major traffic arteries with an average width of eighty feet.

The district is comprised of 683 buildings, of which, 599 are contributing and 80 are noncontributing. The building stock consists of houses, duplexes, churches, garages, carports, sheds, guest houses and a greenhouse and a summerhouse. The building stock ranges from excellent to fair condition, most buildings are in good condition.

The district's internal streets are arranged in a bilateral grid with six blocks of equal size to the south of Midland and five similar blocks to the north of Midland. Holmes Circle and Overland Place represent the only departures from the district's grid plan. Overland Place is a cul-de-sac with a tree-lined median. In 1941, Holmes Street was extended north to Greer Street with the addition of Holmes Circle.

There is a marked horizontal character to the topography of East Buntyn. However, a gradual rise is detectable along a diagonal toward the southeast from Central Avenue and Greer to Ellsworth and Southern. The greatest relative incline occurs on Ellsworth between Central and Midland.

All residential streets in East Buntyn are 50 feet in width and have cast concrete curbing, gutters and three feet wide sidewalks. The streets cut directly through the gently rolling landscape resulting in terracing of varying heights on many lots. Lot sizes are generally 50 feet wide by 190 feet deep and setbacks of 40 feet predominate.

The landscaping of the East Buntyn Historic District is dominated by mature deciduous trees such as oak, maple, sweet gum and bald cypress which form green vaults over the streets creating a forest-like effect. Evergreen species of cedar, pine, native and exotic magnolia and American holly add contrasting colors and textures during the summer and winter. In addition to the shade trees, azalea, dogwood and hydrangea vividly paint the passage of the seasons.

Outbuildings in the district are mainly one car garages located on the rear of many lots at the end of the driveway. These buildings are all nearly identical gable-front buildings with the original double-hinged doors or overhead doors added at a later date.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 2

East Buntyn Historic District
Shelby County, TN

The character of the neighborhood is defined by the almost stylistically homogenous collection of Eclectic style residential dwellings of the mid-1920s through World War II. Most of the building stock dates from circa 1925 to 1945 and displays the characteristics of the architectural forms and styles from this period. The architectural forms represented are the bungalow, the one-story Colonial Revival cottage and the Tudor cottage. Architectural styles include Craftsman, Colonial Revival, Tudor Revival, Minimal/Traditional and Ranch.

The two churches located in the district also reflect the Eclectic style of the housing stock. The 1941 East Side Cumberland Presbyterian Church at 461 S. Prescott Street is in the Tudor Revival style with stone veneer and a Tudor door with an arched stone surround and flying buttresses. The Old Sanctuary of the Buntyn Presbyterian Church is Colonial Revival and retains its integrity, however, it has been abusively altered by the 1955 addition of a new sanctuary on the south side of the building.

An inventory of all structural resources in the East Buntyn area was prepared by K. David Sample and Kim C. Isbell in 1989-1990, *as part of the Memphis Survey*. A first draft National Register nomination was prepared in 1990. In the summer of 1994 the survey data was field-checked and updated and a final draft was prepared by Judith Ann Johnson of the City of Memphis Division of Housing and Community Development with assistance by Tim and Jane Carroll and Jane Kowalewski.

A glossary describing the characteristics of these architectural styles, forms and their individual details are included as a continuation of this nomination. The glossary is adapted from A Field Guide to American Houses by Virginia and Lee McAlester, 1984.

Glossary Of Survey Terms

Bungalow

The bungalow was a generic term applied to relatively unpretentious one-story or story-and-a-half houses of 600 to 800 square feet with small bedrooms and kitchens and a combination living/dining room. This room generally featured exposed ceiling beams, a rough brick or stone fireplace and bands of windows.

Craftsman

The Craftsman style was a clear break from 19th-century derivative architecture that dominated American home building until circa 1910. The identifying features of the Craftsman style include a low-pitched, gable roof with wide, unenclosed eaves overhang; roof rafters usually exposed; decorative beams or braces commonly added under the gables; porches, either full- or partial-width,

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 3

East Buntyn Historic District
Shelby County, TN

with the roof supported by tapered square columns; columns frequently extend to ground level. Locally the Craftsman style retained its popularity until the mid-1930s.

Craftsman windows exhibit geometric patterns of small-pane window glazing in the upper sashes of wooden-muntin, double hung windows.

Craftsman doors exhibit multiple lights composed of a band of lights with the tracery arranged in a set of bordering square and rectangular panes. A second type of Craftsman door has an arrangement of multiple lights above a modillioned rail mounted on the spandrel, above a paneled lower area.

Tudor Cottage

This style was used for a large proportion of early-20th-century suburban houses throughout the country. The style is loosely based on a variety of late Medieval English prototypes. These traditions are freely mixed but place an emphasis on steeply pitched, front-facing gables, ornamental false half-timbering and large, elaborate chimneys. Most Tudor houses have stucco, masonry or masonry-veneered walls. Decorative detailing may draw from Renaissance or modern Craftsman traditions.

Round-arched Tudor doors often are heavy board-and-batten. The doorway may display tabs of cut stone around it or flattened pointed Tudor arches are often used in doorway surrounds or on entry porches.

Prominently placed Tudor chimneys may exhibit complex masonry or stone patterns; they may exhibit multiple shafts also.

Tudor windows can be casements or double sash. Windows are frequently grouped in strings of three or more.

Colonial Revival

This was the dominate style of domestic architecture throughout the country during the first half of the twentieth century and refers to the rebirth of interest in the early English and Dutch houses of the Atlantic seaboard. Symbolic details from the precedents are often combined so eclectic mixtures are most often found instead of pure copies. Identifying features include an accentuated front door, normally with an engaged pediment supported by pilasters; a symmetrical facade; and windows with double-hung sashes, usually with multi-pane glazing. All of the Colonial Revival houses in East Buntyn are the Cape Cod type, a common form of one-story Colonial Revival house. As a form it originated in the early 18th century and continued unchanged until the 1950s. It often exhibits telescopic wings and two gable dormers.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 4

East Buntyn Historic District
Shelby County, TN

Minimal Traditional

The Minimal/Traditional influence is the primary stylistic detailing of residential architecture following the Craftsman and Colonial Revival periods. The style was popular in the Memphis area from c. 1930 to c. 1970. These spare houses retain the form of traditional Tudor houses but lack their decoration. Roof pitches are low, eaves and rake are close, windows have little or no reveal. Brick veneered exterior surfaces were a common treatment. Often there is a large chimney and one front-facing gable, both echoing Tudor influences.

Ranch

This style originated in California in the mid-1930s and is loosely based on Spanish Colonial precedents of the American southwest. The form is dominated by asymmetrical one-story shapes with low-pitched hip roofs with a moderate to wide eaves overhang. Both wood and brick wall cladding are used, as well as modest bits of Spanish or English Colonial detailing.

INVENTORY

Contributing resources (C) add to the historic architectural qualities and historic associations for which the property is significant. Contributing resources were present during the period of significance and retain integrity. Noncontributing resources (NC) do not add to the historic architectural qualities or associations of the district because they were not present during the period of significance or they have lost integrity due to alterations.

ALEXANDER STREET

1. 327 Alexander. c. 1985. Colonial Revival. Brick veneer on first story, weatherboard on second story, asphalt shingle hip roof, L-plan; off set entry, 6/6 windows, garage appends to principal facade. (NC)
2. 330 Alexander. c. 1945. Minimal Traditional. Brick veneer, 1.5 story, asphalt shingle cross gabled roof, irregular plan; principal entry has limestone surround and stoop porch with copper hip roof; 4-4 casement windows. (C)
3. 331 Alexander. c. 1940 Colonial Revival. Asbestos shingle, 1 story, square plan; asphalt shingle side gable roof, 6/6 paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 5

East Buntyn Historic District
Shelby County, TN

-
4. 334 Alexander. c. 1940. Colonial Revival. Aluminum siding, 1.5 story, asphalt shingle gable roof, rectangular plan with rear shed addition, classical door surround, 6/6 paired windows. (C)
 5. 335 Alexander. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, sawn rafter tails, half timber/stucco in gable ends, full porch with porte cochere; 3/1 triple Craftsman windows. (C)
 6. 340 Alexander. c. 1975. Ranch. Brick veneer, 1 story, L- plan; asphalt shingle hip roof, single bay incised porch with wrought iron supports; 2/2 windows. (NC)
 7. 341 Alexander. c. 1930. Craftsman Bungalow. Brick veneer, rectangular plan; asphalt shingle front gable roof, sawn rafters, knee braces and half timbering/stucco in gable ends, triple casement windows in gable ends, partial porch with porte cochere; 6/1 double hung windows. (C)
 8. 344 Alexander. c. 1940. Craftsman Bungalow. Uncoursed stone veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof; single bay porch with gable roof; 3/1 paired Craftsman windows. (C)

Garage. c. 1940. Weatherboard, single bay, paired hinged doors, asphalt shingle gable roof. (C)
 9. 345 Alexander. c. 1940. Colonial Revival. Beveled board siding, 1.5 story, rectangular plan; asphalt shingle side gable roof, shed dormer, partial porch; 3/1 double hung windows. (C)

Garage. c. 1940. Weatherboard, single bay, asphalt shingle roof, paired hinged double doors. (C).
 10. 350 Alexander. c. 1940. Colonial Revival. Beveled board, 1 story, rectangular plan with ell, asphalt shingle side gable roof, enclosed partial porch with shed roof, bay window, 6/6 double hung windows. (C)
 11. 351 Alexander. c. 1940 Tudor Revival Cottage. Uncoursed stone, 1.5 story, asphalt shingle side gable roof with cross gables, L-plan; semi-elliptical front entry, 6/6 double hung windows. (C)
 12. 354 Alexander. c. 1925 Craftsman Bungalow. Brick veneer, 1 story, T-plan; asphalt shingle gable roof, full porch with porte cochere, gable entry, and brick pier supports; French door main entry, 3/1 double hung windows. (C)
 13. 355 Alexander. 1927. Craftsman Bungalow. Brick veneer. 1 story, rectangular plan; asphalt shingle gable roof; full porch with porte cochere, brick pier supports, 1/1 double hung windows. (C)

Garage. c. 1965. Weatherboard, rectangular plan, gable roof with asphalt shingles, overhead door. (NC)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 6

East Buntyn Historic District
Shelby County, TN

-
14. 360 Alexander. 1928. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable entry, brick pier supports; double hung 4/1 windows. (C)
15. 361 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, brick pier supports; double hung 3/1 sash windows. (C)
- Garage. 1927. Weatherboard, rectangular plan, gable roof with asphalt shingles, hinged double doors. (C)
16. 364 Alexander. c. 1940. Minimal/Traditional. Brick veneer, 1 story, asphalt shingle side gable roof, irregular plan; gable entry porch with wrought iron supports; 6/9 windows. (C)
17. 365 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and wrought iron supports; double hung 1/1 windows. (C)
- Garage. 1927. Weatherboard, rectangular plan, asphalt shingle gable roof, hinged paired doors. (C)
18. 370 Alexander. c. 1940. Minimal/Traditional. Brick veneer, 1.5 story, asphalt shingle side gable roof, rectangular plan, 2 bay porch with wrought iron supports; 1/1 sash windows. (C)
19. 371 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle front gable roof, exposed rafters; full porch with double gable entry roof and brick pier supports; 6/1 double hung windows. (C)
- Garage. c. 1960. Vinyl siding, rectangular plan, gable roof with asphalt shingles, overhead doors. (NC)
20. 374 Alexander. c. 1950. Minimal/Traditional. Brick veneer, 1.5 story, irregular plan, asphalt shingle side gable roof, single bay porch with wrought iron supports; double hung 6/6 window. (NC)
21. 375 Alexander. c. 1950. Colonial Revival. Brick veneer, 1 story, asphalt shingle side gable roof, irregular plan; stoop porch, off set entry, bay window, double hung 6/6 sash windows. (NC)
22. 378 Alexander. c. 1940. Classical Revival Cottage. Asbestos shingle siding, 1 story, asphalt shingle side gable roof; 2 bay porch, gable roof with paired boxed column supports; 6/6 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 7

East Buntyn Historic District
Shelby County, TN

-
23. 381 Alexander. c. 1935. Tudor Revival Cottage. Brick veneer, 1.5 story, asphalt shingle multi-gable roof, L- plan; partial porch with gable roof and battered brick pier supports; semi-elliptical front entry, double hung 6/1 windows. (C)
- Garage. c. 1965. Vinyl siding, rectangular plan, asphalt shingle gable roof, overhead door. (NC)
24. 384 Alexander. c. 1930. Asbestos shingle siding, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with shed roof and boxed column supports; double hung 6/6 windows. (C)
25. 385 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asbestos shingle gable roof, partial porch with porte cochere, double hung 3/1 windows. (C)
26. 390 Alexander. 1944. Minimal/Traditional. Brick veneer, 1.5 story, L-plan; asphalt shingle side gable roof, single bay entry porch with shed roof and wrought iron supports; double hung 6/6 sash windows. (C)
27. 391 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1.5 story, asphalt shingle multi-gable roof, irregular plan; partial porch with porte cochere, gable roof, and brick pier supports; double hung 3/1 Craftsman windows. (C)
28. 395 Alexander. c. 1985. Colonial Revival. Weatherboard siding, 1.5 story, rectangular plan; asphalt shingle side gable roof, Colonial door surround, double hung 9/9 sash windows. (C)
29. 396 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, irregular plan; half timber/stucco in gable ends, asphalt shingle jerkin head roof, full porch with porte cochere, gable roof, and piers on pedestal supports; double hung 1/1 windows. (C)
30. 401 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, irregular plan; asphalt shingle multi-gable roof, exposed rafters, knee brace supports; partial porch with battered piers on pedestal supports; double hung 6/1 sash windows. (C)
31. 404 Alexander. 1944. Minimal Traditional. Brick veneer, 1.5 story, L-plan; asphalt shingle side gable roof, single bay porch, hip roof, and wrought iron supports; double hung 6/6 windows. (C)
32. 407 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1.5 story, irregular plan; asphalt shingle side gable roof, exposed rafters, irregular plan; partial porch, gable roof, and wrought iron supports; double hung 9/1 Craftsman paired windows. (C)
- Garage. 1927. Weatherboard, rectangular plan, asphalt shingle gable roof, hinged double doors. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 8

East Buntyn Historic District
Shelby County, TN

-
33. 410 Alexander. 1944. Colonial Revival Cottage. Wood shingle siding, 1.5 story, L-plan; asphalt shingle side gable roof, 2 gable dormers, stoop porch with wrought iron replacement posts, double hung 6/6 sash windows. (C)
34. 414 Alexander. 1944. Colonial Revival Cottage. Beveled wood siding, 1.5 story, L-plan; asphalt shingle side gable roof, 2 gable dormers, single bay porch with shed roof and boxed column supports; double hung 6/6 windows. (C)
- Garage. 1944. Weatherboard, rectangular plan, asphalt shingle gable roof, hinged double doors. (C)
35. 415 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof; full porch with porte cochere, hip roof, and brick pier supports; double hung 1/1 paired windows. (C)
- Garage. 1927. Weatherboard, rectangular plan, asphalt shingle gable roof, replacement overhead door. (C)
36. 420 Alexander. 1944. Colonial Revival Cottage. Aluminum siding, 1 story, rectangular plan; asphalt shingle side gable roof; double hung 6/6 windows. (C)
- Garage. 1970. Wood siding, rectangular plan, asphalt shingle gable roof, overhead door. (NC)
37. 421 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, exposed rafter tails; rectangular plan; full porch with porte cochere, hip roof, gable entry, and battered pier supports; 1/1 double hung windows. (C)
38. 424 Alexander. c. 1940. Classical Revival Cottage. Weatherboard, 1.5 story, asphalt shingle side gable roof, single bay porch with gable roof, and boxed column supports; Craftsman door; double hung 6/6 windows. (C)
- Garage. c. 1940. Weatherboard, rectangular plan, asphalt shingle gable roof, hinged double doors. (C)
39. 427 Alexander. 1927. Vinyl siding, 1 story, asphalt shingle side gable roof, rectangular plan with rear shed addition, full porch with porte cochere, shed roof and plain post supports; 6/6 double hung windows. Renovated 1989. (NC due to alterations)
40. 430 Alexander. c. 1940. Tudor Revival Cottage. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, stoop porch, off set entry, semi-elliptical front entry, other semi-elliptical features include window on porch facade and vent in gable end, 6/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 9

East Buntyn Historic District
Shelby County, TN

-
41. 431 Alexander. 1927. Weatherboard, 1 story, built-up flat roof with parapet wall, L-plan; single bay porch with hip roof and plain supports; sweeping mansard copper hoods over principal 8/8 windows. (NC due to alterations)
 42. 434 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle jerkin head roof, rectangular plan, exposed rafters; full porch with paired jerkin head entry roof and brick pier supports; 3/1 double hung Craftsman windows. (C)
 43. 437 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle front gable roof, half timber /stucco, partial porch with porte cochere, gable roof, and brick pier supports; 1/1 double hung windows. (C)
 44. 438 Alexander. 1928. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch, hip roof, gable entry, and brick pier supports; Craftsman 3/1 paired windows. (C)
 45. 441 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, rectangular plan; exposed rafters, full porch with brick battered pier supports; 24 light stationary window. (C)
 46. 444 Alexander. 1944. Colonial Revival Cottage. Brick veneer, 1 story, asphalt shingle front gable roof, rectangular plan with ell, stoop with gable roof, and 6/6 double hung paired windows. (C)
 47. 445 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle jerkin head roof, exposed rafters, partial porch, hip roof, jerkin head gable entry, with pier supports; 1/1 double hung paired windows. (C)
 48. 450 Alexander. 1944. Classical Revival Cottage. Asbestos siding, 1.5 story, rectangular plan, asphalt shingle side gable roof, 2 gable dormers, partial porch with gable roof and triple classical column supports; 6/6 double hung windows. (C)
 49. 451 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle jerkin head roof, rectangular plan with rear shed roof addition, full porch, hip roof and brick pier supports; 1/1 double hung paired windows. (C)
 50. 460 Alexander. 1944. Colonial Revival Cottage. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, single bay porch with gable roof and boxed column supports; 6/6 double hung windows with attached garage. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 10

East Buntyn Historic District
Shelby County, TN

-
51. 461 Alexander. 1940. Minimal/Traditional. Asbestos shingle siding, 1 story, L-plan; asphalt shingle side gable roof, 1 bay porch with gable roof and wrought iron support; 2/2 double hung paired windows. (C)

Storage Shed. c.1940. Wood paneled siding, 1 bay, asphalt shingle gable roof. (C)

52. 465 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan with rear shed addition, asphalt shingle front gable roof, sawn rafter tails, full porch with brick pier supports; 1/1 double hung paired windows. (C)

Garage. c. 1925. Beveled siding, rectangular plan; 1 bay, overhead door, asphalt shingle gable roof. (C)

53. 466 Alexander. c. 1975. Contemporary. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, single bay porch with shed roof and turned posts supports; 9/6 double hung aluminum storm paired windows. (NC)

Garage. c.1975. Weatherboard, asphalt shingle gable roof, exposed rafters, hinged double doors. (NC)

54. 470 Alexander. c. 1930. Tudor Revival Cottage. Brick veneer, 1.5 story, irregular plan; asphalt shingle side gable roof, half timber/stucco and casement window in gable ends, semi-elliptical recessed front entry, batten door, 6/1 double hung paired windows. (C)

55. 471 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters; full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c.1980. Weatherboard, single bay, overhead door, asphalt shingle gable roof. (NC)

56. 474 Alexander. c. 1930. Tudor Revival Cottage. Beveled siding, 1.5 story, irregular plan; asphalt shingle side gable roof, stoop porch with shed roof and knee brace supports; 6/6 double hung windows. (C)

57. 475 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle front gable roof, exposed rafters, full porch with gable roof and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c.1980. Weatherboard, single bay, overhead door, asphalt shingle gable roof. (NC)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 11

East Buntyn Historic District
Shelby County, TN

-
58. 480 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable, exposed rafters, half timber/stucco in gable ends, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)
- Guest House. c.1925. Weatherboard, 1 story, rectangular plan; asphalt shingle pyramidal roof, exposed rafters, 3 bay, 1/1 double hung aluminum storm replacement windows. (C)
59. 481 Alexander c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, casement window in gable end, full porch with porte cochere, jerkin head roof and brick battered pier supports; 6/1 double hung paired Craftsman windows. (C)
- Summer House. c. 1985. Multiple bays, frame construction, square plan; asphalt shingle hip roof. (NC)
60. 485 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, sawn rafters, full porch with paired jerkin head roof and brick pier supports; 6/1 double hung paired Craftsman windows. (C)
- Garage. c. 1925. Board and batten siding, double hinged door, asphalt shingle front gable roof. (C)
61. 486 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half timbering/stucco in gable ends, full porch with porte cochere, gable entry and brick pier supports; Craftsman door, 1/1 double hung paired windows. (C)
62. 490 Alexander. 1944. Tudor Revival Cottage. Brick veneer, 1.5 story, irregular plan; asphalt shingle side gable roof, semi-elliptical main entry, batten door, Uncoursed stone door surround, 6/6 double hung windows. (C)
- Garage. c. 1925. Weatherboard, 1 story, asphalt shingle gable roof, overhead door. (C)
63. 491 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, half timbering/stucco in gable ends, full porch with porte cohere and paired brick columns; 4/1 double hung paired Craftsman windows. (C)
64. 494 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, hip roof, and stone battered pier supports; off set multi-light main entry, paired French door second entry, 6/1 double hung triple Craftsman windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 12

East Buntyn Historic District
Shelby County, TN

65. 495 Alexander. c. 1945. Colonial Revival. Brick veneer, 1.5 story, T-plan; asphalt shingle side gable roof, stoop porch, door surround with curved broken pediment and finial, 8/8 double hung windows. (C)

Garage. c. 1945. Beveled siding, asphalt shingle front gable roof, double hinged door. (C)

66. 500 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, square plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; 3/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, open bay. (C)

67. 501 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, half timbering/stucco in gable ends, full porch with porte cochere, hip roof, jerkin head entry and brick battered pier supports; 1/1 double hung triple windows. (C)

68. 504 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof and brick pier supports; 3/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, single bay, overhead door. (C)

69. 505 Alexander. c. 1930. Tudor Revival Cottage. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, half timber/stucco, full porch with brick pier support, 3/1 double hung paired Craftsman windows. (C)

Garage. c. 1925. Weatherboard siding, 2 bay, double hinged doors, parapet, flat roof. (C)

70. 508 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, hip roof and brick pier supports; 1/1 double hung paired windows. (C)

71. 511 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle side gable roof, exposed rafters, half timbering/stucco in gable ends; full porch with porte cochere, gable entry and brick pier supports; 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 13

East Buntyn Historic District
Shelby County, TN

72. 512 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere, gable entry and brick pier supports; 1/1 double hung windows. (C)

Shed. c. 1975. Metal siding, asphalt shingle gable roof, single bay. (NC)

73. 515 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle jerkin head roof, exposed rafters, half-timbering/stucco in gable ends, partial porch with porte cochere, jerkin head roof and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c.1925. Weatherboard, 1 bay, double hinged door, asphalt shingle gable roof. (C)

74. 520 Alexander. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere, gable entry and brick pier supports; Craftsman door, French door second front entry, 1/1 double hung windows. (C)

75. 521 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, partial porch with porte cochere, jerkin head roof and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c.1940. Beveled wood siding, 2 bay, overhead door, asphalt shingle gable roof. (C)

76. 524 Alexander. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable entry and brick pier supports; 1/1 double hung paired windows. (C)

77. 525 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere, and brick pier supports; 1/1 double hung paired windows. (C)

78. 530 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, full porch, hip roof, boxed columns on pedestal supports; Craftsman door 3/1 double hung windows. (C)

79. 531 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c.1940. Weatherboard, 2 bay, double hinged door, asphalt shingle gable roof. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 14

East Buntyn Historic District
Shelby County, TN

80. 535 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear ell additions, asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung windows. (C)

Garage. c.1925. Weatherboard, 1 bay, asphalt shingle gable roof, hinged double door. (C)

81. 536 Alexander. c. 1965. Minimal Traditional. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, single bay porch with off set entry, 2/2 double hung windows. (NC)

Garage. c.1965. Novelty siding, asphalt shingle gable roof, overhead door. (NC)

82. 540 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with side ell addition, asphalt shingle front gable roof, exposed rafters, full porch, gable entry and brick pier supports; 3/1 double hung triple Craftsman windows. (C)

83. 541 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, monitor with side gable roof, full porch with porte cochere, gable entry and stone pier supports; 1/1 double hung windows. (C)

Garage. c. 1940. Beveled wood siding, asphalt shingle gable roof, 2 bay, no door. (C)

84. 544 Alexander. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, partial porch with porte cochere, gable roof and brick pier supports; 3/1 double hung paired windows. (C)

Carport and Tool Shed. c. 1940. Beveled wood siding, asphalt shingle gable roof. (NC due to alterations)

85. 545 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere, hip roof, jerkin head entry, and brick pier supports; altered entry, 9/1 double hung Craftsman windows. (NC due to alterations)

Garage. c.1925. Weatherboard, asphalt shingle gable roof, 2 bay, double hinged door. (C)

86. 550 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung windows. (C)

Garage. c. 1925. Beveled wood siding, asphalt shingle gable roof, double hinged doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 15

East Buntyn Historic District
Shelby County, TN

-
87. 551 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, brick pier supports; 1/1 double hung window. (C)
- Garage. c.1940. Aluminum siding, asphalt shingle gable roof, 1 bay, double hinged door. (C)
88. 554 Alexander. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable entry and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Beveled wood siding, asphalt shingle gable roof, double hinged doors. (C)
89. 555 Alexander. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch, hip roof, gable entry, brick battered pier supports; 6/1 double hung Craftsman windows. (C)
- Garage with 2nd Story Apartment. c. 1960. Aluminum siding, 2 story, rectangular plan; asphalt shingle gable roof, overhead door. (NC)
90. 560 Alexander. c. 1925. Tudor Revival Cottage. Weatherboard, 1.5 story, irregular plan; asphalt shingle side gable roof, semi-elliptical main entry, batten door, 6/6 double hung windows. (C)
- Garage. c. 1925. Plywood siding, rolled asphalt shed roof, single open bay. (NC due to alterations)
91. 561 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle front gable roof, exposed rafters, partial/enclosed porch with porte cochere, wrought iron supports; 1/1 double hung windows. (C)
- Carport. c. 1970. 1 story, single bay, open bay, asphalt shingle front gable roof. (NC)
92. 564 Alexander. c. 1935. Tudor Revival Cottage. Beveled board siding, 1 story, irregular plan, asphalt shingle gable roof, uncoursed stone entry surround, 6/6 double hung windows. (C)
- Garage. c. 1925. Beveled siding, open bay, asphalt shingle front gable roof. (C)
93. 565 Alexander. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with gable roof and brick pier supports; 6/1 double hung triple windows. (C)
- Carport. c.1940. Beveled siding, asphalt shingle gable roof, open bay. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 16

East Buntyn Historic District
Shelby County, TN

-
94. 570 Alexander. c. 1925. Craftsman Bungalow. Aluminum siding, asphalt shingle front gable roof, exposed rafters, knee braces at gable ends, full porch with hip roof, gable entry, brick pier supports; Craftsman door, 1/1 double hung windows. (C)
95. 573 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip skirt roof, gable entry and brick pier supports; 1/1 double hung windows. (C)
- Garage. c. 1985. Vertical paneling, open bay, asphalt shingle gable roof. (NC)
96. 574 Alexander. C. 1925. Craftsman Bungalow. Weatherboard, rectangular plan; asphalt shingle front gable roof, full porch with hip roof and brick pier supports; entry altered, rafters enclosed, 1/1 double hung windows. (NC due to alterations)
- Garage. c.1925. Weatherboard, asphalt shingle gable roof, 2 bay, overhead door. (C)
97. 580 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch with porte cochere, hip roof, brick pier support, 3/1 Craftsman windows. (C)
98. 584 Alexander. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gambrel roof, exposed rafters, partial porch with porte cochere, gable roof, and brick pier supports; banks of leaded casement windows. (C)
99. 585 Alexander. c. 1925. Dutch Colonial Revival. Weatherboard, 2 story, rectangular plan; asphalt shingle gambrel roof, shed dormer, curved entry porch, side porch enclosed, 6/1 double hung windows. (C)
100. 591-93 Alexander. c. 1940. Colonial Revival Cottage. Beveled wood siding, irregular plan with c. 1970 front addition; asphalt shingle side gable roof, 6/6 double hung windows. (NC due to alterations)
101. 599 Alexander. 1944. Colonial Revival Cottage. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, 2 gable dormers, partial porch with shed roof and paired box column supports. (C)

CENTRAL AVENUE

102. 3259 Central. c. 1930. Tudor Revival Cottage. Uncoursed stone veneer, asphalt shingle jerkin head roof, irregular plan; partial porch with metal pole replacement supports; bay window with a narrow band of single light casement windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 17

East Buntyn Historic District
Shelby County, TN

-
103. 3265 Central. c. 1930 Colonial Revival Cottage. Uncoursed stone veneer, 1.5 story, L-plan, asphalt shingle side gable roof with dormers and multi-gable roof, partial porch with square column supports, classical door surround, 6/1 double hung windows. (C)
104. 3269 Central. c. 1940. Tudor Revival. Uncoursed stone veneer, 1.5 story, asphalt shingle roof, irregular plan; partial porch with stone pier supports; Colonial door surround with broken pediment and paneled walls in the recessed area of the entry, 6/1 windows. (C)
105. 3275 Central. c. 1940. Colonial Revival. Uncoursed stone veneer, 1.5 story, asphalt shingle gable roof, irregular plan; partial incised porch, 6/6 paired windows. (C)
106. 3279 Central. c. 1940. Colonial Revival. Brick veneer, asphalt shingle gable roof, irregular plan; partial porch with brick pier supports; Colonial door surround on front entry, 6/6 paired windows. (C)
107. 3285 Central. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle multi-gable roof, irregular plan; partial porch with wrought iron supports, 6/6 paired windows. (C)
108. 3289 Central. C. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, irregular plan with rear ell addition, partial porch with turned post supports; full pediment in gable dormer end, 6/1 paired windows. (C)
109. 3297 Central. c. 1940. Colonial Revival. Brick veneer, 1.5 story, asphalt shingle gable roof, irregular plan; partial porch, altered porch posts, 6/6 double hung windows, attached garage. (C)
110. 3305 Central. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, irregular plan; centered single bay porch of new construction, 6/1 paired windows. (C)
111. 3319 Central. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, L-plan; 6/6 windows. (C)
112. 3325 Central. c. 1940. Minimal/Traditional. Brick veneer, 1.5 story, asphalt shingle gable roof, L-plan; single bay porch with wrought iron supports, 6/6 sash windows. (C)
113. 3331 Central. c. 1940. Colonial Revival. Brick veneer, 1.5 story, asphalt shingle gable roof, L-plan; 6/6 windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 18

East Buntyn Historic District
Shelby County, TN

-
114. 3341 Central. c. 1925. Bungalow. Brick veneer, 1.5 story, U-plan with symmetrical facade, clay tile hip roof; two wings extend at either side of central tile floor landing or uncovered porch, four French doors with transoms open onto central landing and flank an exterior battered chimney; each hip roof wing is embellished with a band of four arched casement windows with diamond tracery; there are two gable dormers with semi-elliptical casement windows; porte cochere on east elevation has hip roof and triple column on brick pier supports. (C)
- Guest House. c. 1925. Bungalow. Brick veneer, 1 story, rectangular plan; terra cotta tile jerkin head roof, 2 gable dormers with semi-elliptical casement windows, stoop porch, band of full length casement windows on east elevation. (C)
115. 3365 Central. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, U-plan; single bay porch, 8/8 windows. (C)
116. 3373 Central. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, T-plan; single bay porch with wrought iron supports; double hung paired 6/6 windows, side sun porch enclosed. (C)
117. 3379 Central. c. 1940. Minimal/Traditional. Brick veneer, 1.5 story, asphalt shingle gable roof, rectangular plan; single bay porch with knee brace supports; screen porch on east elevation. (C)
118. 3385 Central. c. 1940. Colonial Revival. Brick veneer, 1.5 story, asphalt shingle gable roof, rectangular plan; stoop porch, 6/6 paired windows. (C)
119. 3391 Central. c. 1940. Colonial Revival. Brick veneer, 1.5 story, asphalt shingle gable roof, U-plan; gable eaves on either side of central porch, cast iron lintels, double hung 8/8 windows. (C)
120. 3411 Central. c. 1940. Colonial Revival. Brick veneer, 1.5 story, asphalt shingle gable roof, L-plan; partial porch with classical column supports; broken pediment with finial and dentilated frieze on door lintel, side porch on west elevation. (C)
121. 3419 Central. c. 1940. Minimal/Traditional. Brick veneer, 1.5 story, irregular plan; gable entry porch with wrought iron supports; ancillary sun porch on east elevation, 8/8 double hung windows. (NC due to abusive alterations)
- Garage. c. 1940. Novelty siding, asphalt shingle roof, double bay, overhead door. (C)
122. 3427 Central. 1929. Tudor Revival. Brick veneer lower, half timbering in stucco background above, 2.5 story, irregular plan; asphalt shingle gable roof, shed dormer, gable entry porch, recessed arched entry, solarium on east elevation, 6/6 double hung windows, heavy cast stone window sills. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 19

East Buntyn Historic District
Shelby County, TN

-
123. 3437 Central. 1930. Tudor Revival. Brick veneer first story, weatherboard second story, 2 story, irregular plan; slate look asphalt shingle hip roof with jerkin head cross gables, stoop porch with copper hip roof, batten door with heavy iron hinges, solarium with arched voussoirs and multi-paned French door entries, brick buttresses, 9/9 double hung windows, corbelled chimneys. Brick wall with Art Nouveau style garden entry. (C)

ELLSWORTH STREET

124. 336 Ellsworth. c. 1970. Colonial Revival Cottage. Brick veneer, 1.5 story, asphalt shingle side gable roof, irregular plan with side ell addition, 4/4 double hung windows. (NC)
125. 337 Ellsworth. c. 1935. Tudor Revival. Brick and stone veneer, 2 story, asphalt shingle gable roof with plain projecting eaves and exposed rafters, rectangular plan with 2 side and 1 rear addition constructed from 1950 to 1970, stone veneer wainscoting, single bay porch with shed roof and wrought iron replacement posts, double hung 6/6 Craftsman windows. (NC due to alterations)
126. 347-49 Ellsworth. c. 1925. French Provincial. Brick veneer, 1 story, asphalt shingle hip roof, irregular plan; Chicago style window, 6/6 double hung windows, multiple additions completed around 1950. (NC due to alterations)
127. 359 Ellsworth. c. 1925. Classical Revival. Weatherboard, asphalt shingle side gable roof, rectangular plan; single bay central porch with gable roof and classical column supports; 8/8 windows. (C)
128. 365 Ellsworth. c. 1940. Colonial Revival Cottage. Aluminum siding, asphalt shingle side gable roof, rectangular plan; rear shed addition, stoop porch with wrought iron railing and embellishment on landing, 8/8 double hung windows. (C)
129. 366 Ellsworth. c. 1965. Contemporary. Brick veneer/wood panels, asphalt shingle front gable roof with projecting eaves, single bay central porch with flat roof and square metal posts supports; single stationary lights, attached garage with flat roof and overhead door. (NC)
130. 371 Ellsworth. c. 1940. Colonial Revival Cottage. Weatherboard siding, T-plan; asphalt shingle front gable roof, partial porch with cantilevered roof, frieze with acorn pendants, 8/8 double hung windows with spandrel panels, enclosed attached garage. (C)
131. 374 Ellsworth. 1944. Colonial Revival. Weatherboard siding, asphalt shingle side gable roof, rectangular plan; vestibule entry, Colonial door surround, 6/6 sash windows. (C)
132. 375 Ellsworth. c. 1950. Minimal/Traditional. Brick veneer, 1.5 story, asphalt shingle side gable roof, rectangular plan; 4/4 double hung windows. (NC)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 20

East Buntyn Historic District
Shelby County, TN

-
133. 380-82 Ellsworth. c. 1950. Minimal/Traditional. Brick veneer, 1.5 stories, asphalt shingle side gable roof, irregular plan; front facing gable ell, single bay porch, wrought iron supports; 6/6 windows. (NC)
134. 381 Ellsworth. c. 1940. Colonial Revival Cottage. Brick veneer, 1 story, asphalt shingle side gable roof, rectangular plan; single bay central porch with gable roof and wrought iron replacement posts, 6/6 double hung windows. (C)
135. 384 Ellsworth. c. 1940. Colonial Revival Cottage. Beveled board, 1.5 stories, asphalt shingle side gable roof, rectangular plan; central single bay recessed entry porch with gable roof and wrought iron supports; 2/2 double hung windows. (C)
136. 385 Ellsworth. c. 1950. Colonial Revival Cottage. Brick veneer, 1.5 stories, asphalt shingle side gable roof, L-shaped plan; single bay porch with wrought iron supports; 6/6 double hung windows. (NC)
137. 395 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, L-plan; exposed rafter tails, partial porch with gable roof and brick pier supports; 3/1 windows. (C)
138. 396-98 Ellsworth. c. 1950. Colonial Revival. Duplex. Brick veneer, 1.5 story, asphalt shingle side gable roof, two gable dormers, irregular plan; single bay central gable entry porch, 6/6 double hung windows. (NC)
139. 401 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle front gable roof; partial porch with gable roof, and brick pier supports; 3/1 Craftsman windows. (C)
140. 404 Ellsworth. c. 1950. Colonial Revival Cottage. Brick veneer, 1 story, asphalt shingle side gable roof, single bay porch with gable roof and wrought iron supports; 8/8 double hung windows. (C)
141. 405 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, knee braces, partial porch with brick pier supports; 3/1 double hung paired windows. (C)
- Garage. c.1925. Weatherboard, asphalt shingle front gable roof, single open bay. (C)
142. 411 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle front gable roof, exposed rafters, knee braces; full porch with porte cochere, gable roof and brick pier supports; 1/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 21

East Buntyn Historic District
Shelby County, TN

Vacant Lot

Vacant Lot

143. 415 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, exposed rafters, monitor with side gable roof, knee braces, full porch with porte cochere, gable entry and battered brick pier supports; 6/1 double hung paired windows. (C)
144. 418-20 Ellsworth. 1944. Colonial Revival Cottage. Duplex. Brick veneer, 1 story, asphalt shingle gable roof, stoop, 6/6 double hung windows. (C)
145. 421 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters; knee braces, full porch with porte cochere, gable roof and paired brick pier on stepped balustrade supports; French doors, 6/1 paired Craftsman windows. (C)
146. 424-26 Ellsworth. 1944. Colonial Revival Cottage. Duplex. Asbestos siding, 1 story, rectangular plan; asphalt shingle side gable roof, 6/6 double hung windows. (C)
147. 425 Ellsworth. c. 1940. Colonial Revival Cottage. 1 story, square plan, asphalt shingle side gable roof, partial porch with gable roof and classical column supports; fan light with arched lenticil with keystone in gable end, 1/1 double hung windows. (C)
148. 431 Ellsworth. c. 1940. Colonial Revival Cottage. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with shed roof and box columns, 6/6 windows. (C)
149. 435 Ellsworth. c. 1925. Craftsman Bungalow with Japanese influences. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof with flared eaves, eyebrow dormer; entry porch with gable roof, wrought iron supports; 6/1 Craftsman windows in paired configuration. (C)
150. 441 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, knee braces, full porch, hip roof, stone pier supports; 1/1 double hung windows. (C)
151. 445 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half timber/stucco and casement window in gable end; partial porch with porte cochere, gable roof, stone pier supports; three-quarter side lights around main entry, 6/1 triple Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle side gable monitor roof, overhead door. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 22

East Buntyn Historic District
Shelby County, TN

152. 451 Ellsworth. c. 1925. Tudor Revival. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, half timber/stucco and casement windows in gable ends, boxed cornice, cornice returns, 2 gable dormers, porch with brick battered pier supports; French door entry, side elevation entry porch, 3/1 double hung triple Craftsman windows. (C)

Garage. c. 1940. Cinder block, 1 story, asphalt shingle gable roof, bank of 4 light casement windows, single open bay. (NC due to deteriorated condition.)

153. 461 Ellsworth. c. 1925. Craftsman Bungalow. Vinyl siding, 1 story, rectangular plan; asphalt shingle jerkin head roof, boxed cornice, full porch, hip roof, jerkin head entry and brick pier supports; 1/1 double hung windows. (C)

154. 465 Ellsworth. c. 1925. Craftsman bungalow. Weatherboard, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch, hip roof, and brick pier supports; Craftsman door, 1/1 double hung windows. (C)

155. 471 Ellsworth. c. 1925. Classical Revival Cottage. Weatherboard, rectangular plan; 1 story, asphalt shingle side gable roof, shed dormer, full porch with classical column supports; 2 French door entries, 9/1 double hung windows. (C)

156. 481 Ellsworth. c. 1925. Cottage. Weatherboard, rectangular plan; 1.5 story, asphalt shingle side gable roof, boxed cornice, gable dormer, full porch with porte cochere, shed roof, boxed column supports; 2 front multi-light entries, 1/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle gable roof, 2 open bays. (C)

157. 488-90 Ellsworth. 1944. Minimal/Traditional. Duplex. Brick veneer, 1 story, irregular plan; asphalt shingle side gable roof, 6/6 double hung paired windows. (C)

Garage. 1944. Weatherboard, asphalt shingle gable roof, 2 bay, double hinged doors. (C)

158. 491 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half story monitor with hip roof, full porch with porte cochere, and stone pier supports; three-quarter length sidelights flank main entry, 3/1 double hung windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle jerkin-head roof, exposed rafters, 2 bay, double hinged doors. (C)

159. 494-496 Ellsworth. c. 1940. Duplex. Weatherboard, 1 story, irregular plan; asphalt shingle side gable roof, exposed rafters, stoop porch, Craftsman door, 6/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 23

East Buntyn Historic District
Shelby County, TN

-
160. 500 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, cross gables, exposed rafters, full porch with porte cochere, jerkin head entry, and brick pier supports; three-quarter length sidelights flank main entry, 6/1 double hung paired Craftsman windows. (C)
161. 505 Ellsworth. c. 1935. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half story monitor with gable roof, full porch with porte cochere, hip roof, 3/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle gable roof, 2 bay, 2 double hinged doors. (C)
162. 506 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, paired multi-light casement in gable ends, full porch with porte cochere, brick pier supports; three-quarter length side lights flank main entry, 6/1 double hung windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle gable roof, exposed rafters, entry boarded. (C)
163. 510 Ellsworth. c. 1925. Craftsman Bungalow. Stucco, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable roof, and paired tapered boxed columns on stucco pedestals; 3/1 double hung paired Craftsman windows. (C)
- Garage/workshop. c. 1940. Weatherboard, 2 story, asphalt shingle gable roof, 2 bay, overhead doors. (C)
164. 511 Ellsworth. c. 1925. Craftsman Bungalow. Stucco, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, partial porch with porte cochere, shed roof, off set entry with three-quarter sidelight configuration, 1/1 double hung windows. (C)
- Garage. c. 1940. Beveled wood siding, asphalt shingle gable roof, single bay, double hinged doors. (C)
165. 514 Ellsworth. c. 1925. Craftsman Bungalow. Stucco, 1 story, rectangular plan; asphalt shingle gable roof, knee braces, exposed rafters, partial porch with gable roof and tapered boxed columns on brick pedestal bases, 1/1 double hung triple windows. (C)
- Carport. Recent Construction. Vertical paneling, asphalt shingle hip roof. (NC)
166. 515 Ellsworth. c. 1945. Minimal Traditional with Colonial influence. Brick veneer, 1 story, irregular plan; asphalt shingle side gable roof, 6/6 double hung windows. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 24

East Buntyn Historic District
Shelby County, TN

-
167. 520 Ellsworth. c. 1925. Craftsman. Stucco, 1.5 story, irregular plan; asphalt shingle hip roof, boxed cornice, hip dormer, partial porch with shed roof and wrought iron supports; three-quarter sidelights around main entry, band of 6/1 double hung Craftsman windows. (C)
168. 521 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, knee brace supports; gable dormer, half story monitor, full porch with shed roof and brick pier on pedestal supports; half light sidelight and multi-light transom around main entry, 1/1 double hung triple window. (C)
169. 528 Ellsworth. 1944. Colonial Revival. Weatherboard, 1.5 story, rectangular plan; asphalt shingle gable roof, 2 gable dormers, central entry, 6/6 double hung windows. (C)
- Shed. c. 1970. Weatherboard, asphalt shingle shed roof, single bay. (NC)
170. 531 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer on first story, half timber and stucco on 2nd story, rectangular plan, 2 story, asphalt shingle cross gable roof, sawn knee braces, sawn rafters, full porch with porte cochere, hip roof, brick pier supports; 6/1 double hung windows. (NC due to alterations)
171. 534 Ellsworth. 1940. Tudor Revival Cottage. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, half-timber/stucco in gable ends, exposed rafters, partial porch with brick pier supports; off set entry, 6/1 double hung Craftsman windows. (C)
- Garage. c.1925. Weatherboard, asphalt shingle gable roof, 1 bay, double hinged doors. (C)
172. 540 Ellsworth. c. 1930. Tudor Revival Cottage. Brick veneer, 1.5 story, rectangular plan; asphalt shingle jerkin-head roof, triple leave multi-light entry doors, porte cochere with flat roof and brick pier supports; 6/1 double hung paired Craftsman windows. (C)
173. 541 Ellsworth. c. 1925. Craftsman Cottage. Stucco, 1.5 story, rectangular plan; asphalt shingle gable roof, knee braces, shed dormer, full porch with shed roof and paneled column on stone battered pier supports; three-quarter sidelight configuration and transom around main entry, 6/1 double hung windows. (C)
174. 546 Ellsworth. c. 1930. Tudor Revival Cottage. Brick veneer, 1.5 story, rectangular plan; asphalt shingle jerkinhead roof, multiple cross gables on principal facade, multi-light entry, porte cochere, half story monitor with gable roof; 6/1 double hung Craftsman windows. (C)
175. 550 Ellsworth. 1944. Colonial Revival. Asbestos, 1.5 story, rectangular plan; asphalt shingle side gable roof, 2 gable dormers with 6/1 double hung windows, partial porch with gable roof, cornice returns and paired Corinthian column supports; 6/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 25

East Buntyn Historic District
Shelby County, TN

176. 554 Ellsworth. 1944. Colonial Revival. Asbestos, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with shed roof and wrought iron supports; 8/8 double hung windows. (C)

Garage. c.1940. Beveled wood siding, asphalt shingle gable roof, 1 bay, double hinged doors. (C)

176A. 555 Ellsworth. c. 1925. Craftsman. Stucco, 1.5 story, asphalt shingle side gable roof, knee braces, exposed rafters, partial porch with gable roof and triple columns; transom above main entry, narrow 6/1 windows in triple configuration. (C)

Garage. c. 1955. Board and batten siding, shed roof, overhead door. (NC)

177. 558-560 Ellsworth. 1944. Colonial Revival. Duplex. Asbestos, 1 story, rectangular plan; asphalt shingle side gable roof, 2 entry porches: #1, gable entry with knee brace supports; #2, partial porch with boxed column supports; 6/6 double hung windows. (C)

178. 564-566 Ellsworth. 1944. Colonial Revival. Duplex. Asbestos, 1 story, rectangular plan; asphalt shingle jerkin head roof, 2 bay porch with hip roof and boxed column support. (C)

Garage. 1944. Weatherboard, asphalt shingle shed roof, open single bay. (C)

179. 561 Ellsworth. c. 1925. Craftsman. Asbestos shingle, 1.5 story, asphalt shingle gable roof, gable dormer, wrap around porch with shed roof and stucco column supports; three-quarter sidelight, single light transom, bay window with shed roof, 1/1 double hung triple windows. (C)

180. 567 Ellsworth. c. 1945. Minimal/Traditional. Duplex. Brick veneer, 1 story, asphalt shingle side gable roof, rectangular plan; gable entry porch with wrought iron supports; 6/6 double hung windows. (C)

181. 570 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, boxed cornice, half story monitor with hip roof, full wrap around porch with hip roof and tapered boxed column on brick pedestal supports; 6/1 double hung triple Craftsman windows. (C)

Carport. c. 1970. Beveled wood siding, asphalt shingle gable roof, open bay. (NC)

182. 571 Ellsworth. c. 1925. Craftsman. Weatherboard, 1 story, asphalt shingle front gable roof, shed dormer, knee braces, exposed rafters, full porch with shed roof and boxed column supports; 2 separate French door front entries, 6/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 26

East Buntyn Historic District
Shelby County, TN

183. 574 Ellsworth. c. 1925. Colonial Revival. Brick veneer, 1 story, asphalt shingle side gable roof, partial porch with gable roof and paired classical column supports; 3/1 double hung paired windows. (C)

Garage. c. 1940. Corrugated Fiberglass siding, asphalt shingle gable roof, exposed rafters, single bay, hinged double doors. (NC due to alterations)

184. 575 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half timber/stucco in gable ends, partial porch with brick pier support; 1/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, 1.5 story, rectangular plan; asphalt shingle gable roof, half story monitor, double hinged doors. (C)

185. 581 Ellsworth. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half story monitor, wrap around partial porch with shed roof and brick pier supports; transom, 1/1 triple double hung windows. (C)

GREER STREET

186. 358 Greer. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, irregular plan with side addition of later construction, single bay porch with paired boxed column supports; side carport addition, 6/6 double hung windows. (NC due to alterations)

Guest house. c.1940. Colonial Revival. Aluminum siding, 1 story, asphalt shingle gable roof, square plan; full porch of new construction with metal poles supports. (C)

187. 400 Greer. 1944. Colonial Revival. Wood shingle siding, 1 story, asphalt shingle gable roof, boxed cornice and shaped frieze, T-plan; partial porch with shed roof and boxed column supports; double hung 6/6 windows, Chicago window on principal facade. (C)

188. 406 Greer. c. 1944. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, L-plan with rear ell addition, partial porch with shed roof and sawn brackets at cornice, boxed column porch supports with arched spandrel, gabled ell on principal facade has recessed arch and spandrel panel with bull's eye motif. (C)

189. 410 Greer. 1944. Colonial Revival. Beveled wood siding, 1.5 story, asphalt shingle gable roof, 2 gable dormers, L-plan; Classical door surround, double hung 6/6 windows. (C)

190. 416 Greer. 1944. Colonial Revival. Brick veneer, 1 story, asphalt shingle gable roof, L-plan; stoop porch, 8/8 double hung windows, Chicago style replacement windows on principal facade. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 27

East Buntyn Historic District
Shelby County, TN

-
191. 422 Greer. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle hip roof, square plan with rear shed addition, partial porch with wrought iron posts replacements, 1/1 double hung windows. (C)
192. 426 Greer. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle gable and hip roof, rafter tails, half timbering and purlins in gable ends, rectangular plan; enclosed partial porch with porte cochere; 1/1 double hung windows. (C)
193. 430 Greer. c. 1925. Craftsman Bungalow. Brick veneer, rectangular plan with rear ell addition, asphalt shingle jerkin head roof, exposed rafters, half timbering and purlins in gable ends, partial porch with porte cochere and wrought iron replacement posts. (C)
194. 436 Greer. 1928. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, full porch with porte cochere and brick pier supports; 1/1 double hung windows. (C)
195. 440 Greer. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle jerkin head roof; partial porch with porte cochere, gable roof, gable entry and wrought iron supports; 1/1 double hung windows. (C)
196. 442-444 Greer. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle gable and hip roof, exposed rafters, purlins in gable end, enclosed full porch with porte cochere; 1/1 double hung windows. (C)
197. 450 Greer. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable and hip roof, exposed rafters, half timbering in gable ends, partially enclosed full porch with porte cochere on brick pier supports; 1/1 double hung windows. (C)
198. 460 Greer. 1927. Tudor Revival Cottage. Half timber/stucco, uncoursed stone wainscoting, 1 story, irregular plan; asphalt shingle mansard roof, stoop with gable roof and knee brace supports; crazy entry, 8/8 double hung windows. (C)
199. 464 Greer. 1927. Cottage. Stucco, 1 story, irregular plan; asphalt shingle gable roof, cross gables, shed entry porch with plain posts supports; 6/6 double hung windows. (C)
200. 470 Greer. c. 1940. Colonial Revival. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, dentilated frieze, Colonial door surround, 6/6 double hung paired windows. (C)
- Garage. c. 1930. Weatherboard, asphalt single front gable roof, double hinged doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 28

East Buntyn Historic District
Shelby County, TN

201. 474 Greer. c. 1940. Tudor Revival Cottage. Permastone veneer, 1 story, irregular plan; asphalt shingle side gable roof, cross gables, 6/6 double hung paired windows. (NC due to alterations)

Garage. Recent Construction. Wide weatherboard siding, asphalt shingle front gable roof, overhead door. (NC)

202. 480 Greer. c. 1940. Colonial Revival. Beveled wood siding, 1 story, rectangular plan; asphalt shingle side gable roof, gabled stoop porch with sawn bracket supports; 2/2 double hung paired windows. (C)

Attached Garage. c. 1940. Beveled wood siding, asphalt shingle front gable roof, double hinged door. (C)

203. 490 Greer. c. 1945. Minimal/Traditional. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, cross gables, single bay gable entry porch with wrought iron supports; 1/1 double hung paired windows. (C)

Attached Carport. c. 1945. Asphalt shingle shed roof, single open bay. (C)

204. 496 Greer. 1944. Minimal/Traditional. Brick veneer, story, rectangular plan; asphalt shingle side gable roof, 1 bay gable entry with wrought iron supports; 1/1 double hung paired windows. (C)

Garage. 1944. Weatherboard, asphalt shingle front gable roof, double hinged door. (C)

205. 500 Greer. c. 1940. Tudor Revival Cottage. Brick veneer, 1 story, irregular plan; asphalt shingle cross gable roof, semi-elliptical main entry, 6/6 double hung paired windows. (C)

Garage. c. 1940. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)

206. 506 Greer. c. 1945. Minimal/Traditional. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, cornice returns, stoop; 8/8 double hung windows. (C)

207. 510 Greer. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle hip roof, sawn rafters, partial porch with brick pier supports,; 6/1 double hung paired Craftsman windows. (C)

Garage. c. 1940. Vertical paneling, asphalt shingle front gable roof, open bay. (NC due to alterations)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 29

East Buntyn Historic District
Shelby County, TN

-
208. 514 Greer. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, full porch with mansard roof and brick pier supports; 3/1 double hung paired Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
209. 518-20 Greer. 1927. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, cross gables, stoop porch, 2/2 double hung paired windows. (NC due to alterations)
210. 524 Greer. 1927. Colonial Revival. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with gable roof and brick pier supports; 2/2 double hung paired windows. (C)
211. 528 Greer. 1928. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, sawn rafters, full porch with gable roof, and brick pier support, 1/1 double hung paired windows. (C)
212. 534 Greer. 1928. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, exposed rafters, half timber/stucco in gable ends, full porch with paired gable roof and brick pier supports; 3/1 double hung paired windows. (C)
213. 540-542 Greer. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, half timber/stucco in gable ends, partial porch with mansard roof and brick pier supports; porte cochere on north elevation with side gable roof, 1/1 double hung paired windows. (C)
- Garage. c. 1930. Weatherboard, asphalt shingle front gable roof, 2 bay, double hinged doors. (C)
214. 544-546 Greer. 1928. Craftsman Bungalow. Brick story, asphalt shingle front gable roof, boxed cornice, partial porch with porte cochere, gable roof and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c.1940. Weatherboard, asphalt shingle front gable roof, two port, overhead doors. (C)
215. 550 Greer. 1928. Tudor/Craftsman. Brick veneer, 1.5 story, asphalt shingle side gable roof, boxed cornice, half story monitor, 1/1 double hung paired windows. (NC due to alterations)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 30

East Buntyn Historic District
Shelby County, TN

216. 554 Greer. c. 1920. Brick veneer, 1 story, rectangular plan; asphalt shingle pyramidal hip roof, boxed cornice, wide eaves, partial porch with gable roof and brick pier supports; 1/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, single open bay. (C)

217. 560 Greer. 1928. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle multi-gable roof, exposed rafters, half timber/stucco in gable ends, partial porch with porte cochere, brick pier supports; 1/1 double hung paired windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)

218. 564-566 Greer. 1928. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, sawn rafters, half timber/stucco in gable ends, partial porch with porte cochere, side gable roof, and brick pier supports; bank of 4 1/1 double hung windows. (C)

219. 570-572 Greer. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, sawn rafters, partial porch with porte cochere, jerkin head roof, brick pier supports; 1/1 double hung paired windows. (C)

Garage. c. 1980. Novelty siding, asphalt shingle front gable roof, single overhead door. (NC)

220. 574-576 Greer. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, partial porch with brick pier supports; bank of 4 1/1 double hung windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)

221. 580 Greer. 1927. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, partial porch with shed roof, brick pier supports; 1/1 double hung paired windows. (NC due to abusive alterations)

Garage. 1927. Weatherboard, asphalt shingle gable roof, single open bay. (NC)

222. 584 Greer. 1927. Craftsman. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, partial porch with shed roof, brick pier supports; 1/1 double hung windows. (C)

Garage. 1927. Weatherboard, asphalt shingle gable roof, double hinged doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 31

East Buntyn Historic District
Shelby County, TN

HOLMES STREET

223. 420 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle jerkin head roof, exposed rafters, partial porch with porte cochere, 1/1 double hung windows in paired configuration. (C)
224. 421 Holmes. c. 1935. Tudor Revival. Brick veneer, 1 story, rectangular plan with rear wing addition, asphalt shingle gable roof, exposed rafters, enclosed full porch with brick pier supports; 1/1 double hung windows. (C)
- Rear storage. c. 1970. Novelty siding, 1 story, asphalt shingle gable roof, single bay. (NC)
225. 425 Holmes. c. 1935. Craftsman. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, partial porch with porte cochere on brick pier supports; 1/1 double hung windows. (C)
226. 426 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with brick piers; Craftsman door entry with full sidelights flank main entry, 1/1 double hung paired windows. (C)
227. 430 Holmes. c. 1935. Craftsman/Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, window and half timbering/stucco in gable ends, partial porch with battered pier supports; 1/1 double hung windows. (C)
228. 431 Holmes. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle gable and hip roof, purlins in gable end, full porch with brick pier supports; 1/1 paired double hung windows, multi light door. (C)
229. 434 Holmes. c. 1935. Craftsman. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle jerkin head roof, exposed rafters, partial porch with brick pier supports; 1/1 paired double hung windows. (C)
230. 435 Holmes. c. 1935. Craftsman. Brick veneer, 1 story rectangular plan; asphalt shingle jerkin head gable/rear hip roof, partial porch with porte cochere, 1/1 paired double hung windows. (C)
- Storage Shed. c. 1935. Novelty siding, 1 story, asphalt shingle hip roof. (C)
231. 440 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, 2 gable dormers, exposed rafters, braces in gable ends, single bay porch with pier on pedestal supports; 1-1 horizontal sliding replacement windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 32

East Buntyn Historic District
Shelby County, TN

-
232. 441 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable and hip roof, purlins in gable ends, partial porch with porte cochere, 1/1 paired double hung windows. (C)
- Garage. c. 1925. Weatherboard siding, 1 story, asphalt shingle gable roof, 2 bay, double hinged doors. (C)
233. 444 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle hip roof, exposed rafters, window and half timber/stucco in gable ends, single bay porch with battered pier supports and jerkin head roof, 1/1 paired double hung windows. (C)
234. 445 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle gable and hip roof, exposed rafters, purlins in gable ends, full porch with pier supports and gable entry roof, 1/1 paired double hung windows. (C)
- Garage. c. 1925. Novelty siding, 1 story, asphalt shingle gable roof. (C)
235. 446 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear wing addition, asphalt shingle jerkin head roof, exposed rafters, half timber/stucco and braces in gable ends, single bay porch with pier supports and jerkin head roof, 1/1 paired double hung windows. (C)
236. 451 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle jerkin head roof, exposed rafters, half timbering/stucco and knee braces in gable ends, partial porch with pier supports and jerkin head roof, 6/1 Craftsman windows in triple configuration. (C)
- Garage. c. 1935. weatherboard siding, 1 story, single bay, asphalt shingle gable roof, no door. (C)
237. 460 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, 2 gable dormers, sawn rafters, half timber/stucco in gable ends, gable entry porch with wrought iron supports; 6/1 double hung paired Craftsman windows. (C)
238. 461 Holmes. 1940. Colonial Revival. Aluminum siding, 1 story, irregular plan; asphalt shingle gable roof, gable entry with knee brace supports; 8/8 double hung windows. (C)
239. 464 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, sawn rafters, full porch with porte cochere, gable roof and brick pier supports; three-quarter length sidelights flank main entry, 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 33

East Buntyn Historic District
Shelby County, TN

-
240. 465 Holmes. c. 1940. Colonial Revival. Brick veneer, 1 story, irregular plan; asphalt shingle multi-gable roof, recessed arched entry, batten entry door, uncoursed stone door surround, 6/6 double hung paired windows. (C)
241. 470 Holmes. c. 1960. Ranch. Brick veneer, 1 story, L-plan; asphalt hip roof, entry porch with wrought iron supports; 6/6 double hung windows. (NC)
242. 473 Holmes. c. 1940. Colonial Revival. Weatherboard, 1 story, rectangular plan; asphalt shingle gable roof, shed entry porch, wrought iron replacement supports; 6/6 double hung windows. (C)
243. 474 Holmes. c. 1960. Ranch. Brick veneer, 1 story, L-plan; asphalt shingle hip roof, entry porch with wrought iron supports; off set entry, Chicago window, 6/6 double hung windows. (NC)
244. 480-482 Holmes. c. 1945. Minimal/Traditional. Brick veneer, 1 story, L-plan; asphalt shingle side gable roof, cross gable, shed entry porch with boxed column supports; offset entry, 6/6 double hung paired windows. (C)
245. 481 Holmes. c. 1930. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, sawn rafters, 2 bay gable entry porch with wrought iron supports; bay window, 8/8 double hung windows. (NC due to alterations)
- Shed. c. 1930. Weatherboard, asphalt shingle front gable roof, exposed rafters, single bay. (C)
246. 484-486 Holmes. c. 1945. Minimal/Traditional. Duplex. Brick veneer, 1 story, L-plan; asphalt shingle side gable roof, shed entry porch, offset entry, 6/6 double hung paired windows. (C)
247. 490 Holmes. c. 1935. Classical Revival. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, cornice returns, partial porch with shed roof and paired box column supports; gable ell side addition, 8/8 double hung windows. (C)
- Garage. c. 1935. Weatherboard, asphalt shingle front gable roof, open bay. (C)
248. 491 Holmes. c. 1935. Craftsman/Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle multi-gable roof, exposed rafters, half story monitor with jerkin head roof, full porch with hip roof and battered pier supports; Tudor arches spanning porch piers, 1/1 double hung paired windows. (C)
249. 501 Holmes. c. 1960. Ranch. Brick veneer, rectangular plan; asphalt shingle hip roof, 1 bay porch, 2/2 double hung windows. (NC)
- Carport. c.1960. Weatherboard, asphalt shingle hip roof, open bay. (NC)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 34

East Buntyn Historic District
Shelby County, TN

-
250. 502 Holmes. c. 1940. Colonial Revival. Weather board, 1 story, rectangular plan; asphalt shingle side gable roof, cornice returns, fan light in gable end, partial porch with gable roof and classical column supports; ell addition on south elevation, 6/6 double hung windows. (C)
251. 507 Holmes. 1944. Colonial Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, partial porch with shed roof and boxed column supports; 8/8 double hung windows. (C)
252. 510 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with hip roof, jerkin head entry, brick pier supports; full length sidelights flank main entry, 3/1 double hung triple windows, attached garage. (C)
253. 511 Holmes. 1928. Colonial Revival. Weatherboard, L-plan; asphalt shingle side gable roof, single bay porch; 6/6 double hung paired windows. (C)
254. 514 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with double gable entry porch roof and brick pier supports; full length sidelights flank main entry, 3/1 double hung triple Craftsman windows. (C)
255. 515 Holmes. c. 1930. Colonial Revival. Aluminum, 1 story, L-plan; asphalt shingle side gable roof, gable dormer, gable entry porch with classical column supports; 6/1 double hung paired windows. (C)
- Garage. c.1930. Weatherboard, asphalt shingle front gable roof, 1 bay, double hinged doors. (C)
256. 518 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with brick pier supports; porte cochere on north elevation with gable roof and brick pier supports; full length sidelights flank main entry, 1/1 double hung triple windows. (C)
257. 519-521 Holmes. c. 1935. Duplex. Craftsman/Tudor Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, exposed rafters, half story monitor with hip roof, full porch with hip roof and brick pier supports; Tudor arches span porch piers, 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 35

East Buntyn Historic District
Shelby County, TN

-
258. 524 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with brick pier supports; full sidelights flank main entry, porte cochere on north elevation with gable roof and brick pier supports; 1/1 double hung triple windows. (C)
- Garage. c. 1935. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
259. 525 Holmes. c. 1955. Minimal/Traditional. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, 8/8 double hung windows. (NC)
260. 531 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, jerkin head entry roof with battered brick pier supports; 1/1 double hung paired windows. (C)
261. 532 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere and brick pier supports; three-quarter length sidelights flank main entry, 1/1 double hung triple windows. (C)
- Garage. c. 1935. Beveled wood siding, asphalt shingle hip roof, 2 bay, overhead doors. (C)
262. 534 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere and brick pier supports; 1/1 double hung windows. (C)
263. 535 Holmes. c. 1935. Craftsman Bungalow. Brick bungalow, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, brick pier supports; 1/1 double hung paired windows. (C)
264. 540 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, half story monitor with gable roof, porch with porte cochere, brick pier supports; 1/1 double hung triple windows. (C)
265. 541 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof and jerkin head entry, brick pier supports; three-quarter sidelight flank multi-light entry, 3/1 double hung triple Craftsman windows. (C)
266. 544 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters; full porch, hip roof, brick pier supports; three-quarter length sidelight, 3/1 double hung triple windows. (C)
- Shed. c. 1935. Beveled wood siding, exposed rafters, single bay. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 36

East Buntyn Historic District
Shelby County, TN

-
267. 545 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, partial porch with porte cochere, gable roof and wrought iron supports; 3/1 double hung paired Craftsman windows, attached garage. (C)
268. 550 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, full porch with porte cochere and brick pier supports; three-quarter length sidelights flank multi-light entry, 3/1 double hung triple Craftsman windows. (C)
- Garage. c. 1935. Beveled wood siding, asphalt shingle front gable roof, overhead door. (C)
269. 551 Holmes. c. 1950. Colonial Revival. Aluminum siding, square plan; asphalt shingle gable roof, 1 bay gable entry porch with wrought iron supports; 6/6 double hung windows. (NC)
- Garage. c. 1950. Weatherboard, asphalt shingle front gable roof, overhead door. (NC)
270. 554 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters; full porch with hip roof and brick pier supports; 3/1 double hung triple Craftsman windows. (C)
- Garage. c. 1935. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
271. 555-557 Holmes. 1928. Colonial Revival. Weatherboard, 1 story, square plan; asphalt shingle side gable roof, gable dormers, partial porch with shed roof and wrought iron supports; classical door surround, 8/8 double hung windows. (C)
- Garage. c. 1945. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
272. 560 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof and brick pier supports; 6/1 double hung Craftsman windows. (C)
- Garage. c. 1935. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
273. 561 Holmes. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half timber/stucco in gable ends, partial porch with gable roof and boxed column on pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1930. Beveled wood siding, asphalt shingle front gable roof, 2 bay, overhead doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 37

East Buntyn Historic District
Shelby County, TN

-
274. 564 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch with porte cochere, gable roof and brick pier supports; 6/1 double hung Craftsman windows. (C)
275. 565 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, half timber/stucco in gable ends, exposed rafters, partial porch with gable roof and wrought iron posts on pedestal supports; 1/1 double hung paired windows. (C)
- Garage. c. 1935. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
276. 570 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch with porte cochere and brick pier supports; Craftsman entry door, 1/1 double hung paired windows. (C)
277. 571 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, half timber/stucco in gable ends, exposed rafters, full porch with hip roof, gable entry, three-quarter length sidelights flank multi-light entry door, 1/1 double hung paired windows. (C)
- Garage. c. 1935. Beveled wood siding, asphalt shingle front gable roof, double hinged doors. (C)
278. 574 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable entry, and brick pier supports; Craftsman door, 1/1 double hung paired windows. (C)
279. 575 Holmes. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, half timber/stucco in gable, exposed rafters, full porch, gable entry, brick piers on pedestal supports; three-quarter length sidelights flank main entry, 1/1 double hung windows. (C)
280. 580 Holmes. 1944. Tudor Revival. Wood shingles, 1 story, rectangular plan; asphalt shingle side gable roof, pedimented entry, uncoursed stone veneer around main entry, 8/8 double hung windows. (C)

HOLMES CIRCLE

281. 380 Holmes Circle. 1942. Colonial Revival. Brick veneer, 1 story, L-plan, asphalt shingle side gable roof with cross gable ell, entry porch with hip roof and wrought iron supports; bay windows and 8/8 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 38

East Buntyn Historic District
Shelby County, TN

-
282. 381 Holmes Circle. 1941. Colonial Revival. Brick veneer, 1.5 story, rectangular plan, asphalt shingle side gable roof, 2 gable dormers, arched entry porch with wrought iron supports; 8/8 double hung windows. (C)
283. 382 Holmes Circle. 1944. Colonial Revival. Brick veneer, 1 story, rectangular plan, asphalt shingle side gable roof, 8/8 double hung windows. (C)
284. 384 Holmes. 1942. Colonial Revival. Aluminum siding, 1 story, L-plan, asphalt shingle side gable roof, cross gable ell, porch with plain posts supports; 8/8 double hung windows, attached garage. (C)
285. 385 Holmes Circle. 1944. Colonial Revival. Brick veneer, 1 story, rectangular plan, asphalt shingle side gable roof, arched entry porch with wrought iron supports; recessed entry, 8/8 double hung windows. (C)
286. 386 Holmes Circle. 1942. Minimal/Traditional. Brick veneer, 1 story, L--plan, asphalt shingle side gable roof, fan light in gable end, 8/8 double hung windows, attached garage. (C)
287. 388 Holmes Circle. 1942. Colonial Revival. Aluminum siding, 1.5 story, rectangular plan, asphalt shingle side gable roof, 2 gable dormers, 1 bay porch with wrought iron supports; off set entry, 8/8 double hung windows. (C)
288. 389 Holmes Circle. 1942. Ranch. Brick veneer, 1 story, rectangular plan, asphalt shingle hip roof, recessed entry, 6/6 double hung windows. (C)
289. 390 Holmes Circle. 1941. Colonial Revival. Brick veneer, 1 story, irregular plan, asphalt shingle side gable roof, cross gable ell, partial porch with shed roof and wrought iron supports; off set entry, 6/6 double hung paired windows. (C)
290. 391 Holmes Circle. 1944. Colonial Revival. Weatherboard, 1 story, rectangular plan, asphalt shingle side gable roof, 1 bay porch with gable entry and plain square column supports; 8/8 double hung windows. (C)
291. 392 Holmes Circle. 1942. Colonial Revival. Brick veneer, 1 story, irregular plan, asphalt shingle side gable roof, frieze with triglyph mold, bay window, 6/6 double hung windows. (C)
292. 394 Holmes Circle. 1941. Ranch. Weatherboard, 1 story, irregular plan, asphalt shingle hip roof, single bay recessed entry, 8/8 double hung windows, attached garage. (C)
293. 395 Holmes Circle. 1942. Colonial Revival. Beveled board siding, 1 story, asphalt shingle front gable roof, partial porch with hip roof and plain posts supports; bay window, 8/8 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 39

East Buntyn Historic District
Shelby County, TN

-
294. 396 Holmes Circle. 1944. Colonial Revival. Brick veneer, 1 story, square plan, asphalt shingle side gable roof, dentilated frieze, 1 bay central porch with flat roof and boxed column supports; classical door surround, 8/8 double hung windows. (C)
295. 398 Holmes Circle. 1945. Colonial Revival. Brick veneer, rectangular plan, 1 story, asphalt shingle front gable roof, bank of 6/6 double hung windows. (C)
296. 399 Homes Circle. 1944. Colonial Revival. Wood shingle siding, 1 story, rectangular plan, asphalt shingle side gable roof, entry porch with plain posts supports; off set entry, 8/8 double hung windows. (C)
297. 400 Holmes Circle. 1942. Tudor Revival. Brick veneer, 1.5 story, asphalt shingle side gable roof, 1 gable dormer, vestibule entry with steeply pitched gable roof with eaves descending to ground level, uncoursed stone veneer entry surround, 6/6 double hung windows. (C)
- Garage. 1942. Beveled wood siding, asphalt shingle front gable roof. (C)
298. 402 Holmes Circle. 1941. Colonial Revival. Weatherboard, 1 story, rectangular plan, asphalt shingle side gable roof, gable roof, partial porch with flat roof and boxed column supports; 6/6 and 8/8 double hung windows. (C)
299. 403 Homes Circle. 1941. Colonial Revival. Brick veneer, 1 story, rectangular plan, asphalt shingle side gable roof, gable entry porch with wrought iron supports; off set entry, 6/6 double hung windows. (C)
- Garage. 1941. Weatherboard, asphalt shingle pyramidal hip roof, double hinged doors. (C)
300. 404 Holmes Circle. 1942. Colonial Revival. Wood shingle siding, 1 story, rectangular plan, asphalt shingle side gable roof, dentilated frieze, partial porch with wrought iron supports; off set entry, 6/6 double hung triple windows. (C)
301. 406 Homes Circle. 1942. Colonial Revival. Brick veneer, 1 story, rectangular plan, 8/8 double hung windows. (NC due to alterations)
- Garage. 1942. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
302. 407 Holmes. 1945. Minimal/Traditional. Brick veneer, 1 story, rectangular plan, asphalt shingle front gable roof, partial porch with wrought iron supports; 6/6 double hung windows, Chicago windows. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 40

East Buntyn Historic District
Shelby County, TN

-
303. 408 Homes Circle. 1942. Colonial Revival. Beveled board siding, 1 story, square plan, asphalt shingle hip roof, gable ell on south elevation, gable entry with wrought iron supports; 6/6 double hung windows. (C)
304. 410 Holmes Circle. 1942. Colonial Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, porch with plain posts supports, Chicago window, 1/1 double hung windows. (C)
305. 411 Holmes Circle. 1942. Colonial Revival. Brick veneer, L- plan with rear shed addition, asphalt shingle gable roof, partial porch with shed roof and wrought iron supports; 8/8 double hung windows, bay window to right of entry. (C)
- Garage. 1942. Weatherboard, 1 story, single bay, hinged double doors. (C)
306. 414 Holmes Circle. 1942. Colonial Revival. Brick veneer, 1 story, L-plan, asphalt shingle gable roof, stoop porch, 6/6 double hung windows, attached garage. (C)
307. 415 Holmes Circle. c. 1940. Colonial Revival. Wood shingle, irregular plan, asphalt shingle gable roof, single bay porch with plain post supports; 8/8 double hung windows. (C)
308. 416 Holmes Circle. 1942. Colonial Revival. Aluminum siding, 1 story, T-plan, asphalt shingle gable roof, partial porch, 8/8 double hung windows. (C)
309. 417 Holmes. c. 1940. Minimal/Traditional. Novelty siding, 1 story, irregular plan; asphalt shingle gable roof, single bay porch; attached garage. (NC due to alterations)
310. 418 Homes Circle. 1944. Colonial Revival. Brick veneer, 1 story, rectangular plan with rear ell addition asphalt shingle gable roof, recessed entry, 8/8 double hung windows. (C)

MIDLAND AVENUE

311. 3350 Midland. c. 1940. Colonial Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with shed roof and classical columns; 5 bays, 6/6 double hung windows. (C)

OVERLAND

312. 3235 Overland. 1927. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, single bay porch with gable roof and plain porch supports; 3/1 double hung paired windows, basket weave patterned water table, louvered front entry, attached garage. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 41

East Buntyn Historic District
Shelby County, TN

-
313. 3239 Overland. c. 1940. Colonial Revival. Shiplap siding, 1 story, rectangular plan, asphalt shingle cross gable roof, vestibule entry, 6/6 double hung paired windows. (C)
314. 3245 Overland. c. 1940. Colonial Revival. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, stoop porch with gable entry, 8/8 double hung windows. (C)
315. 3249 Overland. 1940. Tudor Revival. Weatherboard, 1.5 story, rectangular plan with rear shed addition, asphalt shingle gable roof, 1 gable wall dormer, single bay porch with recessed entry, 6/6 double hung windows. (C)
316. 3250 Overland. 1940. Minimal/Traditional. Weatherboard, 1.5 story, irregular plan; asphalt shingle gable roof, partial porch with wrought iron posts, 6/1 windows. (C)
317. 3253 Overland. c. 1945. Minimal/Traditional. Brick veneer, 1 story, irregular plan; asphalt shingle side gable roof, stoop porch with gable roof and knee brace supports; 6/6 double hung windows. (C)
318. 3256 Overland. 1928. Craftsman. Brick veneer, 1 story, irregular plan; asphalt shingle gable roof, 2 gable wall dormers, single bay porch with iron replacement posts, 1/1 double hung windows. (C)
319. 3259 Overland. c. 1925. Colonial Revival. Weatherboard, 1.5 story, rectangular plan; asphalt shingle side gable roof, eyebrow dormers; central, single bay entry porch with gable roof, full pediment and double boxed column supports; multi-light transom over entry; 6-6 casement windows. (C)
320. 3260 Overland. c. 1930. Colonial Revival. Brick veneer, 1.5 story, L-plan; asphalt shingle gable roof, partial porch with square classical posts and shed roof, 6/6 double hung windows. (C)
321. 3263-65 Overland. c. 1970. Minimal/Traditional. Duplex. Brick veneer, 1 story, square plan; asphalt shingle hip roof, recessed entry with wrought iron supports; 1/1 double hung windows. (NC)
322. 3266 Overland. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, single bay porch with gable roof and classical column supports; 3/1 windows. (C)
323. 3269 Overland. c. 1940. Colonial Revival. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle gable roof, single bay porch with shed roof and wrought iron supports; 6/6 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 42

East Buntyn Historic District
Shelby County, TN

-
324. 3274 Overland. c. 1940. Colonial Revival. Shiplap siding, 1 story, rectangular plan; asphalt shingle side gable roof; central entry with riveted door surround; 6/1 double hung paired windows. (C)
325. 3275 Overland. c. 1940. Colonial Revival. Weatherboard, 1 story, irregular plan, asphalt shingle cross gable roof; recessed entry; 1/1 double hung paired windows. (C)
326. 3279 Overland. c. 1975. French Provincial. Masonite shingle siding, 1.5 story, square plan; asphalt shingle mansard roof, semi-elliptical dormers, single bay porch, stationary window with 42 lights. (NC)
327. 3280 Overland. c. 1940. Colonial Revival. Weatherboard, 1 story, rectangular plan; asphalt shingle gable roof, single bay porch with gable roof and classical square column supports; 6/6 double hung windows in paired configuration. (C)
328. 3285 Overland. 1944. Classical Revival. Weatherboard, 1 story, square plan; asphalt shingle gable roof, exposed rafters, stoop porch, 6/6 double hung paired windows. (C)
329. 3286 Overland. 1926. Craftsman. Weatherboard, 1 story, irregular plan; asphalt shingle gable roof, exposed rafter tails, partial porch with shed roof and wrought iron replacement supports; full sidelights around front entry. (C)
330. 3289 Overland. c. 1940. Colonial Revival. Wood shingle siding, 1.5 story, square plan with rear shed addition, asphalt shingle gable roof, 1 shed dormer, single bay porch with shed roof and wrought iron supports of recent construction, 8/8 double hung windows. (C)

PRESCOTT STREET

331. 327 Prescott. 1926. Tudor Revival. Brick veneer, 1.5 story, L-plan; asphalt shingle cross jerkin head roof, transom over entry door, side porch (added 1990) extends opposite north elevation wing creating asymmetrical facade, 6/6 double hung triple windows. (NC due to abusive alterations)
332. 334 Prescott. c. 1935. Weatherboard, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, gable entry porch with knee brace supports; 4/4 and 6/6 double hung windows. Wing addition: 1984. Contemporary Weatherboard, 2 story, rectangular plan; asphalt shingle salt box roof, exposed rafters, second story cantilevered, 2 story porch, 1/1 double hung paired windows. (NC due to alterations)
333. 335 Prescott. 1944. Colonial Revival. Beveled wood siding, 1 story, square plan; asphalt shingle side gable roof, gable entry with triple boxed column supports; 8/8 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 43

East Buntyn Historic District
Shelby County, TN

-
334. 340 Prescott. c. 1935. Craftsman/Tudor. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half timber/stucco, stoop porch with gable roof, arched entry, enclosed partial porch with gable roof, and brick pier supports; stone rubble exterior other chimney, 1/1 double hung windows. (C)
335. 341 Prescott. c. 1955. Ranch. Brick veneer, 1 story, L-plan; asphalt shingle hip roof, single bay porch, Chicago style window, 2/2 double hung window. (NC)
336. 345 Prescott. c. 1930. Tudor Revival. Brick veneer, 1 story, asphalt shingle side gable roof, single bay porch with gable roof and brick pier supports; exterior other battered chimney, 6/1 double hung windows. (C)
337. 346 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, full porch with porte cochere, hip roof, gable entry, and brick pier supports; 1/1 double hung paired windows. (C)
338. 349-51 Prescott. c. 1925. Tudor Revival. Brick veneer, 1 story, irregular plan; asphalt shingle cross gable roof, single bay porch with shed roof and tapered boxed column supports; 6/1 double hung windows. (C)
- Garage. c. 1970. Vertical board siding, asphalt shingle front gable roof, double open bay. (NC)
339. 350 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half timber/stucco; full porch with porte cochere, hip roof, gable entry, brick pier supports; 1/1 double hung windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, paired hinged doors. (C)
340. 354 Prescott. c. 1940. Minimal/Traditional. Weatherboard, 1 story, irregular plan with rear ell addition, asphalt shingle multi-gable roof, boxed cornice with returns, single bay porch, 6/6 double hung windows. (C)
341. 355 Prescott. 1941. Minimal/Traditional. Brick veneer, 1.5 story, irregular plan; asphalt shingle multi-gable roof, stoop; 2/2 double hung windows, attached garage. (C)
342. 357 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 44

East Buntyn Historic District
Shelby County, TN

-
343. 360 Prescott. c. 1940. Minimal/Traditional. Weatherboard, 1 story, irregular plan; asphalt shingle side gable roof; single bay porch with triple square post corner support, 6/6 double hung paired windows, attached garage. (C)
344. 364 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle front gable roof, exposed rafters, partial porch with gable roof and brick pier supports; 3/1 double hung paired windows. (C)
345. 365 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere and hip roof; three-quarter length sidelights flank main entry, 6/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
346. 370 Prescott. c. 1945. Colonial Revival. Brick veneer, 1.5 story, rectangular plan; asphalt shingle gable roof, single bay porch with gable roof and classical column supports; 9/9 double hung windows. (C)
347. 371 Prescott. c. 1940. Colonial Revival. Brick veneer, 1 story, L-plan; asphalt shingle side gable roof, cross gable ell, shed entry porch with wrought iron supports; 8/8 double hung windows. (C)
348. 374 Prescott. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, partial porch with gable roof and brick piers; 1/4 length sidelights flank main entry, 3/1 double hung paired windows. (C)
349. 375 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, full porch with porte cochere, gable entry, and brick pier supports; 1/1 double hung paired windows. (C)
- Guest House. c. 1950. Aluminum, 1 story, rectangular plan; asphalt shingle front gable roof, three bay, 1/1 double hung windows. (NC)
350. 380 Prescott. c. 1935. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, partial porch with gable roof and brick pier supports; 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 45

East Buntyn Historic District
Shelby County, TN

-
351. 381 Prescott. c. 1940. Colonial Revival. Asbestos shingle, 1 story, L-plan; asphalt shingle side gable roof with cross gable ell, partial porch with shed roof and boxed column, 6/6 double hung paired windows. (C)
- Garage. c. 1940. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
352. 384 Prescott. c. 1925. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, single bay porch with gable roof and arcade porch supports; 12 light main entry, 3/1 double hung triple windows. (C)
353. 387 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with hip roof, gable entry, brick pier supports; 1/1 double hung paired windows. (C)
354. 390 Prescott. c. 1930. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof with cross gables, 3/1 double hung triple windows. (C)
355. 391 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, eyebrow dormers, exposed rafters, full porch with brick pier supports; three-quarter length sidelights flank main entry, 6/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, 2 open bays. (C)
356. 394 Prescott. c. 1930. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, stucco/half timbering in gable ends, single bay porch with gable roof and arched pier supports; 3/1 double hung triple windows. (C)
357. 397 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, T-plan; asphalt shingle pyramidal hip roof, gable entry porch with knee brace supports; three-quarter sidelights flank main entry, 3/1 double hung paired Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, 3/1 double hung paired Craftsman windows. (C)
358. 400 Prescott. c. 1925. Tudor Revival. Brick veneer, 1 story, rectangular plan with rear shed addition, asphalt shingle side gable roof, half timbering/stucco in gable end, partial porch with gable roof and brick pier supports; 3/1 double hung paired windows. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 46

East Buntyn Historic District
Shelby County, TN

-
359. 401 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, eyebrow dormer; single bay central porch with gable roof and brick pier supports; three quarter sidelights flank main entry, 3/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
360. 406 Prescott. c. 1935. Tudor Revival. Brick veneer, 1 story, L-plan; asphalt shingle multi-gable roof, half timbering/stucco in gable ends, partial porch with gable roof and stone battered pier supports; exterior other chimney, 6/1 double hung paired windows. (C)
361. 407 Prescott. c. 1940. Classical Revival. Board siding, 1.5 story, piano box plan; asphalt shingle side gable roof, 2 gable dormers, 2 gable ells flank central porch, partial porch with flat roof and boxed column supports; half length sidelights flank main entry, 6/6 double hung windows. (C)
- Garage/Guest House. c. 1940. Board siding, asphalt shingle hip roof, overhead door, clerestory windows. (C)
362. 414 Prescott. c. 1925. Bungalow. Aluminum siding, 1.5 story, rectangular plan; asphalt shingle side gable roof, 1 gable dormer, full porch with battered pier supports; half light sidelights around main entry, 1/1 double hung windows. (C)
363. 417 Prescott. c. 1925. Craftsman Bungalow. Aluminum, 1 story, rectangular plan; asphalt shingle jerkin head roof, partial porch with gable roof and brick pier supports; three quarter length sidelights flank main entry, 3/1 double hung triple Craftsman windows. (C)
- Garage. c. 1925. Aluminum, asphalt shingle front gable roof, 2 bay, overhead doors. (NC)
364. 420 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, 2 hip dormers, exposed rafter, full porch with hip and gable entry roof and brick piers; 1/1 double hung paired windows. (C)
365. 425 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, sawn rafters, half timber/stucco, full porch with hip roof, gable entry, brick pier supports; 6/1 double hung paired Craftsman windows. (C)
- Carport. c. 1940. Weatherboard, asphalt shingle shed roof, single open bay. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 47

East Buntyn Historic District
Shelby County, TN

-
366. 426 Prescott. c. 1955. Ranch. Brick veneer, L-plan; asphalt shingle hip roof, single bay porch with wrought iron supports; 8/8 double hung windows. (NC)
367. 429 Prescott. c. 1970. Colonial Revival. Brick veneer, 1 story, L-plan; asphalt shingle side gable roof, cross gable ell, incised entry porch, 2/2 double hung windows. (NC)
368. 430 Prescott. c. 1925. Tudor Revival. Brick veneer, 1.5 story, rectangular plan; asphalt shingle multi-gable roof, gable entry with brick pier supports; 6/1 double hung banked windows. (C)
369. 435 Prescott. c. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, sawn brackets, half timber/stucco, partial porch with jerkin head roof, Tudor arch, and battered brick pier supports; one quarter length sidelights flank main entry, 6/1 double hung paired windows. (C)
370. 436 Prescott. c. 1930. Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle hip roof, partial porch with brick pier supports; semi-elliptical main entry, 6/1 double hung paired Craftsman windows. (C)
371. 440 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, sawn rafters, half timbering/stucco in gable ends, partial porch with gable roof and brick piers; 1/1 double hung windows. (C)
372. 441 Prescott. 1941. Minimal/Traditional. Aluminum siding, 1.5 story, irregular plan; asphalt shingle hip roof with multiple cross gables, cornice returns, bay window, 8/8 and 6/6 double hung windows. (C)
- Garage. c. 1945. Weatherboard, asphalt shingle front gable roof, single open bay. (C)
373. 444 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle cross gable roof, exposed rafters, half timbering/stucco in gable ends, stoop porch with gable roof and knee brace supports; 3/1 double hung paired windows. (C)
374. 448 Prescott. c. 1930. Tudor Revival. Brick veneer, 1 story, irregular plan; asphalt shingle multi-gable roof, exposed rafters, half timbering/stucco in gable ends, partial porch with gable roof and brick pier supports; 6/1 double hung paired windows. (C)
375. 449 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof with cross gables, exposed rafters, full porch with porte cochere, gable entry and brick pier supports; three-quarter length sidelights flank main entry, 6/1 double hung paired Craftsman windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 48

East Buntyn Historic District
Shelby County, TN

-
376. 451 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle multi-gable roof, knee braces, full porch with hip roof, gable entry and brick pier supports; three-quarter length sidelights flank main entry, 6/6 double hung paired windows. (C)
377. 458-460 Prescott. 1943. Colonial Revival. Duplex. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof with cross gables, riveted door surround, 8/8 double hung windows. (C)
378. 461 Prescott (Cumberland Presbyterian Church). 1941. Gothic. Uncoursed stone veneer, 1 story, cruciform plan; asphalt shingle cross gable roof, gable end, 2 shed dormers, arched stone entry surround, batten door, stained glass arched transom, multiple 1/1 double hung stained glass windows with matching transoms. (C)
379. 464 Prescott. 1943. Colonial Revival. Duplex. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with gable roof and wrought iron supports; 8/8 double hung windows. (C)
380. 470 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof and battered pier supports; three-quarter length sidelights flank main entry, 3/1 double hung paired Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, exposed rafters, overhead door. (C)
381. 471 Prescott. c. 1925. Craftsman/Tudor. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, half timber/stucco, exposed rafters, full porch with porte cochere and brick battered pier supports; 6/1 double hung paired Craftsman windows. (C)
382. 474 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof with cross gables, exposed rafters, full porch with porte cochere, jerkin head entry, and brick pier supports; 3/1 double hung paired Craftsman windows. (C)
- Tool Shed. c. 1925. Weatherboard, asphalt shingle front gable roof, exposed rafters, single bay, double hinged doors. (C)
383. 475 Prescott. c. 1925. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, half timber/stucco, partial porch with porte cochere, gable roof and brick pier supports; 6/1 double hung paired Craftsman windows. (C)
384. 480 Prescott. 1926. Weatherboard, 1 story, rectangular plan; standing seam gable roof, partial porch with gable roof and plain posts supports; 1/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 49

East Buntyn Historic District
Shelby County, TN

-
385. 481 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, enclosed full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung windows. (C)
386. 484 Prescott. c. 1926. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, half story monitor with hip roof, full porch with porte cochere, hip roof, gable entry, and brick pier supports; three-quarter length sidelights with transom, 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, 2 double hinged doors. (C)
387. 485 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof, brick pier supports; 6/1 double hung paired windows. (C)
388. 490 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung triple windows. (C)
- Garage. c.1950 Aluminum, asphalt shingle front gable roof, overhead door. (NC)
389. 491 Prescott. c. 1940. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle multi-gable roof, half timber/stucco, partial porch with sloping gable roof, 6/1 double hung paired windows. (C)
390. 494 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch, hip roof and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung paired Craftsman windows. (C)
391. 495-97 Prescott. 1944. Minimal/Traditional. Duplex. Brick veneer, 1 story, irregular plan; asphalt shingle side gable roof, 2 entry porches; 6/6 double hung windows. (C)
392. 500 Prescott. 1940. Minimal/Traditional. Brick veneer, 1 story, rectangular plan asphalt shingle side gable roof, central single bay porch with gable roof and brick pier supports; 8/8 double hung windows. (C)
393. 501 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry and brick pier supports; Craftsman door, 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 50

East Buntyn Historic District
Shelby County, TN

-
394. 504-06 Prescott. 1943. Colonial Revival. Duplex. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, riveted door surround, 6/6 double hung windows. (C)
395. 505 Prescott. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half timber/stucco, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)
396. 510 Prescott. c. 1975. Colonial Revival. Brick veneer, 1.5 story, rectangular plan asphalt shingle side gable roof, 6/6 double hung windows. (NC)
397. 511 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere, hip roof, jerkin head entry and brick pier supports; 3/1 double hung triple windows. (C)
398. 512 Prescott. c. 1925. Colonial Revival. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, 2 hip dormers, single bay porch with gable roof and brick pier supports; 4/4 double hung windows. (C)
399. 515 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch, half hip roof, clipped gable entry and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung triple windows. (C)
400. 521 Prescott. c. 1930. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof, gable entry, brick battered pier supports; Craftsman door, 1/1 double hung paired windows. (C)
401. 522 Prescott. 1926. Tudor Revival. Stucco, 1 story, irregular plan; asphalt shingle hip roof, half timber/stucco, arched entry porch with gable roof and solid buttressed wall supports; arched wall niches, solarium on south elevation, stone exterior other chimney with buttressing, 4/4 double hung paired and tripled windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle hip roof, single open bay. (C)
402. 525 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, half timber/stucco, half story monitor with side gable roof, full porch with porte cochere, hip roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)
403. 530 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular, asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere, hip roof and brick battered pier supports; three-quarter length sidelights and transom, 1/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 51

East Buntyn Historic District
Shelby County, TN

-
404. 531 Prescott. c. 1935. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, hip roof with gable entry, and brick pier supports; full length sidelights flank main entry, 2 front entries, 6/1 double hung windows. (C)
405. 534 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof exposed rafters, full porch with porte cochere and brick battered pier supports; three-quarter length sidelights and transom, 1/1 double hung windows. (C)
406. 535 Prescott. c. 1930. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, front facing gable ell, partial porch with wrought iron supports; crazy window, 6/6 double hung paired windows. (C)
407. 540 Prescott. 1926. Tudor Revival. Stucco, 1 story, irregular plan; asphalt shingle hip roof, hip roof dormer, jerkin head ell, shed entry porch of new construction, 4/4 double hung triple windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
408. 541 Prescott. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof, brick battered pier supports; three-quarter length sidelights and transom, 1/1 double hung paired windows. (C)
409. 544 Prescott. 1926. Tudor Revival. Stucco, 1 story, irregular plan; asphalt shingle multi-gable roof, cross gable ell, recessed arched entry, crazy window, 6/6 double hung triple windows. (C)
- Garage. c. 1925. Aluminum, asphalt shingle side gable roof, overhead door. (C)
410. 551 Prescott. c. 1945. Colonial Revival. Weatherboard, 1 story, square plan; asphalt shingle side gable roof, cross gable, classical door surround with fan light transom, 1/1 double hung windows. (C)
411. 550 Prescott. c. 1940. Minimal/Traditional. Weatherboard, 1.5 story, rectangular plan; asphalt shingle side gable roof, shed entry porch with knee brace supports; 6/6 double hung windows, attached garage. (C)
- Greenhouse. c. 1940. Steel frame, glass curtain wall, glass gable roof, side entry. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 52

East Buntyn Historic District
Shelby County, TN

-
412. 555 Prescott. c. 1925. Classical Revival. Weatherboard, 1.5 story, square plan; asphalt shingle side gable roof, knee braces, shed dormer, exposed rafters, full porch with square tapered column supports; porte cochere with flat roof, three-quarter length sidelight with transom, 1/1 double hung paired windows. (C)
413. 560 Prescott. 1940. Colonial Revival. Vinyl siding, 1 story, square plan; asphalt shingle side gable roof, 1 bay central porch with gable roof, and paired boxed column supports; 1/1 double hung windows. (C)
414. 561 Prescott. 1926. Colonial Revival. Buntyn Presbyterian Kindergarten. Formerly Old Sanctuary. Brick construction, brick veneer, irregular plan, asphalt shingle hip roof, leaded stained glass arched double hung 1/1 windows. (NC - due to abusive alterations)
415. 564-66 Prescott. 1944. Colonial Revival. Duplex. Asbestos, square plan; asphalt shingle side gable roof, gable entry porch with louvered panel supports; 8/12 double hung windows. (C)
416. 570 Prescott. 1926. Craftsman Bungalow. Weatherboard, 1.5 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, jerkin head dormer with paired 1/1 double hung windows, partial porch with hip roof and weatherboard clad tapered boxed column supports; 1/1 double hung paired windows. (C)
417. 574-576 Prescott. c. 1965 Ranch. Duplex. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, 2 porch entries with off set entry door and metal pole supports; 1/1 double hung windows with stationary transom windows. (NC)
418. 580 Prescott. 1926. Craftsman Bungalow. Weatherboard, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof and brick pier supports; 1/1 double hung windows. (C)
419. 584 Prescott. 1926. Craftsman Bungalow. Aluminum siding, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with hip roof, gable entry and wrought iron supports; 1/1 double hung windows. (C)
420. 591 Prescott. c. 1955. Colonial Revival. Buntyn Presbyterian Church. Reinforced concrete construction, 1 story, basilica plan; asphalt shingle gable roof, cupola with cross, massive portico with four Doric column supports, gable roof, full pediment; pilasters, classical door surround with arched pediment, five Palladian windows each on east and west elevations. (NC)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 53

East Buntyn Historic District
Shelby County, TN

421. 594 Prescott. 1944. Colonial Revival. Weatherboard, 1 story, T-plan; asphalt shingle hip roof with cross gables, partial porch with gable roof and wrought iron supports; riveted door surround with entablature, 12/12 and 6/6 double hung paired windows. (C)

Garage. c. 1945. Weatherboard, asphalt shingle front gable roof, overhead door. (C)

REESE STREET

422. 330 Reese. 1927. Tudor Revival. Brick veneer, 1.5 story, irregular plan; asphalt shingle cross gable roof, half-timber/stucco and windows in gable ends, stoop porch, rectangular multi-light transom and multi-paned sidelights around main entry, 1/1 double hung paired windows. (C)

423. 336 Reese. 1926. Craftsman. Brick veneer, 1 story, irregular plan; asphalt front shingle gable roof with cross gables, partial porch with shed roof and brick pier supports; 6/1 double hung paired windows. (C)

424. 337 Reese. c. 1955. Contemporary. Vertical paneling, 1 story, rectangular plan; asphalt shingle flat roof, brick wainscoting, 8-8 casement windows. (NC)

425. 340 Reese. c. 1930. Craftsman. Brick veneer, 1.5 story, rectangular plan; asphalt shingle multi-gable roof, partial porch with gable roof and brick pier supports; 3/1 double hung paired windows. (C)

Tool Shed. c. 1930. Weatherboard, asphalt shingle front gable roof, single bay. (C)

426. 345 Reese. 1939. Colonial Revival. Aluminum siding, 1 story, L-plan with rear shed, shingle gable roof, 6/6 double hung paired windows. (C)

Garage. c. 1950. Aluminum, asphalt shingle front gable roof, single open bay. (NC)

427. 346 Reese. c. 1930. Tudor Revival/Craftsman. Brick veneer/stone wainscoting, 1.5 story, irregular plan; asphalt shingle gable roof, half timbering/stucco, 1 gable dormer, 2 hip dormers, stoop porch, bank of 6/1 double hung Craftsman windows. (C)

Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, open bay. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 54

East Buntyn Historic District
Shelby County, TN

-
428. 350 Reese. 1927. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, exposed rafters, half timber/stucco in gable ends, partial porch with gable roof, and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors (C)
429. 351 Reese. c. 1940. Colonial Revival. Aluminum siding, 1 story, irregular plan with rear hip wing, asphalt shingle cross gable roof, stoop porch, 6/6 double hung paired windows. (C)
- Garage. c.1940. Weatherboard, asphalt shingle front gable roof, overhead door. (C)
430. 354 Reese. c. 1940. Colonial Revival. Uncoursed stone, 1 story, L-plan with rear shed, asphalt shingle side gable roof with cross gables, partial incised porch with boxed column supports; 6/1 double hung triple windows. (C)
- Garage. c. 1940. Weatherboard, asphalt shingle front gable roof, exposed rafters, single open bay. (C)
431. 355 Reese. c. 1940. Colonial Revival. Uncoursed stone, 1 story, L-plan; asphalt shingle side gable roof, 1 bay porch with wrought iron supports; 8/8 double hung triple windows. (C)
432. 360 Reese. c. 1940. Colonial Revival. Aluminum siding, 1 story, L-plan, asphalt shingle side gable roof, partial porch with shed roof and wrought iron supports; 6/6 double hung paired windows. (C)
433. 361 Reese. c. 1945. Colonial Revival. Weatherboard, 1 story, L-plan with rear shed addition, asphalt shingle side gable roof, stoop porch, riveted door surrounds with entablature, 6/6 double hung paired windows. (C)
- Garage. c.1940. Beveled wood siding, asphalt shingle front gable roof, double hinged doors. (C)
434. 364 Reese. 1926. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, knee braces and half timbering/stucco in gable ends, full porch with porte cochere, double gable entry roof, and brick pier supports; 1/1 double hung paired windows. (C)
435. 365 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, L-plan with rear ell extension, asphalt shingle front gable roof, exposed rafters, half timbering/stucco in gable ends; partial porch with porte cochere, hip roof and brick pier supports; 1/1 double hung triple windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 55

East Buntyn Historic District
Shelby County, TN

-
436. 370 Reese. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, exposed rafters, partial porch with brick pier supports; 1/1 double hung paired windows. (C)
437. 371 Reese. c. 1940. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere, hip roof with jerkin head entry and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c.1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
438. 374 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with flat w/ hip skirt roof, gable entry and brick pier supports; 1/1 double hung paired windows. (C)
439. 377 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle gable roof, exposed rafters, half timbering stucco in gable ends, partial porch with porte cochere, hip roof with gable entry and brick piers; 1/1 double hung paired windows. (C)
440. 380 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere, gable roof and brick pier supports; 1/1 double hung paired windows. (C)
441. 381 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, eyebrow dormer, exposed rafters, half timbering and stucco in gable ends, full porch with battered pier supports; three- quarter length sidelights flank main entry, 1/1 double hung paired windows. (C)
442. 384 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle front gable roof, exposed rafters, half timber/stucco in gable ends; full porch with porte cochere with hip roof and brick pier supports; 1/1 double hung windows. (C)
443. 387 Reese. 1941. Colonial Revival. Brick veneer, 1.5 story, L-plan, asphalt shingle side gable roof, cross gable ell, partial porch with shed roof and wrought iron supports; 6/6 double hung paired windows. (C)
444. 390 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle jerkin head roof, exposed rafters; full porch with hip roof and brick pier supports; 1/1 double hung windows. (C)
445. 391 Reese. 1925. Craftsman. Weatherboard siding, asphalt shingle hip roof, exposed rafters, stoop porch with shed roof, 1/1 double hung windows. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 56

East Buntyn Historic District
Shelby County, TN

-
446. 394 Reese. 1944. Tudor Revival. Beveled board siding, asphalt shingle side gable roof, steeply pitched gabled vestibule entry, 8/8 double hung windows. (C)
447. 395 Reese. 1944. Colonial Revival. Beveled board siding, asphalt shingle side gable roof, gabled vestibule entry with riveted surround and entablature, 8/8 double hung windows. (C)
- Garage. c.1940. Beveled board siding, asphalt shingle front gable roof, double hinged doors. (C)
448. 400 Reese. 1944. Colonial Revival. Brick veneer, 1 story, square plan; asphalt shingle side gable roof, stoop porch with gable roof and knee brace supports; classical door surround with entablature; 6/6 double hung paired windows. (C)
449. 401 Reese. 1944. Colonial Revival. Vinyl siding, 1 story, rectangular plan; asphalt shingle side gable roof; incised entry porch with plain posts supports and off set entry; 6/6 double hung windows. (C)
450. 404-406 Reese. c. 1945. Minimal/Traditional. Brick veneer, 1.5 story, L-plan, asphalt shingle gable roof, partial porch with wrought iron supports; off set entry, 8/8 double hung windows. (C)
451. 405 Reese. 1940. Tudor. Aluminum, 1.5 story, L-plan; asphalt shingle cross gable roof; partial porch with shed roof and wrought iron supports; bay window, 6/6 double hung windows. (NC due to insensitive renovation)
452. 410 Reese. 1926. Craftsman Bungalow. Weatherboard, 1.5 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof and battered column on pier supports; 1/4 sidelight configuration, 1/1 double hung windows. (C)
453. 411 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan with rear shed addition, asphalt shingle side jerkin head roof, 2 gable dormers, single bay gable entry with battered brick pier supports; full sidelight configuration around main entry, 3/1 double hung paired windows. (C)
454. 414 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, L-plan; asphalt shingle gable roof, full porch with porte cochere, gable roof and brick pier supports; 1/1 double hung triple windows. (C)
455. 415 Reese. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle hip roof, half timber and stucco, full porch with porte cochere, gable roof, and brick pier supports; 1/1 double hug paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 57

East Buntyn Historic District
Shelby County, TN

-
456. 419 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, partial porch with porte cochere, jerkin head roof and brick pier supports; 1/1 double hung paired windows. (C)
457. 420 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle hip roof, exposed rafters, half timbering/stucco, partial porch with gable roof and brick pier supports; 1/1 double hung windows. (C)
458. 424 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan, asphalt shingle jerkin head roof, exposed rafters, half timber and stucco, full enclosed porch with porte cochere and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
459. 425 Reese. 1994. Contemporary. Weatherboard, 1.5 story, irregular plan; asphalt shingle hip roof, 1 bay porch with box posts; 1/1 double hung paired windows. (NC)
460. 430 Reese. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle gable roof, exposed rafters, partial porch with gable roof and brick pier supports; off set entry, 1/1 double hung paired windows. (C)
- Garage. c. 1930. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
461. 431 Reese. 1994. Contemporary. Weatherboard, 1.5 story, irregular plan; asphalt shingle hip roof, 1 bay porch with box posts; 1/1 double hung paired windows. (NC)
462. 434 Reese. c. 1925. Brick veneer, 1 story, L-plan; asphalt shingle gable roof, exposed rafters, half timber/stucco and knee braces in gable ends, partial porch with porte cochere, gable roof and brick pier supports; 1/1 double hung windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
463. 440 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch, hip roof, jerkin head entry and brick pier supports; three-quarter sidelight configuration around main entry, 3/1 double hung triple windows. (C)
- Garage. c. 1925. Beveled wood siding, asphalt shingle front gable roof, double hinged doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 58

East Buntyn Historic District
Shelby County, TN

464. 441 Reese. 1927. Colonial Revival. Asbestos siding, 1 story, rectangular plan; asphalt shingle side gable roof, single bay porch with shed roof and wrought iron replacement supports; 6/6 double hung paired windows. (C)

Tool Shed. c. 1945. Weatherboard, asphalt shingle front gable roof, 2 bay. (C)

465. 444 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan asphalt shingle gable roof, exposed rafters, full porch with porte cochere and brick pier supports; full sidelight configuration around main entry, 3/1 double hung triple windows. (C)

466. 445 Reese. c. 1925. Tudor Revival. Weatherboard, 1 story, irregular plan; asphalt shingle multi-gable roof, recessed semi-elliptical entry, batten door, 1/1 double hung paired windows. (C)

467. 450 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, L-plan; asphalt shingle jerkin head roof, exposed rafters, partial porch, hip roof and brick pier supports; 3/1 double hung triple windows. (C)

468. 451 Reese. c. 1940. Classical Revival. Asbestos siding, .5 story, irregular plan; asphalt shingle gable roof, partial porch with gable roof and paired classical column supports; 8/8 double hung windows. (C)

469. 460-62 Reese. c. 1940. Duplex. Colonial Revival. Brick veneer, 1 story, asphalt shingle side gable roof with cross gables, classical door surround with arched pediment, 8/8 double hung windows. (C)

470. 461 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof, jerkin head entry and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung triple Craftsman windows. (C)

471. 464-66 Reese. 1944. Colonial Revival. Duplex. Brick veneer, 1 story, asphalt shingle side gable roof, enclosed gable entry porch, 8/8 double hung windows. (NC due to abusive alterations)

472. 465-467 Reese. c. 1925. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere, hip roof, jerkin head entry and brick pier supports; 2 entries each with three-quarter length sidelights flanking main entry, 1/1 double hung paired windows. (C)

Garage. c.1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 59

East Buntyn Historic District
Shelby County, TN

-
473. 470 Reese. c. 1925. Tudor Revival. Brick veneer, 1 story, L-plan; asphalt shingle front gable roof, half timber/stucco, front gable ell, partial porch with hip roof and wrought iron supports; porte cochere with gable roof, and brick pier supports; 1/1 double hung paired and triple windows. (C)
- Garage. c. 1925. Stucco, asphalt shingle front gable roof, double hinged doors. (C)
474. 471-73 Reese. c. 1925. Craftsman Bungalow. Duplex. Weatherboard, 1.5 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with hip roof, and tapered boxed column supports; 1/1 double hung windows. (C)
475. 474 Reese. c. 1930. Tudor Revival. Brick veneer, 1 story, L-plan; asphalt shingle front gable roof, front gable ell, partial porch with porte cochere, battered brick pier supports; off set entry, external end chimney, 1/1 double hung paired windows. (C)
- Garage. Recent construction. Novelty siding, asphalt shingle front gable roof, overhead door. (NC)
476. 475 Reese. c. 1925. Craftsman Bungalow. Weatherboard, 1 story, rectangular plan; asphalt shingle front gable roof, full porch, gable entry, and battered brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged door. (C)
477. 479 Reese. c. 1965. Ranch. Brick veneer, 1 story, square plan; asphalt shingle hip roof, entry porch with wrought iron supports; 2/2 double hung triple windows. (NC)
478. 480 Reese. c. 1940. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof with multi-gables, half timber/stucco, partial porch with porte cochere, gable roof and brick pier supports; 1/1 double hung windows. (C)
479. 485 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, single bay porch with gable roof and brick pier supports; porte cochere, 6/1 double hung Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle side pyramidal hip roof, double hinged doors. (C)
480. 486 Reese. c. 1930. Craftsman Bungalow. Brick veneer, 1 story, square plan; asphalt shingle hip roof, half timber/stucco, partial porch with gable roof and brick pier supports; French entry doors, 1/1 double hung windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 60

East Buntyn Historic District
Shelby County, TN

-
481. 490 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, exposed rafters, knee braces, partial porch with gable roof, and brick pier supports; off set entry, 6/1 double hung paired Craftsman windows. (C)
482. 491 Reese. c. 1940. Colonial Revival. Brick veneer, 1.5 story, square plan; asphalt shingle side gable roof, two gables dormers, gable entry porch with wrought iron supports; classical door surround with entablature and broken curved pediment with finial, 6/6 double hung paired windows. (C)
483. 494 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, exposed rafters, hip dormer, full porch with brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c.1925. Weatherboard, asphalt shingle front gable roof, 2 open bays. (C) Party garage shared by 494 and 490 Reese.
484. 495 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, full porch with porte cochere and double brick pier on brick pedestal supports; three-quarter length side lights, 6/1 double hung paired Craftsman windows. (C)
485. 500 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, exposed rafters, gable dormer; full porch with shed roof and brick pier supports; 1/1 double hung paired windows. (C)
486. 501 Reese. c. 1925. Craftsman. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, hexagonal shingles in gable ends, single bay porch with gable roof and brick pier supports; 1/1 double hung paired windows. (C)
487. 505 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side jerkin head roof, exposed rafters, partial porch with jerkin head roof and brick pier supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, single open bay. (C)
488. 506 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, exposed rafters, gable dormer, full porch with shed roof and brick pier supports; 1/1 double hung paired windows. (C)

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 61

East Buntyn Historic District
Shelby County, TN

-
489. 510 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof and brick pier supports; multi-light Colonial entry, gable stoop porch with knee brace supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
490. 511-13 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof and brick pier supports; 1/1 double hung windows. (C)
491. 514 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof and brick pier, supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Vernacular, asphalt shingle front gable roof, double hinged doors. (C)
492. 515 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, partial porch with porte cochere, gable roof and brick pier supports; 1/1 double hung paired windows. (C)
493. 519 Reese. c. 1935. Tudor Revival. Stucco, 1 story, irregular plan; asphalt shingle side gable roof with multi-gable roof and knee brace supports; stoop porch with wrought iron railing, bay window with hip roof, parapet with arched entry and gabled coping appended to north elevation as entry to driveway, 4/1 double hung paired Craftsman windows. (C)
- Garage. c. 1935. Vernacular. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
494. 520 Reese. 1944. Colonial Revival. Brick veneer, 1 story, asphalt shingle side gable roof, classical door surround with pediment, 8/8 double hung windows. (C)
- Shed. c. 1940. Beveled wood siding, asphalt single front gable roof, single bay. (C)
495. 524 Reese. c. 1945. Colonial Revival. Beveled wood siding, 1 story, irregular plan; asphalt shingle front gable roof, off set entry with riveted door surround and scalloped entablature, three-quarter length sidelights flank main entry, 4/4 casement with transom windows, gable wing added on north elevation. (NC due to alterations)
496. 525 Reese. c. 1935. Tudor Revival. Brick veneer, 1 story, irregular plan; asphalt shingle side gable roof with multi-gables, stoop porch with gable roof, 4/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 62

East Buntyn Historic District
Shelby County, TN

-
497. 530 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, asphalt shingle side gable roof, partial porch with jerkin head roof and wrought iron supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Built-up shed roof, plywood siding, single open bay. (NC due to deterioration)
498. 531 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters; partially enclosed full porch with porte cochere and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung paired Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
499. 534 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, asphalt shingle side gable roof, partial porch with jerkin head roof, wrought iron supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Beveled wood siding, asphalt shingle front gable roof, single open bay. (C)
500. 535 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters; partial porch with porte cochere, gable roof and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung Craftsman windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, single open bay. (C)
501. 540 Reese. c. 1990. Brick veneer, 1 story, rectangular plan; asphalt shingle gable roof, partial porch with shed roof and box columns; 6/6 double hung windows. (NC)
502. 541 Reese. c. 1940. Colonial Revival. Brick veneer, 1.5 story, square plan; asphalt shingle side gable roof, gable entry with wrought iron supports; 2/2 double hung windows. (C)
- Garage. c. 1945. Beveled wood siding, double hinged doors. (C)
503. 544 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, knee braces, half story monitor with gable roof, full porch with porte cochere, gable entry and brick pier supports; 1/4 length sidelights flank main entry, 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle hip roof, shingle open bay. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 63

East Buntyn Historic District
Shelby County, TN

-
504. 545 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle side gable roof, jerkin head dormers, sawn rafters, full porch with porte cochere, side gable roof and brick pier supports; three-quarter length sidelights flank main entry, 3/1 double hung paired Craftsman windows. (C)
505. 550 Reese. c. 1940. Tudor Revival. Aluminum siding, 1 story, irregular plan; asphalt shingle side gable roof, entry porch with aluminum shed roof and wrought iron supports; 8/8 double hung windows. (C)
506. 551 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, full porch with porte cochere and hip roof, gable entry and brick pier supports; 1/1 triple double hung windows. (C)
507. 554 Reese. C. 1935. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, exposed rafters, half timber/stucco; partial porch with gable roof and brick pier supports; 1/1 double hung paired windows. (C)
508. 555 Reese. c. 1925. Craftsman. Asbestos, 1 story, rectangular plan; asphalt shingle front gable roof, partial porch with shed roof and boxed column on pedestal supports; one-quarter sidelights flank main entry, 9/1 double hung paired Craftsman windows. (C)
- Garage. c. 1940. Aluminum, asphalt shingle front gable roof, double hinged doors. (C)
509. 560 Reese. c. 1930. Tudor Revival. Brick veneer, 1 story, rectangular plan; asphalt shingle side gable roof, partial porch with gable roof and brick pier supports; 3/1 double hung paired Craftsman windows. (C)
510. 561 Reese. c. 1940. Colonial Revival. Brick veneer, 1 story, asphalt shingle side gable roof; partial porch with flat roof and wrought iron supports; classical door surround with entablature, 6/6 double hung windows. (C)
- Garage. c. 1945. Weatherboard, asphalt shingle front gable roof, exposed rafters, double hinged doors. (C)
511. 564 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, T-plan; asphalt shingle jerkin head roof, jerkin head wing on north elevation, full porch with brick pier supports; 1/1 double hung paired windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 64

East Buntyn Historic District
Shelby County, TN

-
512. 565 Reese. c. 1930. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle front gable roof, partial porch with hip roof and brick pier supports; off set entry, 3/1 double hung paired Craftsman windows. (C)
- Garage. c.1925. Aluminum, asphalt shingle hip roof, exposed rafters, overhead door. (C)
513. 570 Reese. c. 1925. Craftsman Bungalow. Vinyl, 1 story, rectangular plan; asphalt shingle jerkin head roof, full porch, hip roof and triple box columns on pedestal supports; 8/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
514. 571 Reese. c. 1925. Craftsman Bungalow. Weatherboard, 1 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters; full porch with porte cochere, jerkin head entry and boxed column on pedestal supports; 1/1 double hung paired windows. (C)
- Garage. c. 1925. Weatherboard, asphalt shingle hip roof, exposed rafters, single open bay. (C)
515. 574 Reese. c. 1925. Craftsman Bungalow. Vinyl, 1 story, rectangular plan; asphalt shingle jerkin head roof; full porch with hip roof, jerkin head entry and brick pier supports; 8/1 double hung paired Craftsman windows. (C)
516. 575 Reese. c. 1925. Craftsman Bungalow. Vinyl, 1 story, rectangular plan; asphalt shingle front gable roof; glass enclosed full porch with hip roof, gable entry, off set entry, 1/1 double hung paired windows. (NC due to insensitive alterations.)
- Garage. c. 1925. Beveled wood siding, asphalt shingle front gable roof, exposed rafters, double hinged doors. (C)
517. 580-582 Reese. c. 1925. Tudor Revival. Brick veneer, 1 story, square plan; asphalt shingle side gable roof with multi-gables, exposed rafters, half timber/stucco in gable ends, eyebrow dormer, partial porch with gable roof and brick pier porch supports; 6/1 double hung paired windows. (C)
518. 581 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle jerkin head roof, sawn rafters, half story monitor with hip roof, full porch with porte cochere and brick pier supports; 3/1 double hung Craftsman windows. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 7 Page 65

East Buntyn Historic District
Shelby County, TN

-
519. 584 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1 story, rectangular plan; asphalt shingle front gable roof, exposed rafters, knee braces, half timber/stucco in gable ends; full porch with porte cochere and brick pier supports; 1/1 double hung paired windows. (C)
520. 585 Reese. c. 1925. Craftsman Bungalow. Brick veneer, 1.5 story, rectangular plan; asphalt shingle jerkin head roof, exposed rafters, half story monitor with hip roof; full porch with porte cochere, hip roof and brick pier supports; 3/1 double hung windows. (C)
521. 590 Reese. 1944. Colonial Revival. Weatherboard, 1 story, irregular plan; asphalt shingle side gable roof, front gable ell, entry porch with wrought iron supports; side porch, 6/6 double hung paired windows. (C)
- Garage. c. 1940. Weatherboard, asphalt shingle front gable roof, double hinged doors. (C)
522. 591 Reese. c. 1925. Mission Revival. Brick veneer, 1.5 story, rectangular plan; built up flat roof, gabled parapet walls, terra-cotta tile coping, shed stoop porch with knee brace supports; three-quarter length sidelights and transom, porte cochere with gabled parapet, flat roof and brick pier supports. (C)

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 8 Page 66

East Buntyn Historic District
Shelby County, TN

Statement of Significance

The East Buntyn Historic District is being nominated under criterion C for its significance as a cohesive and largely intact collection of 20th century residential architecture embodying the range and diversity of housing prototypes that emerged during the period between 1920 and 1945.

The origins of the district are traced directly to the plantation of Geraldus Buntyn (1791-1865), a veteran of the War of 1812 and an important figure in the development of Memphis and Shelby County. Buntyn, born in North Carolina, was awarded a quarter section land grant in Shelby County for his service to the nation in the War of 1812. The 160-acre grant was bordered on the north by what is now Central Avenue and on the south by what is now Southern Avenue. The western boundary was present day Buntyn Avenue and the eastern boundary was the old Raleigh and Hernando Stage Road, now known as Highland Avenue. After acquiring 520 additional acres, Buntyn established a cotton plantation and by 1835 he had built a large Greek Revival house which stood near present day Goodwyn Road until it burned in 1910.

In 1838, the Memphis and LaGrange railroad reached Buntyn's Plantation, but due to an economic downturn construction of the railroad was not continued beyond Buntyn until 1840. Ante-bellum Buntyn, Tennessee, had a general store, a train stop, and several churches.

Geraldus Buntyn was said to have been overcome with grief at the Confederates' loss of the Civil War; he died in 1865, leaving his estate to his wife, Ann Eliza Buntyn. Three years later, in 1868, Ann Eliza died having arranged for subdivision of the Buntyn property (including the area currently comprising the East Buntyn Historic District) following her death. Unnamed developers registered the Buntyn Subdivision with the Shelby County tax offices in 1868.

The original Buntyn Subdivision extended from Buntyn Avenue on the west, Central Avenue on the north, Raleigh-Hernando Road (now Highland Avenue) on the east, and White's Station-Fort Pickering Road (now Southern Avenue) was the southern boundary with Midland Avenue as an east/west bisector. The current East Buntyn area east of Greer Street was divided into lots of ten acres each. There is no record that any development occurred in the area prior to its 1911 re-subdivision.

The Greek Revival home built by Geraldus Buntyn had a number of owners from 1868 until 1905 when it was purchased by the Memphis Country Club. In 1910, the house was destroyed by fire. Memphis Country Club rebuilt and continues its operation at the same location.

In 1911, during a period of great economic growth and eastward expansion of the city limits, the developers, Commonwealth Realty and Ernest R. Parham Real Estate Company, re-subdivided the eastern part of the Buntyn Subdivision into the Country Club Subdivision. The development of the Country Club

National Park Service
United States Department of the interior

National Register of Historic Places Continuation Sheet

Section number 8 Page 67

East Buntyn Historic District
Shelby County, TN

Subdivision coincided with the opening of the Normal School on Patterson Avenue (now the University of Memphis) and the rebuilding of the Memphis Country Club, two obvious selling points to the new home buyer.

Bounded on the east by the new Normal School, on the south by the Southern Railroad, on the west by the exclusive Memphis Country Club, and on the north by estate properties, the development was marketed as a "restricted residence subdivision," suggesting that this community was protected from the commercial, industrial, and lower-income residential development that had long been considered urban problems.

As part of the 1911 subdivision, the developers added the north/south Alexander, Prescott, Reese, and Peachtree (now Ellsworth) Streets to the grid. Although the grid plan of the Country Club Subdivision reflected a pattern inherited from the earlier tradition of the streetcar suburb, the wide streets of the subdivision suggest that the automobile had supplanted the streetcar as the primary mode of transportation. The increasing reliance on the automobile had many effects on residential planning including mandatory garages, paved roads and cement curbs and gutters. Though the first house in the Country Club Place Subdivision was built in 1919, large scale development did not get off the ground until the City had connected sewer lines in the early 1920s and had made final plans to annex Buntyn in 1929.

From 1926 to 1929 the area experienced its greatest spurt of construction activity. The concentration of the Eclectic movement Craftsman and Revival styles found in East Buntyn attests to the rapid development that occurred during this three-year period, which resulted in a relatively homogenous neighborhood. The Eclectic architecture movement began quietly in the last decades of the nineteenth century and stressed relatively pure copies of the architectural traditions of different European countries and their New World colonies. This early emphasis on period styles was almost overwhelmed by the first wave of architectural modernism, the Craftsman style, during the first two decades of the twentieth century. Although World War I brought an abrupt end to this first phase of the Modern movement nationally, locally the Craftsman bungalow remained an immensely popular style with builders and consumers until the mid-1930s.

Beginning in the 1920s, fashions in domestic architecture shifted toward period or Revival styles such as Colonial, Dutch Colonial, Neoclassical and Tudor Revival. Building technology advanced to allow a thin veneer of stone or brick to be added to a traditional balloon frame house and soon modest cottages, such as those in East Buntyn, began to mimic the masonry facades of Old World landmarks or the masonry construction Colonial homes of the Eastern seaboard.

Unlike the diverse housing stock of the Hein Park Historic District (NR 11-16-88), which is comprised of very expensive homes interspersed with a variety of more modest ones, the homes in the East Buntyn historic district are more uniform in price and style. While Hein Park represented a socially diverse development, East Buntyn represented social and economic homogeneity to the families who invested in

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 8 Page 68

East Buntyn Historic District
Shelby County, TN

the suburban way of life hoping to find both individual freedom and social stability at a time when America was becoming more restrictive and racially exclusive.

Development in the area slowed after the fall of 1929 and by the spring of 1933, 15 million people were out of work and there were 1000 home foreclosures a week. The housing industry was particularly hard hit so Franklin Roosevelt's New Deal government made an effort to rebuild it. The landmark National Housing Act of 1934 established, among other things, the Federal Housing Administration (FHA) to stimulate the moderate cost private-housing market by insuring low-interest, long-term mortgages with a \$20,000 ceiling. At first only expensive houses were insured, but by 1938 most loans were for moderate housing costing between \$6,000 and \$8,000.

These FHA loans were probably the stimulus for the final stage of development in the subdivision in the middle 1930s to the early 1940s. Construction of new homes resumed on the remaining vacant lots in the district and included the creation of Holmes Circle in 1941. Homes constructed after 1939 in East Buntyn, especially on Central Avenue, reflect a continued local preference for the Colonial Revival style. The undying local popularity of this style can be somewhat attributed to a nationally known Memphis architect, J. Frayser Smith, who authored a very influential book about Southern Colonial architecture called White Pillars.

By 1945, 92 percent of the area had been developed. The neighborhood has continued to experience piecemeal development from 1945 to the present. From 1965 to 1975, the neighborhood experienced a number of changes. With the aging of the resident population, there was a gradual decline in the repair of the building stock. The exodus of a number of the original inhabitants and the general flight of people to the newer suburbs was a citywide, indeed a national, phenomenon that also contributed to the decline of the neighborhood.

During the period from 1965 to 1975, the neighborhood remained viable as transient housing for students at Memphis State University. The result is that many of the single-family homes were divided into either duplexes or apartment units.

As the 1970s came to a close, the East Buntyn Historic District experienced a phenomenon common to other areas of the city. Young couples moved into the neighborhoods from which their parents had fled. By 1980, the median age of the neighborhood resident had declined from 55 in 1970 to 38.6. The infusion of new people eager to restore the neighborhood's homes to their former charm has contributed to the stability of a unique collection of homes in the Memphis area.

In addition to East Buntyn, Memphis contains two other areas that contain large numbers of Eclectic Style resources. The Cooper-Young Historic District (NR 6/22/89) and Evergreen Historic District (NR 1/11/85) share an affinity with East Buntyn in terms of 1920-1940s housing styles. However, both of those districts

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 8 Page 69

East Buntyn Historic District
Shelby County, TN

developed from circa 1900 to 1930 and they exhibit an older and more varied housing stock than does the East Buntyn neighborhood with solely Eclectic style houses.

The East Buntyn district is an excellent local example of an Eclectic style suburban residential community of the 1920-1940s, a time of major technological improvements and increased reliance on the automobile. It was developed at a time when the critical problems of the American housing system such as booms and collapses of the real estate market and a tripling of the mortgage rate were redressed with personalized design and uniform planning in residential communities.

From the depths of the Great Depression came the beginning of a new wave of Modernism in architecture that was responsible for the final two historic building styles found in East Buntyn, the Minimal Traditional style and the Ranch style. Although these Modernistic styles remained rare and savant garde locally in the years before World War II, their stylistic descendants would come to dominate the domestic housing market in the decades immediately following World War II. It is the diversity, yet homogeneity of the Eclectic styles and types located here that makes the East Buntyn historic district important and worth preserving.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 9 Page 70

East Buntyn Historic District
Shelby County, TN

Bibliographic References

Fiftieth Anniversary, 1910-1960, Buntyn Presbyterian Church. n.p., n.d.

McAlester, Virginia and Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1986.

Polk, R. L. and Company. Polk's Memphis City Directories. St. Louis: 1900-1950.

Shelby County, TN Will Book #4. Buntyn, Geraldus O. and Ann Eliza Buntyn. Office of the Clerk of the Probate Court, Shelby County Courthouse, Memphis, TN, pp. 177 and pp. 361

Smith, J. Frazer. White Pillars. New York: Bramhall House, 1941.

Tilly, Bette B. A Visit to Buntyn. Memphis: Memphis Inter-Faith Association, 1979.

Wright, Gwendolyn. Building the Dream. New York: Pantheon Books, 1981.

United States Census, 1920-1980.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number 10 Page 71

East Buntyn Historic District
Shelby County, TN

10. GEOGRAPHICAL DATA

Verbal Boundary Description

Bound by Greer Street on the west, Central Avenue on the north, the rear property lines of the eastern side of Ellsworth Street on the east and by the southern property lines of the last contributing structures on the south end of all the streets between Greer and Ellsworth Streets on the south, as outlined in the bold black line on the enclosed Shelby County property tax maps.

Boundary Justification

The boundary of the East Buntyn Historic District includes only those properties historically related to the development of the district.

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number photos Page 72

East Buntyn Historic District
Shelby County, TN

East Buntyn Historic District
Shelby County, Tennessee

Photographs by: Judith Ann Johnson, Historic Preservation Analyst
City of Memphis Housing and Community Development
701 North Main Street
Memphis, TN 38107-2311

Date: January 1995

Negatives: Tennessee Historical Commission
2941 Lebanon Road
Nashville, TN 37214-0442

1 of 22
Ellsworth Street from Midland Avenue, looking northwest

2 of 22
Ellsworth Street from Midland Avenue, looking southwest

3 of 22
Prescott Street from Midland Avenue, looking southwest

4 of 22
Prescott Street From midland Avenue, looking northeast

5 of 24
Reese Street from Midland Avenue, looking northwest

6 of 22
Reese Street from Midland Avenue, looking northeast

7 of 22
Holmes Circle, looking northeast

8 of 22
Holmes Circle, looking northwest

9 of 22
Overland Place, looking southwest

10 of 22
Overland Place, looking northwest

11 of 22
Central Avenue, looking southeast from 3259 Central

National Park Service
United States Department of the Interior

National Register of Historic Places Continuation Sheet

Section number photos Page 73

East Buntyn Historic District
Shelby County, TN

12 of 22

Central Avenue , looking southwest from 3341 Central

13 of 22

Reese Street from Central Avenue, looking Southeast

14 of 22

Central Avenue from Prescott Street, looking southwest

15 of 22

Central Avenue from Ellsworth Street, looking southwest

16 of 22

Holmes Circle from Greer Street, looking southeast

17 of 22

Greer Street from Holmes Circle, looking southeast

18 of 22

Holmes Street from Midland Avenue, looking northwest

19 of 22

Ellsworth from Southern Avenue, looking northwest

20 of 22

Elsworth Street from Southern Avenue, looking northeast

21 of 22

Reese Street from Southern Avenue, looking northwest

22 of 22

Reese Street from Southern Avenue, looking northeast