



ALNWICK HALL/Photo #1/July 1984

Morris Twp., Morris Cty., N.J.

View looking South

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #2/July 1984

Morris Twp., Morris Cty., N.J.

View looking Northwest

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #3/July 1984

Morris Twp., Morris Cty., N.J.

View looking Southeast

Negative:

Specialized Photodesign

346 Main Street

Chatham, New Jersey 07928



ALNWICK HALL/Photo #4/July 1984

Morris Twp., Morris Cty., N.J.

View looking Northwest (Service wing)

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #5/July 1984

Morris Twp., Morris Cty., N.J.

View looking Northeast (juncture of service wing at right with main block of house; under construction is new vestibule)

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #6/July 1984

Morris Twp., Morris Cty., N.J.

View looking East

Negative:

Specialized Photodesign

200 Main Street

Chatham, New Jersey 07928



ALNWICK HALL/Photo #7/July 1984

Morris Twp., Morris Cty., N.J.

Stair Hall

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #8/July 1984

Morris Twp., Morris Cty., N.J.

Stair Hall Detail: Ceiling

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #9/July 1984
Morris Twp., Morris Cty., N.J.
Stair Hall Detail: Sconce
Negative:
Specialized Photodesign
346 Main Street
Chatham, N.J. 07928



ALNWICK HALL/Photo #10/July 1984

Morris Twp., Morris Cty., N.J.

Great Hall, insertion of intermediate-
level floor

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #11/July 1984

Morris Twp., Morris Cty., N.J.

Louis XVI Room, detail of mantel & ceiling

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #12/July 1984

Morris Twp., Morris Cty., N.J.

Louis XVI Room, doors to Great Hall

Negative :

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #13/July 1984

Morris Twp., Morris Cty., N.J.

Adam Room (note ceiling reflected in mirror)

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #14/July 1984

Morris Twp., Morris Cty., N.J.

Dining Room Detail: Wainscot

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #15/July 1984

Morris Twp., Morris Cty, N.J.

Library (note cornice detail & bookcase
in right corner)

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928



ALNWICK HALL/Photo #16/July 1984

Morris Twp., Morris Cty., N.J.

Mrs. Meany's Suite, mantel wall

Negative:

Specialized Photodesign

346 Main Street

Chatham, N.J. 07928