United States Department of the Interior National Park Service

National Register of Historic Places **Inventory—Nomination Form**

See instructions in How to Complete National Register Forms Type all entries—complete applicable sections

Name

historic /Jacob Schunk / Farmhouse

N/A and/or common

Location

N104 W15446 Donges Bay Read, street & number

Germantown city, town VIC,

state

4.

code

vicinity of

county

55

Washington

Present Use

agriculture

commercial

educational

government

industrial

military

entertainment

131 code

not for publication

museum

religious

scientific

other:

X private residence

transportation

park

3. Classification

Wisconsin

Category	Ownership	Status
district	public	_X_ occupied
district _X buildIng(s)	X private	unoccupi
structure	both	work in p
site	Public Acquisition	Accessible
object	in process	yes: restr
	being considered	<u>X</u> yes: unre

work in progress
Accessible
yes: restricted
<u>X</u> yes: unrestricted
no
-

_ unoccupied

X N/A **Owner of Property**

name Francis and Carlyn Rott

street & number N104 W15446 Donges Bay Road

city, town Germantown vicinity of

state Wisconsin 53022

1.1.1.1.1.1

_ federal __X_ state _

Location of Legal Description 5,

Washington County Courthouse courthouse, registry of deeds, etc.

street & number 432 East Washington Street

West Bend city, town

Representation in Existing Surveys 6,

title Wisconsin Inventory of Historic Place shas this property been determined eligible? yes <u>X</u> no

1977 date

depository for survey records State Historical Society of Wisconsin

Madison city, town

Wisconsin 53706 state

__ county _

_ local

Wisconsin 53095 state

OMB NO. 1024-0018 EXP. 12/31/84

983

7. Description

Cond	ition

<u> </u>	deteriorated	unaltered
good	ruins	_X_ altered
fair	unexposed	

Check one __X_ original site ____ moved date .

Describe the present and original (if known) physical appearance

Check one

With an addition in 1870 made to the original 1858 house, the Jacob Schunk farmhouse acquired a T-shaped form. The original two-story, gable-front building of limestone rubble faces south, and is intersected by the two-story stone (lower story) and clapboard (upper) addition. Simple wood sills and lintels frame the double-hung windows in both portions: three per story on the front gable end, two per story on the rear and east gable ends, and four per story on the west side elevation. Wide wood entablatures underline the horizontal roof cornices, and wood fascias trim the raking cornices in the gable ends. Quarter-round windows light the peaks of the front (south) and side (east) gable ends. Unrelated to the house in period and materials, the three outbuildings (chicken coop, garage, and pumphouse) on the property are not included in the nomination.

The single-door entrance at the east end of the original gable end is recessed, and framed by sidelights and transom. Doors in the front and rear of the intersecting wing are undecorated. Simple square columns span the open porch in the front of the wing. Of the four red brick interior chimneys (two per ridge) on the roof, only that over the front gable end is possibly original. The roof is currently covered with composition shingles, and clapboards on the addition were renewed in 1977. A lean-to summer kitchen appended to the rear wall was removed sometime before 1940, but was replaced in 1982 with a board-andbatten version; this new addition is not considered significant.

Although the current use and general disposition of rooms in the interior resembles patterns of use in the nineteenth century, sizes have been altered by removal or slight shifting of walls. (The most significant change has been conversion of the original kitchen and a bedroom, both at the rear of the original house, to use as a family room. A second kitchen, included in the 1870 wing which served the household of the son of the original owner, is now the kitchen of the single-family residence.) The front hall and stair against the east wall of the original section remain as original, with a (painted) wood balustrade and stained newel guarding the single flight of stairs. The living room on the first story, and bedrooms (and baths) on second, parallel nineteenth-century uses, although the sizes of rooms have been changed. Due to comprehensive remodeling in the mid to recent twentieth century, only the stair and painted plaster outside wall surfaces and openings can be considered representative of the historic interior of the 1857-70 era.

Although the original farm property has been subdivided among various owners, tillage of the land to the rear (north) of the house recalls the historic qualities of the site. The area is still largely rural in feeling, but tract housing and light industrial development are visible from the site.

8. Significance



Statement of Significance (in one paragraph)

The Jacob Schunk farmhouse is one of a number of Greek Revival and/or stone buildings in southern Washington County, corresponding in time and form to characteristic construction of German settlers in southeastern Wisconsin. Among buildings of the same period or method of construction in the area, the house is distinguished by its broad proportions, handsome coursed rubble walls with simple articulation, and its fine state of preservation.

Originally the single-family dwelling of German immigrant³ Jacob Schunk, the house grew to its present form in 1870 with the addition of a stone-and-clapboard side wing for the second generation of the family. Both the added east gable end and original south gable end are decorated with Greek Revival-era quarter-round windows and "capitals" marking the termination of wood entablatures on the side walls. A reconnaisance survey of 1977 identified a substantial number of surviving Greek Revival and variously-constructed stone buildings in the Germantown area and beyond, remnants of German and Yankee settlement in the early to mid nineteenth-century in Wisconsin. German-born Schunk and his New York-born wife' thus represented both points of origin when they arrived in Germantown in 1841, in the 1840-43 period of principal settlement of the area.⁴ The farmer Schunks retained title to the house and its eighty acres of land until the property was divided and sold in 1924, since which the house has passed through several owners.

Recent inspection suggests that increasing development threatens the historic feeling of the rural areas surrounding metropolitan Milwaukee, including the Germantown vicinity. Given that several formerly-significant buildings have been neglected or recently altered, and that tract housing and industrial parks are common sights in the area, the efforts of the present and previous owners of the Jacob Schunk house to maintain the property are noteworthy, and the significance of the house as a survivor of its type may well increase.

² Cornerstone, 1870 addition.

⁵ Abstract of title.

¹ Tax Rolls, Washington County, Courthouse, West Bend, Wisconsin.

³ Washington County census records, 1850, State Historical Society of Wisconsin, Madison.

⁴ Western Historical Company, <u>History of Washington and Ozaukee Counties</u>, Wisconsin, 1881, p. 323.

9. Major Bibliographical References

÷

<u>History of Washington and Ozaukee Counties</u>, <u>Wisconsin</u>; Western Historical Company, Chicago, 1881.

10. Geograph	ical Data				
Acreage of nominated property	less than one				
Quadrangle name Menomonee	Falls, Wisconsin		Quadrangle scale <u>1:24,000</u>		
UMT References					
	4 7 8 4 1 5 0 iorthing	B Zone Eas	sting Northing		
		⊳ <u>∟</u> 」 [_]			
ε		F L L_			
GLI LIIII		Halling			
Verbal boundary description	and justification		44.12C - 23 - 24		
see continuation she	et	.	a ta a a construction de la constru La construction de la construction d		
List all states and counties for properties overlapping state or county boundaries					
state	code	county	code		
state	code	county	code		
11. Form Prep	pared By				
name/title Diane H. Filip	owicz/Architectura	l Historian	(Continued)		
State III should					
organization State Historic	cal Society of Wise	consin date	June 1983		
street & number 816 State	e Street	teleph	one 608/262-2732		
city or town Madison		state	Wisconsin 53706		
12. State Hist	oric Prese	vation Of	ficer Certification		
The evaluated significance of thi	s property within the stat	e is:			
national	<u>stateX</u>	. local			
As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89– 665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.					
State Historic Preservation Offic	er signature	Hun			
title Director, Historic 1	Preservation Divis	/ lon, SHSW	date Øov. (, 1983		
For NPS use only					
I hereby certify that this pr	operty is included in the t		1. 1		
Allous Byen		tional In the	date 12/8/8.3		
Keeper of the National Regis	ter				
Attest:			date		
Chief of Registration					

5

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

Jacob Schunk Farmhouse, Germantown, Washington County, Wisconsin Continuation sheet Item number 10, 11

10. Verbal Boundary Description:

In the west one-half of the SW quarter of Section 26, Township 9N, Range 20E, in the County of Washington and State of Wisconsin; commencing at a point on the S line of said $\frac{1}{4}$ section, 440.00 feet N 88 27'16" E on the southwest corner of said $\frac{1}{4}$ section; thence N 88 27'16" E along the south line of said $\frac{1}{4}$ section, 150 feet; thence N 1 29' 37" W, parallel with the west line of said $\frac{1}{4}$ section, 200 feet; thence S 88 27'16" W, parallel with the south line of said $\frac{1}{4}$ section, 150 feet; thence S 1 29'37" E, parallel with the west line of said $\frac{1}{4}$ section 200 feet to the point of the beginning, excepting from the S 33.00 feet for public street purposes.

11. Form Prepared By:

Research Assistance By:

Francis and Carlyn Rott N104 W15446 Donges Bay Road Germantown June, 1981 414/255-1692 Wisconsin 53022

