



The Hersey-Duncan House (N-1244)

Wilmington, vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation,

15 The Green, Dover,

Delaware 19901

Camera Facing Northwest

1 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and
Historic Preservation

15 The Green, Dover,

Delaware, 19901

Camera Facing West

2 of 10



The Hawley Park Farm House, 10000th Street,
Wilmington, Delaware.

Photographed by Alice Smith
November, 1930

Location of photograph is Delaware
Road at Arrington, Del.

Location of photograph
is The Green River

Wilmington, Delaware

Location of photograph
is at

Wilmington



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation

15 The Green, Dover,

Delaware, 19901

Detail of Stairs and Newel Post

4 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Anne Wilson

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation

15 The Green, Dover,

Delaware, 19901

Detail of Fireplace Mantel in Parlor

5 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation

15 The Green, Dover,

Delaware, 19901

Fireplace Mantel and Built-in Cupboard

in Dining Room

6 of 10



The Hersey-Duncan House (N-1244)

New Castle Co

Wilmington Vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation

15 The Green, Dover,

Delaware, 19901

Detail Fireplace in Rear Kitchen Wing First Floor

7 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Valerie Cesna

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation


15 The Green, Dover,

Delaware, 19901

Fireplace Mantel and Closet Door in

Chamber above Dining Room

8 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Anne Wilson

November, 1989

Location of Negative: Delaware

Bureau of Archaeology and

Historic Preservation


15 The Green, Dover,

Delaware, 19901

Smokehouse Facade: Camera

Facing Northwest

9 of 10



The Hersey-Duncan House (N-1244)

Wilmington Vicinity, Delaware

Photographer: Anne Wilson

November, 1989

Location of F Negative: Delaware

Bureau of Archaeology and

Historic Preservation

15 The Green, Dover,

Delaware, 19901

Side of Garage: Camera

Facing North

10 of 10