



G.L. Stocker Blacksmith Shop
Photo No. 1

Potter Co. South Dakota

Photographer Mark Hufstetter

Date August 12, 1995

Negatives located at South Dakota State Historic Preservation Office Pierre SD

primary elevation (east) view facing west north west



G. L. Stocker Blacksmith shop
Photo No. 2

Potter Co. South Dakota

Photographer Mark Hufstetter

Date Aug 12, 1995

Negatives located at South Dakota State Historic Preservation office Pierre SD

east and north elevations view facing southwest



G. L. Stocker Blacksmith Shop

Potter Co , South Dakota

Photo No. 3

Photographer Mark Hufstetter

Date Aug 12, 1995

Negatives located at South Dakota State Historic Preservation Office Pierre SD

North and West elevations view facing southeast



G. L. Stocker Blacksmith shop
Photo No. 4

Potter Co. South Dakota

Photographer Mark Hufstetler
Date: Aug 12, 1995

Negatives located at South Dakota State Historic Preservation Office Pierre SD
west elevation view facing east