



Photograph No. 1

FARMINGTON CANAL LOCK NO. 13

Hamden, Connecticut

Michael S. Raber June 23, 1981

Negative: Connecticut Historical Commission

Farmington Canal Lock 13, looking south.
Stone headers which separated masonry from
wooden lock walls in the original structure
are visible along both walls.



Photograph No. 2

FARMINGTON CANAL LOCK NO. 13

Hamden, Connecticut

Michael S. Raber June 23, 1981

Negative: Connecticut Historical Commission

Farmington Canal Lock 13, looking north.

Stone headers which separated masonry from wooden lock walls in the original structure are visible at left and in center. Later wall added across the lock is in foreground.



Photograph No. 3
FARMINGTON CANAL LOCK NO. 13
Hamden, Connecticut

Michael S. Raber June 23, 1981
Negative: Connecticut Historical Commission

Intersection of underground channel and
Farmington Canal Lock 13, looking west. The
masonry wall crossing the lock is at left;
different block sizes between the two layers
of this wall are visible, suggesting two periods
of construction for the cross wall. One of the
stone headers which separated the masonry lock
walls from the original wooden lock chamber is
at right center.