



Robarge, John B. Duplex  
Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: January 2005

Negative filed at Vermont Division for Historic Preservation

Description: Looking northeast: Streetscape, east side of  
North Champlain Street

Photograph #1



Robarge, John B. Duplex

Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking southeast: Primary (west) and north facades

Photograph #2



Robarge, John B. Duplex  
Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking northeast: Primary (west) and south facades.

Photograph # 2b



Robarge, John B. Duplex

Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: January 2005

Negative filed at Vermont Division for Historic Preservation

Description: Looking west; Rear (east) and north facades

Photograph #3





Robarge, John B. Duplex  
Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking west; Rear (east) and south facades

Photograph # 3b



Robarge, John B. Duplex  
Burlington, Chittenden County, Vermont  
Credit: Rebecca A. Williams  
Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking northeast; Porch, bay, window; and door details

Photograph #4



Robarge, John B. Duplex

Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking west: Interior, 2nd floor, north apartment

Photograph #5



Robarge, John B. Duplex

Burlington, Chittenden County, Vermont

Credit: Rebecca A. Williams

Date: November 2004

Negative filed at Vermont Division for Historic Preservation

Description: Looking west; Interior, 2<sup>nd</sup> floor, north apartment,  
window muntin detail

photograph #6