



LUKE JILLSON HOUSE
Cumberland, Rhode Island

Photographer: Warren Jagger

Date: January 1982

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

Exterior view facing west.

Photo #1.



LUKE JILLSON HOUSE
Cumberland, Rhode Island

Photographer: Warren Jagger

Date: January 1982

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

Exterior view facing northeast.

Photo #2.



LUKE JILLSON HOUSE
Cumberland, Rhode Island

Photographer: Warren Jagger
Date: January 1982
Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View of staircase in center hall.

Photo #3.



LUKE JILLSON HOUSE
Cumberland, Rhode Island

Photographer: Warren Jagger

Date: January 1982

Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI

View of fireplace in southeast parlor.

Photo #4.




LUKE JILLSON HOSUE
Cumberland, Rhode Island

Photographer: Warren Jagger
Date: January 1982
Negative filed at: Rhode Island Historical
Preservation Commission
150 Benefit Street
Providence, RI.

View of fireplace wall in the library.

Photo #5.



Luke Jillson House

2510 Mendon Road
Cumberland , Rhode Island

Sketch plan—not to scale

