

John Arnold House 99 Providence Street Woonsocket, Rhode Island

Warren Jagger, Photographer March 1981 Negative: Rhode Island Historical Preservation Commission

General view from the east.

Figure 82



John Arnold House 99 Providence Street Woonsocket, Rhode Island

Warren Jagger, Photographer March 1981 Negative: Rhode Island Historical Preservation Commission

Interior: second-story southwest room showing heavy timber framing and late-Victorian alterations, most noteably the elaboration of the fireplace.

Figure 84



John Arnold House 99 Providence Street Woonsocket, Rhode Island

Warren Jagger, Photographer March 1981 Negative: Rhode Island Historical Preservation Commission

Interior: detail of corner cupboard in the firststory northeast room.

Figure 85