



88-A-159

South Windham Village Historic  
District  
Windham, Vermont  
Credit: David Tansey  
Date: July 1988  
Negative filed at Vermont Division  
for Historic Preservation  
Description: TH #1, South Windham  
Baptist Church (#6)  
View looking south.

Photograph 1



South Windham Village Historic  
District

Windham, Vermont

Credit: Gina Campoli

Date: February 1984

Negative filed at Vermont Division  
for Historic Preservation

Description: TH #1. Buildings #  
3B, 3, 3C, 6, 8, 10 (left to  
right)

View looking north.

Photograph 2

84A-55



88-A-159

South Windham Village Historic  
District

Windham, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division  
for Historic Preservation

Description: TH #1, Buildings #  
2 and 3A

View looking north.

Photograph 3



88-A-159

South Windham Village Historic  
District  
Windham, Vermont  
Credit: David Tansey  
Date: July 1988  
Negative filed at Vermont Division  
for Historic Preservation  
Description: TH #1, Buildings #  
10, 11, 12 (left to right)  
View looking north.

Photograph 4





88-A-159

South Windham Village Historic  
District

Windham, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division  
for Historic Preservation

Description: South Windham Baptist  
Church (#6), Parsonage (#7)

View looking northeast.

Photograph 5



84-7-55

South Windham Village Historic  
District

Windham, Vermont

Credit: Gina Campoli

Date: February 1984

Negative filed at Vermont Division  
for Historic Preservation

Description: Harrington-Brown House  
(#2)

View looking north.

Photograph 6



South Windham Village Historic  
District

Windham, Vermont

Credit: Gina Campoli

Date: February 1984

Negative filed at Vermont Division  
for Historic Preservation

Description: Perry House (#3) and  
Perry Barn (#3C)

View looking west.

Photograph 7

84A-55



8  
South Windham Village Historic  
District

Windham, Vermont

Credit: William Chapman

Date: August 1982

Negative filed at Vermont Division  
for Historic Preservation

Description: Perry Barn (#30)

View looking northwest.

Photograph 8





88-A-159

South Windham Village Historic  
District

Windham, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division  
for Historic Preservation

Description: Old Schoolhouse (#5)

View looking west.

Photograph 9



82-A-2

South Windham Village Historic  
District  
Windham, Vermont  
Credit: William Chapman  
Date: August 1982  
Negative filed at Vermont Division  
for Historic Preservation  
Description: South Windham Baptist  
Church (#6)  
View looking north.

Photograph 10



South Windham Village Historic  
District

Windham, Vermont

Credit: William Chapman

Date: August 1982

Negative filed at Vermont Division  
for Historic Preservation

Description: Old Baptist Church

Parsonage-Hall House (#7)

View looking east.

Photograph 11

82-206-35



82-206-31

South Windham Village Historic  
District  
Windham, Vermont  
Credit: William Chapman  
Date: August 1982  
Negative filed at Vermont Division  
for Historic Preservation  
Description: Old Whipple Store  
(#8); demolished c.1987  
View looking northwest.

Photograph 12





88-A-159

South Windham Village Historic  
District  
Windham, Vermont  
Credit: David Tansey  
Date: July 1988  
Negative filed at Vermont Division  
for Historic Preservation  
Description: Site of Old Whipple  
Store (#8); demolished c.1987  
View looking northwest.

Photograph 13



South Windham Village Historic  
District

Windham, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division  
for Historic Preservation

Description: Kingsbury-Reed House  
(#9)

View looking east.

Photograph 14

88-A-159



South Windham Village Historic  
District

Windham, Vermont

Credit: William Chapman

Date: August 1982

Negative filed at Vermont Division  
for Historic Preservation

Description: Worden House (#10)

View looking southeast.

Photograph 15

82-206-28



88-A-159

South Windham Village Historic  
District

Windham, Vermont

Credit: David Tansey

Date: July 1988

Negative filed at Vermont Division  
for Historic Preservation

Description: Fellows House (#11)

View looking southeast.

Photograph 16





84-A-55

South Windham Village Historic  
District  
Windham, Vermont  
Credit: Gina Campoli  
Date: February 1984  
Negative filed at Vermont Division  
for Historic Preservation  
Description: Holmes House (#12)

View looking east.

Photograph 17