

Front view of house.

No. 1 of 12

Sept. 1984



View of south side front.

No. 2 of 12

Sept. 1984



View of south side rear.

No. 3 of 12

Sept. 1984



View of rear of house, showing shed which housed carbide lighting plant and poultry house to the rear.

No. 4 of 12

Sept. 1984



Detail of front parlor fireplace and hearth showing coal-burning cast-iron fireplace with glazed-tile hearth.

No. 5 of 12

Sept., 1984



View of front parlor fireplace and carved marble mantel.

No. 6 of 12

Sept. 1984



View from parlor into dining room showing double sliding doors and dining room mantelpiece.

No. 7 of 12

Sept. 1984



Detail of moulded door surrounds and ornamental turned and sawn decoration of archway leading from front hall.

No. 8 of 12

Sept. 1984



View of front stairway showing varnished walnut railings and turned balusters above paneling.

No. 9 of 12

Sept. 1984



View of interior of entrance hall.

No. 10 of 12

Sept., 1984



View of entry bay of front porch, showing screened section on south side of porch.

No. 11 of 12

Sept. 1984



Reproduction of early photograph of house, showing its appearance circa 1910. Note original barn and windmill to right and latticed fencing separating side yard from rear yard. No. 12 of 12 Sept., 1984