NPS Form 10-900 (Rev. 10-90)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM

This form is for use in nominating or requesting determinations for NCH individual properties and districts. See instructions in How to Complete the National Register of Historic Places Registration Form (National Register Bulletin 16A). Complete each item by marking "x" in the appropriate box or by entering the information requested. If any item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, architectural classification, materials, and areas of significance, enter only categories and subcategories from the instructions. Place additional entries and narrative items on continuation sheets (NPS Form 10-900a). Use a typewriter, word processor, or computer, to complete all items.

1. Name of Property historic name F.E. Company Manager's House

other names/site number \_ The White House, Sisters' Convent\_\_\_\_\_

AHRS Site No. FAI-273

2. Location

street & number 757 Illinois Street

not for publication <u>n/a</u>

city or town Fairbanks

vicinity n/a

state <u>Alaska</u> code <u>AK</u> county <u>Fairbanks North Star</u> code <u>090</u>

**zip code** <u>99701</u>

	OMB No		0 <b>PTB</b>
	JAN I	7 1946	IJ
INTERAC Na dotNATE	denoted on	RCES D	E I

<b>USDI/NPS NRHP Registration Form</b> F.E. Company Manager's House Fairbanks North Star, Alaska		ge 2
3. State/Federal Agency Certification		
As the designated authority under the Na 1986, as amended, I hereby certify that for determination of eligibility meets to registering properties in the National H meets the procedural and professional re 60. In my opinion, the property <u>X</u> me Register Criteria. I recommend that this significant <u>nationally</u> statewide continuation sheet for additional commen	ational Historic Preserventhis <u>X</u> nomination <u>the documentation stands</u> register of Historic Plate equirements set forth in sets <u>1000</u> does not meet a property be considered a <u>X</u> locally. ( <u>Set</u>	vation Act of request ards for aces and n 36 CFR Part the National ed
Signature of certifying official	Date . 19,1	995
Alaska State or Federal agency and bureau		
In my opinion, the property meets _ Register criteria. ( See continuations See continuations See continuations Signature of commenting or other officia	on sheet for additional	National comments.)
State or Federal agency and bureau		
4. National Park Service Certification		
I, hereby certify that this property is:		
entered in the National Register 	Oal R. Juga	2 /11/94
other (explain):		
	Signature of Keeper	Date of Action

USDI/NPS NRHP Registration Form F.E. Company Manager's House Fairbanks North Star, Alaska Page 3 5. Classification Ownership of Property (Check as many boxes as apply) X private \_\_\_\_ public-local \_\_\_\_ public-State \_\_\_\_ public-Federal Category of Property (Check only one box) \_X\_ building(s) \_\_\_\_ district \_\_\_\_ site \_\_\_\_ structure \_\_\_\_ object Number of Resources within Property Contributing Noncontributing \_\_\_\_\_ buildings \_\_1\_\_

\_\_\_\_ sites

\_\_\_\_\_ structures

Number of contributing resources previously listed in the National

Name of related multiple property listing (Enter "N/A" if property is not part of a multiple property listing.) n/a

\_\_\_\_\_ objects \_\_\_\_\_ Total

\_\_\_\_\_

**Register** n/a

USDI/NPS NRHP Registration Form F.E. Company Manager's House Fairbanks North Star, Alaska	Page 4
6. Function or Use	
Historic Functions (Enter categories from in Cat: <u>domestic</u> Sub:	
Current Functions (Enter categories from ins Cat: <u>domestic</u> Sub:	
7. Description	
Architectural Classification (Enter categori late 19th and 20th century revivals, Colonial Revival	
Materials (Enter categories from instruction foundation <u>concrete</u> roof <u>asphalt</u> walls <u>wood</u> other	us) 

## Narrative Description (Describe the historic and current condition of the property on one or more continuation sheets.)

The F.E. Company constructed a house for its general manager in Fairbanks in 1935-1936. The house is an exceptional example of the Colonial Revival architectural style in Alaska. Located towards the corner of Illinois Street and College Avenue and just south of Noyes Slough, the manager's house was at the northern end of the F.E. Company housing complex on the east side of Illinois Street. The company's central offices, warehouses and shops stood on the west side of Illinois Street. These associations are maintained today.

The Colonial Revival style was a move away from the Victorian houses with their high pitched gables and extensive ornamentation. Colonial revival buildings are rectangular with a symmetrical facade. Roofs are often hipped, and topped with a flat deck surrounded by a balustrade. Chimneys are placed to contribute to the overall symmetry. The central part of a facade may project slightly and be crowned with a pediment with or without supporting pilasters. Doorways have fanlights and are often set in tabernacle frames. Double hung sash windows are standard.

The three story F.E. Company manager's house measures 30 feet by 48 feet and has 3,746 square feet of space. The third floor is under the gable roof. The floor plan is a shallow T, with the leg measuring 9 1/2 feet by 20 feet and centrally placed on the rear (south) elevation. The house is balloon framed with clapboard siding painted white. The foundation is concrete and concrete posts. A one story garage with laundry room,

## USDI/NPS NRHP Registration Form

F.E. Company Manager's House Fairbanks North Star, Alaska Page 5 bedroom, bath and pantry extends from the southeast corner. It measures 22 1/2 by 39 feet. A wood balustrade is around the garage roof's perimeter.

The north elevation is the front of the house. The door in the center is framed by Doric pilasters supporting a pediment. A fan-shaped leaded glass sash tops the panel door which has an eight light storm door. On both sides of the entry are a pair of 12/12 and 8/12 double hung sash windows evenly spaced on the first and second floors respectively. An 8/8 double hung sash window is directly above the entry. All windows have shutters.

To the west of this elevation is the garage, bedroom, bath and pantry. It has a flat roof. The north elevation has two eight foot wide garage doors on its right half. It has two double 4/4 double hung sash windows and a four light door evenly spaced on the left half. Approximately one half of the building's width extends beyond the rear of the house. In the east elevation is a double hung sash window on the left and a door on the right. The south elevation has two 8/8 double hung sash windows at the east end. Only one of these windows has shutters. The west elevation has two sets of windows with shutters evenly spaced.

The east elevation is a gable end. A brick chimney is centrally placed with 12/12 double hung sash windows with shutters evenly spaced on both sides of the first floor and 8/12 double hung sash windows on the second floor. There are large louvered screens on each side of the chimney on the third floor.

The back, or south, elevation of the house has the leg of the T extending from its center. Most of the windows on this elevation, including the sides of the leg of the T, are double hung sash windows with shutters; a few are casement windows. Originally, the second floor of the leg was a solarium with a flat roof. In the 1960s the solarium windows were replaced with casement windows, and in the 1990s a gable roof was added.

The west elevation has a large multi-light bay window on the north half of the first floor and a 8/8 double hung sash window flanked by 4/4 double hung sash windows on the south half. It has two evenly spaced 8/12 double hung sash windows with shutters on the second floor. A louvered screen with shutters is in the gable wall.

With the exception of the changes to the rear elevation, the exterior of the house has not been altered. Inside, the first floor retains all of its original finishes and built-in cabinetry. Other interior features include tongue and groove oak hardwood floors with wooden pegging, plaster walls, a curved door underneath the staircase, and steam heated closets (inoperable today) in the laundry room for clothes drying. The front door leads to a foyer with a wide staircase. The living room with brick fireplace is east of the foyer, and a formal dining room is west. A greenhouse and storage shed are on the back side of the lot.

In 1984 the Keeper of the National Register determined the house eligible for listing under criteria A and C and of local significance.

USDI/NPS NRHP Registration Form F.E. Company Manager's House Fairbanks North Star, Alaska Page 6 8. Statement of Significance Applicable National Register Criteria (Mark "x" in one or more boxes for the criteria qualifying the property for National Register listing)

- <u>X</u> A Property is associated with events that have made a significant contribution to the broad patterns of our history.
- \_\_\_\_ B Property is associated with the lives of persons significant in our past.
- X C Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack individual distinction.
- D Property has yielded, or is likely to yield information important in prehistory or history.

Criteria Considerations (Mark "X" in all the boxes that apply.) n/a

	A	owned by a religious institution or used for religious
		purposes.
<del></del>	в	removed from its original location.
	С	a birthplace or a grave.
<u> </u>	D	a cemetery.
	Е	a reconstructed building, object, or structure.
. <u></u>	F	a commemorative property.
. <u></u>	G	less than 50 years of age or achieved significance within
		the past 50 years.
	F G	a commemorative property. less than 50 years of age or achieved significance with

Areas of Significance (Enter categories from instructions)

commerce architecture

Period of Significance 1935-1936

Significant Dates \_1936

Significant Person (Complete if Criterion B is marked above)  $\frac{n/a}{n/a}$ 

Cultural Affiliation n/a

Architect/Builder \_ Johnson, Victor, builder \_\_\_\_\_

USDI/NPS NRHP Registration Form

F.E. Company Manager's House Fairbanks North Star, Alaska Page 7 Narrative Statement of Significance (Explain the significance of the property on one or more continuation sheets.)

The U.S. Smelting, Refining and Mining Company of Boston, through its subsidiary, the Fairbanks Exploration Company (F.E. Company) started large scale gold mining operations in the Fairbanks area in the late 1920s. The company built its central complex along Illinois Street near downtown Fairbanks. The complex included housing. The finest house was the residence for the vice president and general manager built in 1935-1936. The house is an exceptional example in Alaska of the Colonial Revival architectural style.

Completion of the Alaska Railroad in 1923 provided ready access to the Healy coal fields and lowered shipping costs to Fairbanks. The USSR&M began acquiring mining claims in the Fairbanks Mining District and shipped in dredges to operate them. The company eventually operated eight gold dredges in the area. In 1926, the company began construction of an office, machine shop and warehouse complex just north of downtown Fairbanks. From what the company called the "townsite" it built and maintained the dredges, oversaw operations, and refined the gold. The site straddled the road to the gold fields and connected by a rail spur with the Alaska Railroad. To house the principal officials, the F.E. Company constructed homes along the east side of Illinois Street, directly across from the industrial complex.

The company constructed a house for the general manager in 1935-1936. Of interest, this was the year after President Roosevelt set the price of gold at \$35 an ounce--an increase of over eight dollars an ounce. It was the first Colonial Revival style house in Fairbanks. It is the finest example of this architectural style in Alaska--the Governor's Mansion in Juneau (listed in the National Register of Historic Places, November 7, 1976), built much earlier, in 1912, is its closest rival. The manager's house was built by Victor Johnson, an employee of the F.E. Company.

Roy B. Earling and his family were the first occupants of the house. Earling was a Michigan School of Mines graduate and World War I veteran. He had worked with a number of copper companies in Montana and Arizona before joining USSR&M, where he was one of the pioneers in developing large-scale cold water thawing. He became the manager of the Fairbanks operations in 1935.

The F.E. Company was the largest private employer in interior Alaska from the 1920s until 1964. Before World War II, 860 of the 3,455 people in Fairbanks worked for the company. Mining operations ceased during World War II because gold mining was not considered essential to the war effort. Although mining resumed after the war, the F.E. Company did not dominate the regional economy as it had before the war. It did, however, account for more than half the gold production in Alaska between 1950 and 1965. In all of its years of operations, the company mined over \$125 million of gold.

When operations shut down in 1964, the company sold the houses. The Catholic Church purchased the manager's house and used it for a convent for thirty years. This past year it was sold to a long-time Fairbanks family.

## USDI/NPS NRHP Registration Form

F.E. Company Manager's House Fairbanks North Star, Alaska Page 8 During the years the company operated, the manager's house was an integral part of the F.E. Company townsite. It retains its orientation to the industrial complex and other company houses. It also is a visual expression of the success and organization of the mining operation.

Occupants:

Roy B. Earling, Vice President and General
Manager, Alaskan Operations, F.E. Company
James D. Crawford, Vice President and General
Manager, Alaskan Operations, F.E. Company
Catholic Bishop of Northern Alaska; Sisters'
Convent
John and Ann Ringstad

USDI/NPS NRHP Registration Form F.E. Company Manager's House Fairbanks North Star, Alaska Page 9 9. Major Bibliographical References (Cite the books, articles, and other sources used in preparing this form on one or more continuation sheets.) Boswell, John C. History of Alaskan Operations of United States Smelting, Refining, and Mining Company. Mineral Industries Research Laboratory, University of Alaska Fairbanks, 1979. Lazenby, M.E. Colleen. Historical Resources Along Illinois Street, Final Report. Fairbanks, Alaska: Department of Transportation and Public Facilities, 1990. (pages 128, 146). Matheson, Janet. Fairbanks: A City Historic Building Survey. 1978, updated 1985. (pages 61, 125) Naske, Claus-M and Herman E. Slotnick. Alaska, A History of the 49th State. Norman: University of Oklahoma Press, 1989. Seeliger, Al, Personnel Manager, F.E. Company, 1941-1959. Personal communication. Spence, Clark C., "Fairbanks Exploration Goes to War," Alaska History, Vol. 10, No. 1 (Spring 1995):28-43. Previous documentation on file (NPS) preliminary determination of individual listing (36 CFR 67) has been requested. \_\_\_\_ previously listed in the National Register X previously determined eligible by the National Register \_\_\_\_ designated a National Historic Landmark \_\_\_\_ recorded by Historic American Buildings Survey # recorded by Historic American Engineering Record # \_\_\_\_\_ Primary Location of Additional Data X State Historic Preservation Office \_\_\_\_ Other State agency \_\_\_\_ Federal agency \_\_\_\_ Local government \_\_\_\_ University \_\_\_ Other Name of repository: 10. Geographical Data Acreage of Property 1.038 acres UTM References (Place additional UTM references on a continuation sheet) Zone Easting Northing Zone Easting Northing **1** <u>06</u> <u>466100</u> <u>7192200</u> **3** \_\_\_\_\_ 4 2 See continuation sheet.

USDI/NPS NRHP Registration Form F.E. Company Manager's House Fairbanks North Star, Alaska Page 10				
Verbal Boundary Description (Describe the boundaries of the property.)				
The house occupies the SW 1/4 of the NE 1/4 of the SE 1/4 of Section 3, Township 1S, Range 1W, Fairbanks Meridian. It is Lot B, Monroe Catholic School, First Addition replat filed 6/6/95, Plat #95-51, Fairbanks Recording District, 4th Judicial District, State of Alaska				
Boundary Justification (Explain why the boundaries were selected.)				
The boundary encompasses the house and the lot historically associated with the property.				
11. Form Prepared By name/title _John and Ann Ringstad, Owners				
organization <u>n/a</u>				
date October 20, 1995				
street & number <u>757 Illinois St.</u>				
telephone				
city or town <u>Fairbanks</u> state <u>AK</u> zip code <u>99701</u>				
Additional Documentation				
Submit the following items with the completed form:				
Maps A USGS map (7.5 or 15 minute series) indicating the property's location. A sketch map for historic districts and properties having large acreage or numerous resources.				
Photographs				
Representative black and white photographs of the property.				
Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items) Property Owner				
Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items)				
Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items) Property Owner				
Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items) Property Owner (Complete this item at the request of the SHPO or FPO.)				
Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items) Property Owner (Complete this item at the request of the SHPO or FPO.) name				

F.E.	<b>'NPS NRHP Registration Form</b> Company Manager's House Danks North Star, Alaska	Page 11	
	NPS Form 10-900-a OMB No. 1024-0018 (8-86)		
	ed States Department of the Interior onal Park Service	• •	
	ONAL REGISTER OF HISTORIC PLACES		
Secti	on _photograph identification_		
	F.E. Company Manager's House Fairbanks North Star, Alaska Russ Sackett November 2, 1995 Office of History and Archaeology, Alaska Depart Resources, 3601 C St., #1278, Anchorage, AK 9950 looking south at the front elevation of the hous	3-5921	
	F.E. Company Manager's House Fairbanks North Star, Alaska Russ Sackett November 2, 1995 Office of History and Archaeology, Alaska Depart Resources, 3601 C St., #1278, Anchorage, AK 9950 looking southwest at the east elevation of the h	3-5921	
	F.E. Company Manager's House Fairbanks North Star, Alaska Russ Sackett November 2, 1995 Office of History and Archaeology, Alaska Depart Resources, 3601 C St., #1278, Anchorage, AK 9950 looking northeast at greenhouse, garage, and sou of the house	3-5921	
	F.E. Company Manager's House Fairbanks North Star, Alaska Russ Sackett November 2, 1995 Office of History and Archaeology, Alaska Depart Resources, 3601 C St., #1278, Anchorage, AK 9950 looking northeast at west and south elevations o	3-5921	
	F.E. Company Manager's House Fairbanks North Star, Alaska Russ Sackett November 2, 1995 Office of History and Archaeology, Alaska Depart Resources, 3601 C St., #1278, Anchorage, AK 9950 looking east at west elevation of the house2		

