

North Bennington Historic District North Bennington, VT


Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for

Historic Preservation

Description: Greenwich Streetscape (Bldgs. #8-2). View looking east. Bennington Photograph 1



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: "Brick Row" duplexes (#4 & 3) west and south elevations. View looking NE
Photograph 2



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: E.D. Welling & Huling Houses (#14 & 11) - south and east elevations. View look-Photograph 3/ ing north.



North Bennington Historic District North Bennington, VT JUL 9 1980

Credit: Hugh H. Henry
Date: October 1979

Negative filed at Vermont Division for
Historic Preservation
Description: Upper Main Street-scape - east side (Bldgs. #12, 13, & 15). View-looking N.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Vermont Railway yard from east end (Bldgs. #17, 18, & 16). View looking SW.
Photograph 5



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Vermont Railway Freight house
(#17) - west and south elevations. View lookPhotograph 6/ ing north.




North Bennington Historic District North Bennington, VT Credit: Hugh H. Henry JUL 9 1980

Date: December 1979

Negative filed at Vermont Division for Historic Preservation

Description: Depot Street-scape (Bldgs. #20-24). View looking east. Photograph 7



North Bennington Historic District

North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979

Negative filed at Vermont Division for
Historic Preservation
Description: Houses #29, 27, & 26 - south and
east elevations. View looking northwest.
Photograph 8

#8




North Bennington Historic District

North Bennington, VT Credit: Hugh H. Henry Date: October 1979

Negative filed at Vermont Division for

Historic Preservation

Description: Willis' Garage (#32) and H. C. Simmons House (#30) - south and east eleva-Photograph 9/ tions, View looking northwest.




North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979
Negative filed at Vermont Division for

Historic Preservation

Description: Houses #28, 31, and 33 - west and south elevations. View looking northeast.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Houses #35 and 34 - south and
east elevations. View looking northwest.
Photograph 11



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry JUL 9 1980
Date: December 1979
Negative filed at Vermont Division for Historic Preservation
Description: Buildings #36-38 - west elevations. View looking northeast.
Photograph 12

#1-



North Bennington Historic District

North Bennington, VT

Credit: Hugh H. Henry UL 9 1980

Date: October 1979

Negative filed at Vermont Division for Historic Preservation Bennington Co.

Description: Houghton Street-scape - east side (buildings #45-48). View looking NE.

Photograph 13



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979

1980

Negative filed at Vermont Division for

Historic Preservation

Description: Gingerbread House (#49) - north and west elevations. View looking southeast.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Catamount Bank (#50) - south and east elevations. View looking northwest.
Photograph 15



North Bennington Historic District

North Bennington, VT

Credit: Hugh H. Henry

Date: October 1979

Negative filed at Vermont Division for

Historic Preservation

Description: Bank Street-scape - north side
(bldgs. #54-51). View looking northwest.

#16



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation Bennington and Hoosick Valley
Railway carbarn (#60) - south and east elevaPhotograph 17/ tions. View looking northwest.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Bank Street-scape - South side
(bldgs. #65-62). View looking west.
Photograph 18



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry JUL 9 1980
Date: February 1980
Negative filed at Vermont Division for Historic Preservation Bennington,
Description: Congregational Parsonage & Church (#67 & 66) - north and west elevations. View Photograph 19/ looking south.



North Bennington Historic District

North Bennington, VT

Credit: Hugh H. Henry

Date: October 1979

Negative filed at Vermont Division for Historic Preservation

Description: Village center (bldgs. #68, 67, & 50) and Main Street Park. View looking west.

Photograph 20

20



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Baptist Parsonage & Church (#80 & 79) - south and east elevations. View looking Photograph 21/ northwest.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Van Ben Thuysen & Harrington
Houses (#82 & 81) - south and east elevations.
Photograph 22/ View looking northwest.



North Bennington Historic District
North Bennington, VT

Credit: Hugh H. Henry
Date: October 1979

Negative filed at Vermont Division for
Historic Preservation

Description: North Bennington School (#86) south and east elevations. View looking NW.
Photograph 23



North Bennington Historic District
North Bennington, VT 91980
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Houses #100, 102, & 103 - south
and east elevations. View looking northwest.
Photograph 24

24



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Lower Main Street-scape - west
side (bldgs. #105-110 & 50). View looking N.
Photograph 25



North Bennington Historic District


North Bennington, VT

Credit: Hugh H. Henry

Date: October 1979

Negative filed at Vermont Division for Negative filed at Vermont Division for Description: Dr. Gleason House (#107) - south and east elevations. View looking west.

Photograph 26



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: G.B. Welling House (#112) - west
and south elevations. View looking northeast.
Photograph 27



North Bennington Historic District

Credit: Hugh H. Henry
Date: October 1979

Negative filed at Vermont Division for
Historic Preservation

Historic Preservation

Description: Lower Main Street commercial row (bldgs. #113-116) - west elevations. View Photograph 28/ looking east.




BENNING for County

,5

North Bennington Historic DistrictJUL 9 1980
North Bennington, VT Credit: Hugh H. Henry
Date: February 1980 Negative filed at Vermont Division for Historic Preservation
Description: Paran Creek-scape showing ex-stark
Paper Mill (#124), milldam, ex-firehouse (#127),
ex-Payne's Shop (#164), Prospect St. bridge
(#128), and ex-Walbridge Red Mill (#129).
Photograph 29/ View looking northeast.

AUG 29 1990

29



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: ex-Stark Paper Mill (#124) - east elevation. View looking southwest; 1980
Photograph 30



BENNINGton County

North Bennington Historic District

North Bennington, VT

Credit: Hugh H. Henry

JUL 9 1980

Date: October 1979 AUG 2 9 1980

Negative filed at Vermont Division for

Historic Preservation

Description: Bldgs. #126 & 125 - north and west

elevations. View looking southeast.

Photograph 31



BENNINGton County

North Bennington Historic District

North Bennington, VT JUL 9 1980

Credit: Hugh H. Henry
Date: October 1979

Negative filed at Vermont Division for

Historic Preservation
Description: ex-firehouse (#127) - east and north elevations. View looking southwest.

Photograph 32



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Prospect Street-scape toward West
St. (Bldg. #129 on L, #119 on R). View looking
Photograph 33/ northwest.



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Milldam above Prospect St. bridge,
showing ex-Payne's Shop (#164) & North St.
Photograph 34/ bridge (#163). View looking NE.



North Bennington Historic District

North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979

Negative filed at Vermont Division for
Historic Preservation
Description: Fred Welling House (#139) - south
and east elevations. View looking west.

Photograph 35



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: G.H. Elwell House (#147) - west
and south elevations. View looking north.
Photograph 36

36



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Houses #149-151 - west and south elevations. View looking northeast.
Photograph 37

REMANDIAN

O



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Mechanic Street-scape (bldgs.
#162-154). View looking east.
Photograph 38



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: December 1979
Negative filed at Vermont Divisio for
Historic Preservation
Description: North Street bridge (#163). View looking northwest.
Photograph 39



North Bennington Historic District
North Bennington, VT
Credit: Hugh H. Henry
Date: October 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Sage Street-scape north side
(houses #175, 173, 174, 168, & 165). View
Photograph 40/ looking northeast.

40