United States Department of the interior National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page _____

SUPPLEMENTARY LISTING RECORD

NRIS Reference Number: 91001953 Date Listed: 1/13/92

<u>Tipover Lookout Tree</u> Property Name

CoconinoAZCountyState

<u>National Forest Fire Lookouts in the Southwestern Region TR</u> Multiple Name

This property is listed in the National Register of Historic Places in accordance with the attached nomination documentation subject to the following exceptions, exclusions, or amendments, notwithstanding the National Park Service certification included in the nomination documentation.

autainot alter Signature of the Keeper

for

1/23/92 Date of Action

Amended Items in Nomination:

Statement of Significance: Under Areas of Significance, Engineering is added.

This information was confirmed with Evan DeBloois of the U.S. Forest Service.

DISTRIBUTION: National Register property file Nominating Authority (without nomination attachment)

NATIONAL	REGISTER	OF	HISTORIC	PLACES
REGISTRAT	ION FORM			

Name of Property historic name Tipover Lookout Tree	877
historic name Tipover Lookout Tree	
$\Delta r n \alpha n \alpha n \alpha \alpha (\alpha) + \alpha n m n \alpha n \alpha n \alpha \alpha$	
other names/site number AR-03-07-03-702	
2. Location	
street & number N/A	/ /not for publication
city, town Fredonia	/ x/vicinity
state Arizona code AZ county Cocor	nino code 005 zip code 86022
3. Classification	
Ownership of Property Category of Property	Number of Resources within Property
_ private _ building(s)	Contributing Noncontributing
_ public-local _ district	buildings
public-State <u>x</u> site	_1sites
x public-Federal structure	structures
_ object	objects
	<u>1</u> Total
Name of related multiple property listing:	Number of contributing resources
	previously listed in the National
NATIONAL FOREST FIRE LOOKOUTS IN THE	Register0
SOUTHWESTERN REGION, USDA FOREST SERVICE	
4. State/Federal Agency Certification	
requirements set forth in 36 CRF Part 60.	In my opinion, the property <u> </u> meets eria. _ See continuation sheet.
USDA - Forest Service	
In my opinion, the property meetsdoes criteriaSee continuation sheet.	not meet the National Register
Signature of certifying official	
State Historic Preservation Office	
5. National Park Service Certification	
I, hereby, certify that this property is: 	1/13/92
_ See continuation sheet. _ determined not eligible for	
the National Register.	
removed from the National	
Register.	
[_[other, (explain:)	
	f the Keeper Date of Action
Signature of	I ONC WEEPET DALE OF ACTOM

6. Function or Use Historic Functions (enter categories from instructions GOVERNMENT/ Lookout Facility

Current Functions (enter categories from instructions) VACANT/NOT IN USE

7. Description	
Architectural Classification	Materials enter categories from
(enter categories from instructions)	instructions)
N/A	foundation
	walls
	roof
	other N/A

Describe present and historic physical appearance.

Summary

This site, which has two historic lookout trees, is located on a ridge between Bear and Wall Lakes overlooking Demotte Park to the east and the Tipover, Big Spring and Kanabonits drainages to the south and west. It is on the interior of the Kaibab Plateau on the North Kaibab Ranger District, Kaibab National Forest. It is within the mixed conifer forest at an elevation of 9,160 feet. One tree is still alive and standing and the other has fallen. They maintain sufficient integrity to qualify for National Register listing.

Physical Description

The standing lookout tree is a white fir 75 feet high and 3 feet in diameter with a ladder constructed up its eastern side approximately 40 feet. Two contiguous segments of ladder works remain. The first 10-15 feet are gone. The remaining ladder is in good condition. The construction is typical of other ladders on lookout trees: 2" X 4" lumber sidepieces with 1" x 12-14" crosspieces. It is attached to the tree with lag bolts. This tree is associated with a downed lookout tree with a ladder up its side and 6 foot by 6 foot platform in its top. This is the only documented platform tree on the North Kaibab Ranger District.

Setting

Vegetation surrounding the site currently consists of an aspen-spruce-fir community with some grasses and forbs. This area was logged last year (1989) and much debris remains. The entire area is heavily littered with duff and downed vegetation. However, the setting retains much of its historic appearance.

Integrity

The Tipover Lookout tree is still in good condition, despite having been abandoned for approximately 30 years. Only the lower 10-15 feet of ladder has been removed, for safety purposes. It is still readily identifiable as a lookout tree facility. The fallen tree is an integral part of the site. As a whole, this site retains integrity of location, design, feeling, materials, workmanship, setting, and associaton.

8. Statement of Significance		
Certifying official has considered the sig	nificance of this proper	ty in relation to
other properties:		
nati	onally [] statewide	X locally
Applicable National Register Criteria $ \overline{x} $ A	$ B \overline{\mathbf{x}} C D$	
Criteria Considerations (Exceptions) _ A	_ B _ C _ D _ E _ I	₹ _ G
Areas of Significance (enter categories from instructions)	Period of Significance	Significant Dates
Conservation		
Politics/Government	1905-1940	
	Cultural Affiliation N/A	
Significant Person	Architect/Affiliation	

State significance of property, and justify criteria, criteria considerations, and sreas and periods of significance noted above.

Summary

Tipover Lookout Tree is significant under Criterion A [36 CFR 60.6] for its association with 1) the development of forest fire prevention, detection, and control by the USDA Forest Service between 1905 and 1940, and 2) the conservation movement and its influence on public land management from 1905 to 1940. It is also significant under Criterion C [36 CFR 60.6] because it embodies the distinctive characteristics of a type of construction, the earliest and simplest form of fire detection structure, built into a living tree.

Historic Contexts/Background

The construction and abandonment dates for the Tipover Lookout Tree are presently unknown. They might be ascertained, however, through oral history. This site is unusual because the fallen tree had a platform, a unique feature among lookout trees on the North Kaibab Ranger District. The fact that it was replaced after it had fallen is indicative of this site's importance to the fire detection network of the area.

Although much remains to be learned about the history of this lookout tree, it had an important function in the earliest fire detection network on the Kaibab National Forest. It continues to evoke a sense of the past.

9. Major Bibliographical References	
Previous documentation on file (NPS): 	<pre> _ See continuation sheet. Primary location of additional data: _ State hist. preservation office Other State agency x Federal agency Local government University Other Specify repository: Kaibab National Forest Williams, AZ</pre>
10. Geographical Data	
Acreage of property less than one	
UTM References A 1 2 3 9 7 8 5 0 4 0 2 4 9 0 0 B Zone Easting Northing C	Image: See continuation sheet
Verbal Boundary Description	
The boundary of the site is a rectangle measu the standing and downed trees (see accompanyin	
Boundary Justification	
The boundary includes the lookout tree and its	immediate area only.

[_] See continuation sheet

11. Form Prepared By				
name/title Marietta A. Davenport District Archaeologist North Kaibab RD				
organization USDA	Forest Service Kaibab Natl Forest			
street & number	430 S. Main	telephone (602)643-7395		
city or town	Fredonia	state AZ zip code 86022		

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

PHOTOGRAPHS Page 1

THE FOLLOWING INFORMATION IS THE SAME FOR ALL PHOTOGRAPHS ACCOMPANYING THIS NOMINATION:

- 1). Tipover Lookout Tree
- 2). Vicinity of Grand Canyon, North Rim, southwest of DeMotte Park, Kaibab Plateau. Arizona
- 3). John C. Davenport
- 4). May 1990
- 5). North Kaibab Ranger District, Kaibab National Forest, Fredonia, Arizona

INFORMATION FOR INDIVIDUAL PHOTOGRAPHS:

- 6). Facing east, tree in its setting.
- 7). #1
- 8). Facing north, fallen tree with platform.
- 9). #2

