Historic Sites Survey

1

1 3

.

20

2002275  $\cap$ 

Depar P. O.

State of Mississippi Department of Archives & History P. O. Box 571, Jackson, MS. 3920

ARCHITECTURAL DESCRIPTION:	NAME: Douglas House
	STREET NO:
1-story log house, second pen (frame) added on south facade but has deteriorated. Foundation of pine blocks, logs hewn on four sides and joined with <sup>1</sup> / <sub>2</sub> -dovetailed corners. Eaves extend on left (north) facade to shelter brick chimney. Interior not ceiled as logs fit tightly, attic floored but no stairs extant. All facades except front have been weatherboarded, shed rooms added to rear (east) facade. ALTERATIONS:	TOWN/VIC: Sontag Alle
	COUNTY: Lawrence
	BLOCK/LOT:
	PRESENT OWNER:Mr. and Mrs. J. Leslie MayADDRESSSontag, MS39665
	PRESENT USE: vacant
	FORMER USE: residence
	DATE: 1858
	STYLE: log house
	ARCH/BUILDER: Elisha Douglas
	SOURCE OF DATE: 1and records
OUTBUILDINGS:	ENVIRONMENT: rural
Set in large clearing surrounded by forest.	LEVEL OF SIGNIFICANCE
LANDSCAPE FEATURES:	NEIGHBORHOOD
	LOCAL X STATE
	NATIONAL
STATEMENT OF SIGNIFICANCE:	PHOTOS
The Douglas House is architecturally significant as a well constructed single pen log house constructed prior to the Civil War. Quality of workmanship is seen in the wall logs hewn on all sides and joined with $\frac{1}{2}$ -dovetailed notches which fit tightly and did not require interior ceiling. Additional charac- teristic features are the foundation of pine blocks and the extended eaves on the north facade that shelter the chimney.	
Historically it was associated with its builder, Elisha Douglas, a pioneer Baptist preacher and Mason who served in the Confederate Army.	

## SITE OR AREA PLAN WITH NORTH ARROW AND SHAPE OF STRUCTURE: PHYSICAL CONDITION: Fair THREATS: VERBAL BOUNDARY DESCRIPTION: S23-T8N-R10E A lot 500' square with house at center. ACREAGE: less than 5 acres UTM REF: 3 5 0 4 7 1 0 NORTHING A 115 76 7 6 7 9 0 0 cl -1 вL NORTHING ZONE EASTING D 1 1 FORM PREPARED BY: DATE April 1980

CONTINUATION: