


UNITED STATES POST OFFICE



GLENDALE MAIN POST OFFICE, CA

AUGUST, 1982

NEGATIVE # 8A FRONT ELEVATION



GLENDALE MAIN POST OFFICE, CA

AUGUST, 1982

NEGATIVE # 10A NORTH ELEVATION



Decorative balcony railing with vertical balusters.

Arched windows with decorative frames.

Decorative tower with geometric patterns.

Palm tree in the background.

U.S. MAIL

White utility vehicle with a logo on the side.

White utility vehicle with the number 01/0975 on the side.

White utility vehicle with a logo on the side.

Shopping cart parked near the building entrance.

GLENDALE MAIN POST OFFICE, CA

AUGUST, 1983

NEGATIVE #11A NORTH ELEVATION