



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Southwest - porte-cochere

Photo # 1



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Southeast - front facade

Photo # 2



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Northeast - front & side

Photo # 3



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

North northeast - side porch

Photo # 4





Tillandsia

Baldwin, Louisiana, St. Mary Parish

Photographer: jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Northwest - rear

Photo # 5



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

North northeast - chickenhouse, boiler shed, gardener's  
shed

Photo # 6



Tillandsia  
Baldwin, St. Mary Parish, Louisiana  
Photographer: Jessica Kemm  
Neg. at: State Historic Preservation Office, Baton Rouge  
Date taken: Spring 1982  
Northeast - gardener's shed  
Photo # 7



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Southeast - privy

Photo # 8





Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

North northeast - garage

Photo # 9



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Northeast - billiards house

Photo # 10



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Interior - living hall & stairway

Photo # 11



Tillandsia

Baldwin, St. Mary Parish, Louisiana

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Interior - living hall & sliding door

Photo # 12





Tillandsia  
Baldwin, Louisiana, St. Mary Parish  
Photographer: jessica Kemm  
Neg. at: State Historic Preservation Office, Baton Rouge  
Date taken: Spring 1982  
Interior - stairway  
Photo # 13



Tillandsia  
Baldwin, Louisiana, St. Mary Parish  
Photographer: Jessica Kemm  
Neg. at: State Historic Preservation Office, Baton Rouge  
Date taken: Spring 1982  
Interior - mantel  
Photo #14



Tillandsia

Baldwin, Louisiana, St. Mary Parish

Photographer: Jessica Kemm

Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Interior - mantel

Photo # 15



Tillandsia

Baldwin, Louisiana, St. Mary Parish

Photographer: Jessica Kemm


Neg. at: State Historic Preservation Office, Baton Rouge

Date taken: Spring 1982

Interior - cast hardware

Photo # 16





Tillandsia

Baldwin, Louisiana, St. Mary Parish

Photographer: Jessica Kemm'

Date taken: Spring 1982

Neg. at: State Historic Preservation Office, Baton Rouge

Interior - floral gold leafed freize

Photo # 17