

Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Contemporary Bathroom

Artifacts Consulting, Inc.

Photo No. 37 of 37

R. 2003 FRK.

APP



DAVENPORT

CLOCK TOWER

WAGON LITE BUS

UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	JUN 13 1975
DATE ENTERED	SEP 5 1975

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC  
Davenport Hotel

AND/OR COMMON  
Pennington Hotel

**2 LOCATION**

CITY, TOWN  
Spokane

\_\_\_\_VICINITY OF

COUNTY  
Spokane

STATE  
Washington

**3 PHOTO REFERENCE**

PHOTO CREDIT  
Jacob Thomas

NEGATIVE FILED AT  
Washington State Parks and Recreation Commission

DATE OF PHOTO  
April, 1975

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

View from the southeast  
Pennington Hotel in foreground

PHOTO NO  
a

INT: 2983-75

Custom Photo Service  
P. O. Box 5  
Littlerock, Wa. 98556

**PROPERTY OF THE NATIONAL REGISTER**

MAY 13 '75

DAVENPORT HOTEL, SPOKANE COUNTY, WASH (3)



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY	
RECEIVED	JUN 13 1975
DATE ENTERED	SEP 5 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC

Davenport Hotel

AND/OR COMMON

Pennington Hotel

**2 LOCATION**

CITY, TOWN

Spokane

\_\_\_\_ VICINITY OF

COUNTY

Spokane

STATE

Washington

**3 PHOTO REFERENCE**

PHOTO CREDIT

Jacob Thomas

DATE OF PHOTO

April, 1975

NEGATIVE FILED AT

Washington State Parks and Recreation Commission

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT. GIVE BUILDING NAME & STREET

View of the main lobby

PHOTO NO  
b

Custom Photo Service

P. O. Box 5

Littlerock, Wa. 98556

MAY 13 '75

PROPERTY OF THE NATIONAL REGISTER

DAVENPORT HOTEL, SPOKANE COUNTY, WASH (B)



UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES  
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY	
RECEIVED	JUN 13 1975
DATE ENTERED	SEP 5 1975

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*  
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

**1 NAME**

HISTORIC  
Davenport Hotel

AND/OR COMMON  
Pennington Hotel

**2 LOCATION**

CITY, TOWN  
Spokane

\_\_\_\_ VICINITY OF

COUNTY  
Spokane

STATE  
Washington

**3 PHOTO REFERENCE**

PHOTO CREDIT  
Jacob Thomas  
NEGATIVE FILED AT

DATE OF PHOTO  
April, 1975

**4 IDENTIFICATION**

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Hall of the Doges  
Ceiling and clerestory detail

PHOTO NO  
C

INT: 2983-75

Custom Photo Service  
P. O. Box 5  
Littlerock, Wa. 98556

**PROPERTY OF THE NATIONAL REGISTER**

MAY 13 '75

Davenport Hotel Spokane WA





Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Northwest corner  
Artifacts Consulting, Inc.  
Photo No. 1 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Southwest corner  
Artifacts Consulting, Inc.  
Photo No. 2 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

West facade

Artifacts Consulting, Inc.

Photo No. 3 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
First Avenue entrance  
Artifacts Consulting, Inc.  
Photo No. 4 of 37





Davenport Hotel

10 S Post St


Spokane, Spokane, Washington

July 2003

Exterior detail

Artifacts Consulting, Inc.

Photo No. 6 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

South entrance

Artifacts Consulting, Inc.

Photo No. 5 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Exterior Detail

Artifacts Consulting, Inc.

Photo No. 7 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Terrace looking east

Artifacts Consulting, Inc.

Photo No. 8 of 37





Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Lobby skylite cover

Artifacts Consulting, Inc.

Photo No. 9 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
West wing rooftop  
Artifacts Consulting, Inc.  
Photo No. 10 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

East wing rooftop

Artifacts Consulting, Inc.

Photo No. 11 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
View looking Southeast  
Artifacts Consulting, Inc.  
Photo No. 12 of 37





Davenport Hotel

10 S Post St.

Spokane, Spokane, Washington

July 2003

View from Second Floor of Lobby looking Southwest

Artifacts Consulting, Inc.

Photo No. 13 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
View of Lobby from Second Floor looking Northwest  
Artifacts Consulting, Inc.  
Photo No. 14 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Southwest Lobby Detail  
Artifacts Consulting, Inc.  
Photo No. 15 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Lobby Fountain looking towards Sprague Avenue Entrance

Artifacts Consulting, Inc.

Photo No. 16 of 37





Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

North Lobby looking East

Artifacts Consulting, Inc.

Photo No. 17 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Second Floor North Gallery looking West  
Artifacts Consulting, Inc.  
Photo No. 18 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

First Avenue Entrance

Artifacts Consulting, Inc.

Photo No. 19 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Reception Desk

Artifacts Consulting, Inc.

Photo No. 20 of 37





Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Isabella Room looking East

APR 2003 FRK  
Artifacts Consulting, Inc.  
Photo No. 21 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Isabella Room looking West

APR 2003 FRK  
Artifacts Consulting, Inc.  
Photo No. 22 of 37

APR 2003 FRK



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Isabella Room detail

3 FRK

APR. 2003 FRK

Artifacts Consulting, Inc.  
Photo No. 23 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Marie Antoinette Room

Artifacts Consulting, Inc.

Photo No. 24 of 37





Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Marie Antoinette Room gallery

Artifacts Consulting, Inc.

Photo No. 25 of 37



MARIO ANTONIETTI BIELLA

Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Lobby to Marie Antoinette Room

Artifacts Consulting, Inc.

Photo No. 26 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Ladies Waiting Room  
Artifacts Consulting, Inc.  
Photo No. 27 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Hall of the Doges looking Northeast

Artifacts Consulting, Inc.

Photo No. 28 of 37





Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Hall of the Doges Detail

Artifacts Consulting, Inc.

Photo No. 29 of 37



-POOL

NOTICE

POOL

EXIT

EXIT

Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Basement Corridor

Artifacts Consulting, Inc.  
Photo No. 30 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Circus Room detail

Artifacts Consulting, Inc.

Photo No. 31 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Elevator Lobby looking South  
Artifacts Consulting, Inc.  
Photo No. 32 of 37

APR. 2003 FRK

APR. 2003 FRK





Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Contemporary Upper Floor Hallway

Artifacts Consulting, Inc.

Photo No. 33 of 37

2003 FRI

7/27/03



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Contemporary Upper Floor Hallway

Artifacts Consulting, Inc.

Photo No. 34 of 37



Davenport Hotel

10 S Post St

Spokane, Spokane, Washington

July 2003

Contemporary Upper Floor Hallway

Artifacts Consulting, Inc.

Photo No. 35 of 37



Davenport Hotel  
10 S Post St  
Spokane, Spokane, Washington  
July 2003  
Contemporary Guestroom  
Artifacts Consulting, Inc.  
Photo No. 36 of 37

