
OLD ALLENSTOWN
MEETING HOUSE

ALLENSTOWN MEETING HOUSE
MERRIMACK CTY, NH
PHOTO #1

Exterior, south (front) and east elevations, looking NW.

[illegible]

[illegible]

[illegible]

Interior looking northeast from the southwest
of the meeting room, showing the pulpit (at left)
and the benches mounted on a slanted floor

ALLENSTOWN MEETING HOUSE
MERRIMACK CTY NH
PHOTO #3

Interior of the Allenstown Meeting House, looking East, showing the benches mounted on a slanted floor and the box pews around the perimeter of the meeting room.



[illegible]
[illegible]
[illegible]

Interior of the Allentown Meeting House
looking SW, showing the benches mounted
on a slanted floor and the box pews
around the perimeter of the meeting room